

DAFTAR PUSTAKA

- Emzir, 2008, Metodologi Penelitian Pendidikan Kualitatif & Kuantitatif, Pt. Rajagrafindo Persada, Jakarta.
- Fakhrurrozi, 2017, *Penanganan, Pengaturan dan Pengamanan Muatan Kapal*, CV. Budi Utama, Yogyakarta.
- Gianto, Herry dan Martopo, Arso, 2004, *Pengoperasian Pelabuhan Laut*, Balai Pendidikan dan Latihan Pelayaran, Semarang.
- IMO, 2001, *BC Code : Code For Safe Practice For Solid Bulk Cargoes*, International Maritime Organization, London.
- IMO, 2010, *IMDG Code International Maritime Dangerous Goods Code*, International Maritime Organization, London.
- Isbester, Jack, 1993, *Bulk Carrier Practice*, The Nautical Institute, London.
- Istopo, 1999, *Kapal dan Muatannya*, Koperasi Karyawan BP3IP, Jakarta.
- Moleong, L.J., 2004, *Metodologi Penelitian Kualitatif*, PT. Remaja Rosdakarya, Bandung.
- Mudjiono, Mudjiono dan Prihermono, FX. Dicky, 2008, *Kamus Umum Bahasa Indonesia*, Scientific Press, Tangerang.
- Sudjamiko, F.D.C., 2007, *Pokok-Pokok Pelayaran Niaga*, PT. Toko Gunung Agung. Jakarta.
- Sugiyono, 2011, *Metode Penelitian Kuantitatif Kualitatif Dan R&D*, Alfabeta, Bandung.
- Sugono, Dendy, 2008, *Kamus Bahasa Indonesia*, Pusat Bahasa, Jakarta.
- Suyono, R.P, 2005, *Pengangkutan Intermodal Ekspor Impor Melalui Laut*, PPM, Jakarta.
- PIP, 2017, *Pedoman Penyusunan Skripsi Jenjang Pendidikan Diploma IV*, Politeknik Ilmu Pelayaran, Semarang.
- Poerwadarminta, W.J.S, 1976, *Kamus Umum Bahasa Indonesia*, Balai Pustaka, Jakarta.

LAMPIRAN I

WAWANCARA

1. Wawancara Dengan Nakhoda

Nama : Kang Kyeong Seob

Tempat : MV. Pan Global

Tanggal : 06 Mei 2017

Deck cadet: Good morning, Sir. Excuse for interviewing you in a few minute.

What is the factor caused the coal cargo can smolder?

Deck cadet: Selamat pagi pak. Mohon ijin untuk wawancara. Apa faktor yang

menyebabkan muatan batu bara berasap?

Nakhoda : *An empty space in the hold means the empty space contains air.*
What is meant by the air here is oxygen. Oxygen is one of the factors of fire occurrence. Fire can be overcome by breaking the triangle of fire where in this case we must eliminate the oxygen (O₂) element. Or by minimizing the amount of empty load space.

Nakhoda : Ruang kosong dalam palka berarti ruangan yang kosong tersebut berisi udara. Yang dimaksud dengan udara disini adalah oksigen. Oksigen adalah salah satu faktor terjadinya kebakaran. Kebakaran dapat ditanggulangi dengan cara memutus hubungan segitiga api dimana dalam hal ini kita harus menghilangkan unsur oksigen (O₂) tersebut. Atau dengan meminimalisir jumlah ruang muatan yang kosong.

Deck cadet: What is the action taken to tackle the smoke of smolder coal?

Deck cadet: Apa tindakan yang dilakukan untuk menanggulangi muatan batu bara berasap?

Nakhoda : The effort taken to tackle the smoky coal load is to dismantle the cargo that emits smoke or fire, informing the shipper. In addition it can set up a warning in the loading space.

Nakhoda : Upaya yang dilakukan untuk menanggulangi muatan batu bara yang berasap adalah dengan membongkar muatan yang mengeluarkan asap atau api, menginformasikan kepada shipper. Selain itu dapat mengatur peranginan di ruang muat.

Deck cadet: What does the captain do to prevent coal loads from getting smolder?

Deck cadet: Apa yang kapten lakukan untuk mencegah muatan batu bara agar tidak berasap?

Nakhoda : Always check the load temperature in the hold by using dipping thermometer and check the gas content in the hold with gas sampling technique.

Nakhoda : Selalu mengecek suhu muatan di dalam palka dengan menyounding menggunakan thermometer celup dan mengecek kandungan gas dalam palka dengan teknik gas sampling.

2. Wawancara Dengan Mualim I

Nama : Pangala Jefri Ronting

Tempat : MV. Pan Global

Tanggal : 06 Mei 2017

Deck cadet: Selamat malam, *Chief.* Mohon ijin untuk wawancara. Menurut

Chief, Apa faktor yang menyebabkan muatan batu bara berasap?

Mualim I : Batu bara adalah muatan curah yang mudah menangas atau membawa sendiri dikarenakan batu bara mengandung senyawa metana. Senyawa metana tersebut dapat terjadi sebuah ledakan atau bahkan terjadi sebuah kebakaran apabila ada pencampuran dengan udara khususnya oksigen.

Deck cadet: Bagaimana pengaruh suhu udara terhadap muatan batu bara di suatu tempat dibandingkan dengan tempat lain?

Mualim I : Pada saat di pelabuhan Kalimantan yang memiliki suhu lebih tinggi (panas) dibandingkan pada saat di pelabuhan Korea Selatan, memang benar suhu muatan batu bara memiliki suhu yang lebih panas saat di pelabuhan Kalimantan dibandingkan di pelabuhan Korea Selatan. Oleh karena itu, kita harus selalu mengecek keadaan suhu lingkungan maupun suhu muatan itu sendiri. Apabila kenaikan suhu muatan tersebut naik drastis maka akan menyebabkan bahaya yang lebih fatal dan merugikan bagi berbagai pihak

Deck cadet: Bagaimana pengaruh ruang muat terhadap muatan batubara dan akibat apa yang ditimbulkan?

Mualim I : Sistem peranginan dalam ruang muat atau palka sangatlah penting karena sistem peranginan ini dapat mengurangi keringat muatan yang dapat menyebabkan muatan batu bara menjadi rusak bahkan apabila tidak segera ditangani dapat menimbulkan sesuatu yang berbahaya. Batu bara yang berasap ini disebabkan karena sistem peranginan di MV. Pan Global tidak berjalan dengan optimal. Hal ini disebabkan kurangnya kesadaran perwira kapal ataupun awak kapal dalam perawatan sistem peranginan ini.

Deck cadet: Bagaimana pengaruh kedisiplinan serta kesadaran *crew* dalam menjalankan tugas dan tanggung jawabnya?

Mualim I : Kurangnya kedisiplinan serta kesadaran dalam menjalakan tugas dan tanggung jawab tersebut ada karena kurangnya pengetahuan para anak buah kapal terhadap bahaya yang ditimbulkan jika tidak dilaksanakannya tugas dan tanggung jawab, seperti halnya tidak dilaksanakan pengecekan suhu dan kandungan gas dalam muatan batu bara. Hal ini akan berakibat sangat fatal karena kita tidak tau kondisi muatan batu bara, berapa suhu batu bara pada saat itu dan bagaimana keadaan kandungan batu bara tersebut. Jika ternyata suhu muatan batu bara tinggi (panas) dan kandungan gas terutama metana besar maka muatan batu bara dapat menimbulkan asap yang lama-lama bisa terbakar apabila hanya didiamkan dan akan

menimbulkan kerugian bagi berbagai pihak termasuk awak kapal sendiri. Selain itu para anak buah kapal juga kurang respek terhadap lingkungan sekitar. Terlalu cuek dan menyepelekan akan bahaya yang akan ditimbulkan bila terjadinya suatu muatan batu bara yang berasap

Deck cadet: Apa tindakan yang dilakukan untuk menanggulangi muatan batu bara yang berasap?

Mualim I : Upaya yang harus dilakukan untuk menanggulangi muatan batu bara yang berasap adalah dengan membongkar terlebih dahulu pada bagian yang telah mengeluarkan asap atau api dan dengan melakukan pemantauan kandungan metana, karbon monoksida dan oksigen di dalam palka, ketika kandungan di dalam ruang muat mencapai 50 ppm atau meningkat secara teratur dalam 3 (tiga) hari berturut-turut, Nakhoda wajib menginformasikan kepada *shipper*. Selain itu dapat mengatur peranginan di ruang muat. Hal tersebut selalu dilakukan agar di dalam palka tidak terdapat muatan batu bara yang berasap apabila didiamkan akan terbakarnya muatan tersebut sehingga dapat merusak muatan.

Deck cadet: Bagaimana cara mencegah muatan batubara agar tidak berasap?

Mualim I : Kegiatan mencegah lebih baik daripada menanggulangi. Agar muatan batu bara tidak berasap dapat dilakukan dengan cara selalu mengecek suhu muatan di dalam palka dengan menyounding menggunakan thermometer celup dan mengecek kandungan gas

dalam palka dengan teknik gas sampling. Kedua kegiatan tersebut dilakukan secara rutin. Hal tersebut dilakukan agar dapat meminimalisir terjadinya muatan batu bara yang berasap

Deck cadet: Terima kasih atas waktunya *chief*, selamat malam.

Mualim I : Selamat malam.



3. Wawancara Dengan Mualim II

Nama : Surya Gandhi

Tempat : MV. Pan Global

Tanggal : 7 Mei 2017

Deck cadet: Selamat pagi, Ken. Mohon ijin beberapa waktu untuk wawancara.

Apa faktor yang menyebabkan muatan batubara berasap?

Mualim II : Kurangnya kedisiplinan serta kesadaran dalam menjalakan tugas dan tanggung jawab disebabkan oleh beberapa faktor seperti dalam pelaksanaan HSE (*Health, Safety and Environment*) Meeting belum maksimal. Dimana dalam HSE meeting tidak dijelaskan bahaya yang akan terjadi pada muatan yang akan dimuat, cara penanggulangan apabila muatan tersebut rusak sehingga anak buah kapal tidak mengetahui apa yang harus diperbuat ketika muatan batu bara tersebut berasap. Selain itu, kelalaian atau tidak disiplinnya dalam menjalankan tugas dan tanggung jawab dikarenakan kurangnya pengawasan terhadap proses bongkar muat

Deck cadet: Apa upaya yang dilakukan untuk menanggulangi muatan batu bara berasap?

Mualim II : Dilarang menggunakan air dalam pemadam kebakaran muatan di dalam ruang muat karena air tidak dapat memadamkan api yang berasal dari batu bara melainkan dapat menambah genangan di dalam palka sehingga dapat mengurangi kualitas

batu bara. Menutup *hatch cover* dan semua ventilasi peranginan yang menuju ke dalam ruang muat karena untuk mengurangi kontak langsung dengan oksigen yang merupakan faktor dari kebakaran. Selain itu, mengeluarkan udara di dalam palka untuk mengurangi kebakaran, disarankan untuk penggunaan karbon dioksida atau *inert gas system* jika tersedia dan harus dipertahankan hingga api padam

Deck cadet: Cukup sekin ken, terima kasib telah meluangkan waktu untuk melakukan wawancara. Selamat pagi.

Mualim II : Selamat pagi.



4. Wawancara Dengan Bosun

Nama : Djemi Marlon Pioh

Tempat : MV. Pan Global

Tanggal : 7 Mei 2017

Deck cadet: Selamat siang, bos. Minta waktunya sebentar untuk wawancara.

Bosun : Selamat siang, det. Iya Silahkan.

Deck cadet: Saya mau tanya, apa faktor yang menyebabkan batu bara berasap?

Bosun : Saya tidak terlalu memahami tentang penanganan muatan batu bara, namun menurut saya kebakaran disebabkan karena ventilasi ruang muat yang tidak difungsikan sebagaimana harusnya dan Mualim 1 tidak pernah memerintahkan kepada saya untuk mengatur ventilasi di setiap palka, saya hanya selalu merawat ventilasi tersebut.

Deck cadet: Bagaimana pengaruh kedisiplinan dan kesadaran para *crew* dalam menjalankan tugas dan tanggung jawab?

Bosun : Kurangnya kedisiplinan dan kesadaran dalam menjalankan tugas dan tanggung jawab disebabkan kurangnya pengawasan pihak perwira dalam pelaksanaan pengecekan suhu dan kandungan gas dalam muatan batu bara oleh anak buah kapal. Tidak hanya itu, Perwira kapal tidak pernah menginformasikan atau memberitahu

dampak yang terjadi dan cara penanggulangan jika terjadi muatan batu bara yang berasap ketika diadakannya HSE *meeting*.

Deck cadet: Terima kasih bos atas waktunya, cukup sekian. Selamat siang bos.

Bosun : Iya sama-sama. Selamat siang.



LAMPIRAN II

Data – Data Kapal

1. Stowage Plan

REMARK:


**PLEASE NOTE THAT ABOVE STOWAGE PLAN MIGHT BE CHANGE BY REAL SF,
REAL HARBOUR DENSITY AND THE CONDITION OF SAGGING / HOGGING.**

MASTER OF M/V. PAN GLOBAL : Capt. Kang Kyeong Seob

2. *Cargo Temperature*

CARGO TEMPARATURE ON THE BARGE

**1. BARGE NAME : KALIMANTAN CAHAYA 68
DATE : 10TH JUNE 2017**



4. Coal Monitoring Temperature Report



AISI No.86

PT. SARANA INSPECT INDONESIA
Independent Surveyors - Inspection & Marine Consultants
Marine Bulk Surveyors - Marine Superintendent
Marine Consultants Analytical & Testing Laboratories

COAL MONITORING TEMPERATURE REPORT

THIS IS TO REPORT, that the undersigned of PT. SARANA INSPECT INDONESIA did the request of MessrsSPICA SERVICE INDONESIA..... attend on board:

Vessel Name : MV. PAN GLOBAL


Whilst she was lying anchored at MVARA PERPAN, SAMARINDA
On APRIL, 01, 2017, from 10.05 hours local time up to 10.30 hours local time, for the purpose of conducting inspection Coal Temperature at cargo barge :

KALIMANTAN TUJUH

Declared Cargo On Barge : 7535

Measurement Results and Equipment Used :
Inspection was carried out and measuring using DIGITAL THERMOMETER inserting stick sensor into the cargo
The result of measurements are as follows:

POINT	TEMPERATURE (°C) DIGITAL
1	31.8
2	31.9
3	30.4
4	32.0
5	35.7
6	21.9
7	32.7
8	46.5
9	53.2
10	29.1
11	53.2
12	31.6



MAX : 53.2 MIN : 29.1


CONCLUSION:

Based on above result of temperature measurement of coal cargo in the subject hold found temperature of BELOW 55° C. During inspection, there is no sign of smoke was observed and the cargo appeared to be in suitable condition. Based to IMO BC Code In case of the temperature of coal cargo exceeds 55° C, expert advice should be obtained.

This Report refers to Coal Temperature Inspection Only and does not certify any other matters, it reflects our finding at the time and place of intervention only and is issued without prejudice.

Acknowledge by,

Master/Chief Officer



PT. SARANA INSPECT INDONESIA

Surveyor,



Form Certificated No. SII-01
Jl. Gorontalo III No. 14 Jakarta 14330, INDONESIA Telp. (021) 43800165, Fax. ((021) 43935389
Email : one@saranainspect.com and sii@saranainspect.com website www.saranainspect.com



AISI No.86

I. SARANA INSPECT INDONESIA

Independent Surveyors - Inspection & Marine Consultants

Marine Bulk Surveyors - Marine Superintendent

Marine Consultants Analytical & Testing Laboratories

**COAL MONITORING
TEMPERATURE REPORT**


THIS IS TO REPORT, that the undersigned of PT. SARANA INSPECT INDONESIA did the request of
 Messrs SPICA SERVICES INDONESIA attend on board:

Vessel Name : MV. PAN GLOBAL
 Whilst she was lying anchored at MUARA BEPAU, SAMARINDA
 On APRIL 02, 2017 from 12.30 hours local time up to 13.50 hours local time, for the
 purpose of conducting Inspection Coal Temperature at cargo barge :

B6. KALIMANTAN DUADeclared Cargo On Barge : 7494**Measurement Results and Equipment Used :**

Inspection was carried out and measuring using DIGITAL THERMOMETER. Inserting stick sensor into the cargo
 The result of measurements are as follows:

POINT	TEMPERATURE (°C)	
	DIGITAL	EKA
1	72.1	73.5
2	71.3	72.7
3	72.1	71.9
4	60.9	60.8
5	67.4	60.8
6	62.1	61.1
7	65.9	65.0
8	66.2	66.1
9	70.4	60.0
10	82.1	78.9
11	82.2	83.1
12	77.9	76.1



CONCLUSION: MAX: 83.1 / MIN: 57.4

Based on above result of temperature measurement of coal cargo in the subject hold found temperature of BELOW 55° C. During inspection, there is no sign of smoke was observed and the cargo appeared to be in suitable condition. Based to IMO BC Code In case of the temperature of coal cargo exceeds 55° C, expert advice should be obtained.
 This Report refers to Coal Temperature Inspection Only and does not certify any other matters, it reflects our finding at the time and place of intervention only and is issued without prejudice.

Acknowledge by,
 Master/Chief Officer



PT. SARANA INSPECT INDONESIA
 Surveyor,



Form Certificated No. SII-01
 Jl. Gorontalo III No. 14 Jakarta 14330, INDONESIA Telp. (021) 43800165, Fax. ((021) 43935389
 Email : ops@saranainspect.com and siops@indo.net.id website. www.saranainspect.com

5. Checklist Break Bulk Cargo Operation (Before Loading)

POS	Checklist for Break Bulk Cargo Operation (Before Loading)	Form Number : BOM - 10
		Revision Number : 00
		Revision Date : 2010.01.01
VSL/VOY. NO : 034		DATE :
MASTER : _____ (SIGNATURE)		PORT : TAMBUNO - IDN
		C/OFF : _____ (SIGNATURE)
No.	Contents to Perform	Results
1	The methods of hold cleaning	Sweeping(<input checked="" type="checkbox"/>), washing(<input type="checkbox"/>)
2	The methods of hold washing 1) hold 2) hatch cover	FW only(<input type="checkbox"/>), FW rinse after SW(<input type="checkbox"/>) FW only(<input checked="" type="checkbox"/>), FW rinse after SW(<input type="checkbox"/>)
3	Hatch cover hose test - If leaked, leaked hold no., reason and taken Measurement? - Condition of tarpauline cover (in case of pontoon type h/cover)	Yes(<input checked="" type="checkbox"/>), No(<input type="checkbox"/>) Leaked(<input type="checkbox"/>), No leaked(<input checked="" type="checkbox"/>)
4	Hold dry up condition - If not dried, taken measurement?	Dried up(<input type="checkbox"/>), Humid(<input type="checkbox"/>) Water droplet(<input type="checkbox"/>)
5	Previous voyage cargo residues 1) under hatch cover 2) on the upper structure in hold - If remained, taken measurement?	Remained(<input type="checkbox"/>), Cleaned(<input checked="" type="checkbox"/>) Remained(<input type="checkbox"/>), Cleaned(<input type="checkbox"/>)
6	Remained salty (results of silver nitrate test) 1) under hatch cover 2) near the hatch cover and in hold 3) inside of tarpauline - If positive, taken measurement?	Positive(<input type="checkbox"/>), Negative(<input checked="" type="checkbox"/>) Positive(<input type="checkbox"/>), Negative(<input checked="" type="checkbox"/>) Positive(<input type="checkbox"/>), Negative(<input checked="" type="checkbox"/>)
7	Condition of hold ventilator	Good(<input checked="" type="checkbox"/>), Poor(<input type="checkbox"/>), Stick(<input type="checkbox"/>)
8	Condition of manhole cover tightness - If leaked, leaked position and taken Measurement?	Leaked(<input type="checkbox"/>), No leaked(<input checked="" type="checkbox"/>)
9	Condition of ballast tank - If leaked, tank No. and taken measurement	Leaked(<input type="checkbox"/>), No leaked(<input checked="" type="checkbox"/>)
10	The custody method of dunnages and lashing materials collected in previous voyage 1) Whether they are covered or not, when on deck during in bound voyage, covering? 2) Whether or not they contact with in bound cargo, when in hold?	On deck(<input checked="" type="checkbox"/>), In hold(<input type="checkbox"/>) Covered(<input checked="" type="checkbox"/>), Uncovered(<input type="checkbox"/>)
11	Others	

6. Checklist Break Bulk Cargo Operation (During Loading)

POS	Checklist for Break Bulk Cargo Operation During Loading	Form Number : BUM - 11 Revision Number : 00 Revision Date : 2010.01.01
VSL/VOY. NO. : _____		DATE : _____
MASTER : _____ (SIGNATURE)		C/OFF : _____ (SIGNATURE)
No.	CONTENTS TO PERFORM	RESULTS
1	TYPES OF THE CARGO SLING - STAINED CARGRO LOCATION : EXTENT(Q'TY AND B/L NO.)	PLY : <input type="checkbox"/> TIMBER : <input type="checkbox"/> REG PIPE : <input type="checkbox"/> TWP & F/T : <input type="checkbox"/> PLT : <input type="checkbox"/> COIL : <input type="checkbox"/> BAR : <input type="checkbox"/> H-BEAM : <input type="checkbox"/>
2	USING WET/GREEN DUNNAGE - STAINED CARGRO LOCATION : EXTENT(Q'TY AND B/L NO.)	YES(<input type="checkbox"/>), NO(<input type="checkbox"/>)
3	USED F/LIFT? - F/LIFT OIL LEAKAGE : - STAINED CARGRO LOCATION : EXTENT(Q'TY AND B/L NO.) - TAKEN MEASUREMENT	YES(<input type="checkbox"/>), NO(<input type="checkbox"/>)
4	RESONABLE Q'TY OF RUNNING PLATES USED OR NOT? - IF NOT SUFFICIENT, TAKEN	YES(<input type="checkbox"/>), NO(<input type="checkbox"/>)
5	REMAINED SALTY ON STEEL CARGO FROM BARGE (SILVER NITRATE TEST) - POSITIVE B/L NO.: - CARRIED BARGE NAME: - THER B/L NO. OF CARGO IN THOSE GRADE : - TAKEN MEASUREMENT	YES(<input type="checkbox"/>), NO(<input type="checkbox"/>)
6	UNCOVERED BARGE - B/L NO. OF CARGO IN THOSE GRADE :	BARGE NAME : _____
7	STOPPAGE OF LOADING DUE TO RAIN - CARGO WORK IN RAINY DAYS, PERIODS AND REASON	STOPPAGE PERIODS
8	EXCEPTION(HEAVY DMG ONLY : EXTENT, REASON, TAKEN MEASUREMENT)	RUST DAMAGE : PHYSICAL DAMAGE :
9	CARGO GEAR TROUBLE - STOPPAGE : - REASON : - TAKEN MEASUREMENT :	YES(<input type="checkbox"/>), NO(<input type="checkbox"/>)
10	OTHERS(MAIN ITEMS HAD DISCUSSED WITH SUPERCARGO BEFORE DEPARTURE)	

■ SHEQ-3.1 Ch. 6.5.3 / FILE NO. G-10

- 1/1 -

7. Declaration Of Cargo Condition

 DEPARTEMEN KEUANGAN REPUBLIK INDONESIA DIREKTORAT JENDERAL BEA DAN CUKAI KANTOR PENGAWASAN DAN PELAYANAN BEA DAN CUKAI TIPE MASYA PABEAN B BALIKPAPAN SEKSI PENINDAKAN DAN PENYIDIKAN	
PERNYATAAN KEADAAN MUATAN DECLARATION OF CARGO SITUATION	
<u>Nama Kapal / Voy. No.</u> Name of Ship/Voy. No.	: MV. PAN GLOBAL VOY.
<u>Bendera</u> Flag	: PANAMA
<u>Bobot Mati</u> Dead Weight	: 82765 MT
<u>Agen</u> Agent	: PT PELAYARAN BAHTERA ADHICUNA
<u>Tanggal/jam tiba</u> Date time of arrival	JULY 2017, at 00 HRS
<u>Datang dari</u> Last Port	HADONG, S. KOREA
<u>Posisi Kapal</u> Ship position	ADANG BAY ANCHORAGE
<p>Yang bertanda tangan di bawah ini sebagai Nakhoda Kapal Under Sign Master of The Ship</p> <p><u>Capt. KANG KYEONGSEOB</u></p> <p>Menerangkan sebagai berikut To declare as follow</p>	
<p>a. Muatan Sesuai dengan daftar muatan (Manifest) : <u>NIL</u></p> <p>b. Muatan berbeda dengan daftar muatan (Manifest) : <u>NIL</u></p> <p>c. Ada muatan / barang-barang yang tidak dilindungi dokumen : <u>NIL</u></p>	
<u>Muatan untuk pelabuhan lain</u> Cargo for next Port	: <u>NIL</u>
<u>Muatan untuk Balikpapan</u> Cargo for Balikpapan	: <u>NIL</u>
Balikpapan, July 2017	
<u>Nakhoda / Atas nama Nakhoda</u> Master / On behalf of master	
<p>Lembar 1 : Laporan Lembar 2 : Nakhoda Kapal Lembar 3 : Arsip</p> <p><u>Capt. KANG KYEONGSEOB</u></p> <p style="text-align: right;">M/V PAN GLOBAL</p>	

8. Form For Cargo Information

FORM FOR CARGO INFORMATION for Solid Bulk Cargoes		
MSC 84/24/Add.3 ANNEX 12		
Bulk Cargo Shipping Name : COAL		
Shipper : PT. KIDECO JAYA AGUNG MENARA MULIA, SUITE 1701, 17th FLOOR, JL. JEND. GATOT SUBROTO KAV. 9-11, JAKARTA 12930, INDONESIA	Transport document number : 244/660/TMCT-SP/VII/2017	
Consignee : TBN	Carrier : Dry Bulk Carrier	
Name/means of transport : MV. PAN GLOBAL Port/place of departure : Adang Bay, Indonesia	Instructions or other matters: Refer to IMSBC Code Appendix 1	
Port/place of destination : Any South Korean Port (S)		
General description of the cargo : INDONESIAN STEAM COAL IN BULK	Gross mass (kg/tonnes): Abt 80,000 MT (as per shipping request)	
(Type of material/particle size) : SIZE : 0 - 50mm 100%		
Specifications of bulk cargo, if applicable: Stowage factor: Approx. 43 - 44 CUFT / MT WOG Angle of repose, if applicable: - Trimming procedures: Trimming by Dozer or FLF Loader Chemical properties if potential hazard: ("e.g., Class & UN No. or "MHB")		
Group of the cargo : <input type="checkbox"/> Group A and B* <input type="checkbox"/> Group A* <input checked="" type="checkbox"/> Group B <input type="checkbox"/> Group C	* For cargoes which may liquefy (Group A and Group A and B cargoes) Transportable moisture limit : N/A Moisture content at shipment : Approx. 18.5 %	
Relevant special properties of the cargo: (e.g., highly soluble in water) a) The commodity is not considered a cargo which may liquefy during the voyage. b) The intended cargo is not considered liable to emit significant amounts of methane. c) The intended cargo is considered not liable to spontaneous combustion. d) The cargo loaded on board are not harmful to the marine environment.	Additional certificate(s)*: <input type="checkbox"/> Certificate of moisture content and transportable moisture limit <input type="checkbox"/> Weathering certificate <input type="checkbox"/> Exemption certificate <input type="checkbox"/> Other (specify) * If required	
DECLARATION : I hereby declare that the consignment is fully and accurately described and that the given test results and other specifications are correct to the best of my knowledge and belief and can be considered as representative for the cargo to be loaded.	Signature on behalf of shipper PT. KIDECO JAYA AGUNG Tahah Merah, July 19,2017 FAHMI A. RAMADHANI Port Captain	Acknowledge receipt the document by or on behalf of ship's Master Adang Bay, July 2017 Master

9. Standard Operational Procedure Of Loading And Unloading Cargo

POS	Standard Operational Procedure	Form Number	TRA - 05
	Loading And Unloading Cargo	Revision Number	00
		Revision Date	2015.10.15

1. Before entering a port for loading or unloading cargo, the chief officer must prepare the cargo plan such as the stowage plan and loading/ unloading sequence, etc. so that it conform to the relevant domestic or international regulations including the following matters.
 - a. Ensure properly stability during the entire period of navigation
 - b. The limits of the hull's strength such as the shearing force and bending moment, etc according to allocation of cargo in holds.
 - c. Local strength when loading of heavy cargo.
 - d. The best suitable trim to maintained.
 - e. The ballasting and de ballasting capability of the ship.
 - f. The sequence, quantity, and rate of loading or unloading, taking into consideration the speed of loading or unloading
2. The master must review the cargo plan submitted by the chief officer to see if it is appropriate and approve it.
3. Before commencing loading or unloading of cargo, the chief officer should receive the sign of superintendent of the stevedore's company in the cargo plan which was reviewed and approved by master. Then, the chief officer hand the copy of the cargo plan to the superintendent.
4. The chief officer should carefully confirm the difference between the cargo plan and the stevedore's and the finally ask for the master's approval before the cargo operation is started. (Accident case caused by the mistaken cargo plan of the stevedore).
5. If there is any abnormal conditions found during the loading or unloading which is not in accordance with the cargo plan, the chief officer must immediately notice the superintendent so that the abnormal conditions can be removed.
6. When loading or unloading solid bulk cargo (except grain), apply the company Standard form BOM-01 "Cargo Loading/Unloading Plan", break bulk cargoes and PCTC, apply stowage plan, subjected owner's business dept.

BIODATA PENULIS

Data Diri

Nama : Muhammad Kodrat Wicaksana

NIT : 51145221N

Tempat,Tanggal Lahir: Muara Bungo, 20 Januari 1996



Alamat : Jalan Jendral Sudirman no 61 Mardisari, Temanggung

Data Orang Tua

Nama Ayah : Drh. Sri Widodo

Nama Ibu : Tri Yuliningsih

Alamat : Jalan Jendral Sudirman no 61 Mardisari, Temanggung

Riwayat Pendidikan

1. SD Negeri 2 Jampiroso Temanggung, Lulus Tahun 2008
2. SMP Negeri 2 Temanggung, Lulus Tahun 2011
3. SMA Negeri 1 Temanggung, Lulus Tahun 2014
4. Politeknik Ilmu Pelayaran Semarang

Pengalaman Praktek Laut

1. Perusahaan Pelayaran : PT. Jasindo Duta Segara

2. Alamat : Jl. Raya Boulevard Barat, RT.2/RW.9, Kelapa Gading Barat, DKI Jakarta 14240, Indonesia.

3. Nama Kapal : MV. Pan Global

4. Masa Layar : 01 September 2016 – 06 September 2017