

DAFTAR GAMBAR

Gambar 2.1	Skema Pengisian Tekan Pada Mesin Diesel.....	15
Gambar 2.2	Bagian dari <i>Turbocharger</i>	18
Gambar 2.3	Bagian Inti (<i>Centre Core</i>) Dari <i>Turbocharger</i>	19
Gambar 2.4	Diagram Tulang Ikan (<i>Fishbone Analysis</i>).....	31
Gambar 2.5	Kerangka Pikir Penelitian.....	32
Gambar 4.1	<i>Turbocharger</i> MET83SE II.....	45
Gambar 4.2	Diagram Tulang Ikan (<i>Fishbone Analysis</i>).....	51
Gambar 4.3	Diagram Pohon Kesalahan <i>Fault Tree Analysis</i>	57
Gambar 4.4	Kerusakan Sudu-Sudu <i>Blower Side</i>	59
Gambar 4.5	Pohon Kesalahan 1.....	59
Gambar 4.6	Pohon Kesalahan 2.....	61
Gambar 4.7	<i>Faul Tree</i> Kurangnya Perawatan <i>Turbocharger</i>	63