| KT | Non-Conformity Report | | No.: EM/I/04/13 Page: 1/1 Date: 11/09/2015 |
|---------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------|
| Organization | | Finder | • |
| CI 'C' ' | N. C. C. i. Ol. ii | Related basis / | |
| Classification | Non-Conformity, Observation | Regulation | |
| Description | | | |
| THE PIPE LINE OF HYDRAULIC OPEN/CLOSED HATCH COVER LEAKING NEAR HATCH No. 6 FWD & 4 STBD SIDE. | | | |
| Plan for Correction/Improvement (Due date: 11th September 2015) | | | |
| Renewed Partially Leaking after Sailing from Muara Berau SAMARINDA | | | |
| Head of Division/Master (DD/MM/YY) Find | | | i /11 th Sept. 2013 der (DD/MM/YY) YES□, NO□ |
| Detail of Corrective/improvement (Completed date: 16 th Sept. 2013) | | | Preventive Action |
| Dismantle & Renewed Partially Leaking of The Pipe Hydraulic for Open / Closed Hatch Cover. | | | |
| Head of Division/Master sign | | | sign_ |
| Comment of F | rinder : | | |
| | | Finder: | sign |
| Final Confirmation | □ Completion, Identification of data/f □ Re-corrective Action | rield DP : | sign |