

LAMPIRAN II
GAMBAR - GAMBAR



Gambar 1. Cargo Control Panel yang terletak di CCR (Cargo Control Room)



Gambar 2. Cargo Pump



Gambar 3. Cargo manifold



Gambar 4. PV Valve




Gambar 5. Pipe Line cargo



Gambar 6. manhole



Gambar 7. Muatan yang masih tersisa di sekitar *bellmouth* akibat pelaksanaan tank cleaning yang kurang optimal.



Gambar 8. Butterworth Head