

## DAFTAR GAMBAR

Gambar 2.1 Sambungan Bintang .....	10
Gambar 2.2 Sambungan Segitiga .....	10
Gambar 2.3 Kontruksi Motor .....	13
Gambar 4.1 Motor listrik penggerak <i>LO pump</i> .....	32
Gambar 4.2 Kondisi winding terbakar .....	34
Gambar 4.3 Kerusakan <i>bearing</i> .....	37
Gambar 4.4 Misalignment poros .....	56
Gambar 4.5 Kerusakan <i>bearing</i> .....	58
Gambar 4.6 Pengukuran ujung kutup .....	59

