

DAFTAR GAMBAR

Gambar 2.1 <i>Stern Tube in place</i>	6
Gambar 2.2. <i>Sea water lubricated</i>	7
Gambar 2.3 <i>Oil lubricated system</i>	8
Gambar 2.4. <i>The AFT seal (left) and the FWD seal (right)</i>	10
Gambar 2.5. <i>Rubber bearing (left) dan Lignum vitae bearing (right)</i>	12
Gambar 2.6. Kerangka Pikir Penelitian.....	14
Gambar 4.1. MV. Oriental Mutiara.....	29
Gambar 4.2. Kebocoran minyak pelumas <i>stern tube</i>	32
Gambar 4.3. <i>Seal stern tube</i> yang baru.....	34
Gambar 4.4. MV. Oriental Mutiara melaksanakan <i>dock</i>	35
Gambar 4.5. Karet pada <i>seal</i> yang mengeras.....	38
Gambar 4.6. Masuknya air laut ke dalam kamar mesin.....	38
Gambar 4.7. MV. Oriental Mutiara di <i>towing</i> menuju dock.....	39
Gambar 4.8. MV. Oriental Mutiara di <i>towing</i> kapal <i>tug boat</i>	40
Gambar 4.9. Peta Kuadran Strategi.....	57