

Lampiran I

Gambar Proses pengeboran baut patah di MV. Lieke



Sumber : Dokumen pribadi (2015)

Lampiran II

Gambar baut yang sudah di cabut di MV. Lieke



Sumber : Dokumen pribadi (2015)