

DAFTAR GAMBAR

Gambar 2.1	<i>Crane</i> MV. Bara Anugerah.....	13
Gambar 2.2	<i>Grabes</i> MV. Bara Angerah.....	15
Gambar 2.3	<i>Hopper</i> Pelabuhan Tanjung Intan, Cilacap	16
Gambar 2.4	<i>Loader Vehicle</i>	16
Gambar 2.5	Kerangka Pikir	19
Gambar 4.1	MV. Bara Anugerah.....	32
Gambar 4.2	<i>Ship's crane</i> MV. Bara Anugerah.....	33
Gambar 4.3	<i>Hydraulic cylinder crane</i> bocor.....	35
Gambar 4.4	<i>Grab</i> tidak tertutup rapat.....	36
Gambar 4.5	<i>Wire drum crane</i>	37
Gambar 4.6	<i>Motor crane</i>	38
Gambar 4.7	Perbaikan <i>hydraulic cylinder crane</i>	43
Gambar 4.8	Perbaikan <i>grab</i>	44
Gambar 4.9	Pemasangan <i>wire drum</i>	45
Gambar 4.10	<i>Motor crane</i> tiba di Cilacap.....	46