



MT. SINAR JOGYA	ITEM DEFECTS	MR.107
Ref. No. : 02/10/SJ/M	C.O.T HIGH LEVEL ALARM & OVERFILL ALARM	
Item Code	Report date : 12 th September 2010	
DEFECT REPORT		
Summary Description	: 1) High Level Alarm not function for C.O.T : 2P/S, 3S, 4P/S 2) Overfill alarm lamp signal on the bridge not function.	
Repair Specification	: Nil	
Cause of Defect :		
Master : 	Chief Officer : 	
FOR OFFICE USE ONLY		
Reviewed by Company	Approve to action :	Yes <input type="checkbox"/> No <input type="checkbox"/>
	Deffered until next dry docking :	
	Planned Completion date :	
	Carried out by :	
	Completion date :	