Tabel Crew List MV. Oriental Ruby

PT SALAM PACIFIC INDONESIA LINES MY ORIENTAL RUBY / POGB

DAFTAR AWAK KAPAL CREW LIST

 NAMA KAPAL
 KM.ORIENTAL RUBY
 DARI PELABUHAN
 BITUNG

 BENDERA
 INDONESIA
 KE PELABUHAN
 GORONTALO

 PEMILIK
 PT S P I L
 G T
 18 000 TON

 JENIS KAPAL
 KONTAINER
 H P
 16 546 KW

NO	NAMA AWAK KAPAL	JABATAN	BUKU PE	LAUT - EXP	IJAZAH	NO IJAZAH
1	Capt JONI SULLE	NAKHODA	Y 093615	06-DEC-2016	ANT-I	6200019838N10211
2	NICODEMUS NEBORE	MUALIMI	C 056227	08-APR-2017	ANT-II	6200070276N20111
3	HERIZAL	MUALIM II	E 097772	29-JUN-2019	ANT-III	6200016230M30216
4	WAHYU TEGUH PRIHADI	MUALIM III	A 055107	01-AUG-2017	ANT-III	6201321870M30216
5	EDY SUBIYANTORO	KKM	Y 074322	20-SEP-2018	ATT-I	6200060301T10215
6	SUTRISNO	MASINIS II	W 055166	14 JAN-2017	ATT-II	6200037794T20310
7	DONI SETIAWAN	MASINIS III	D 088447	19 JUN-2018	ATT-III	6200356993T30311
8	MUHAMMAD HUSSEN B P	MASINIS IV	A 026633	24-MAY-2017	ATT-III	6201657718T30315
9	AKHMAD KHOIRI	MASINIS V	X 081066	08-OCT-2017	ATT-V	6200506114T502 09
10	DAHLAN	MARCONIST	B 036494	02-APR-2018	SRE-II	1129/SRE-II/T/V/2016
11	SUBHAN	SERANG	Y 087676	10-NOV-2018	ANT-D	6200198723N60609
12	TOMMY RATUMBYUSANG	JURU MUDI	D 063868	30-MAR-2018	ANT-D	6200394706N60710
13	RACHMAT	JURU MUDI	C 080397	18-AUG-2017	RENW	6200047941330715
14	MAMAN ROFII	JURU MUDI	E 107359	01-AUG-2019	RAASD	6200568883340715
15	SUYANTO	ELEKTRISEN	X 013621	17-FEB-2017	BST	6201506541010715
16	SUPRIYATNA	MANDOR MSN	Y 078407	17-OCT-2018	ATT-D	6200412987T60104
17	PETRUS LAMA TOKAN	JURU MINYAK	X 061128	22-JUL-2017	ANT-D	6201561154T60711
18	SUMALI	JURU MINYAK	C 017697	02-JAN-2017	REPWER	The second secon
19	MUHAMMAD FIRDAUS	JURU MINYAK	A 046867	05-JUN-2017	ATT-D	6201346074T60612
20	SARODJI	JURU MASAK	E 107358	01-AUG-2019	BST	6201296654010315
21	ACHMAD RIZKI SUKMAWAN	PELAYAN	D 003772	10-SEP-2017	BST	6211419159011814
-	I G P SUNARYANA	CADET DEK	D 074589	06-MAY-2018	PROLA	SPIL/SPM/2016/02/016
22		CADET DEK	E 090129	07-JUN-2019	PROLA	SPIL/SPM/2015/08/006
23	MUHAMMAD TAUFIK	CADET DEK	E 056269	15-FEB-2019	PROLA	SPIL/SPM/2016/09/018
24	JUMEDI MANURUNG	CADET MESIN	D 086783	07-JUL-2018	PROLA	SPIL/SPM/2016/05/024
25	WAHYU EFENDI ASNAN ROIS MABRURI	CADET MESIN	E 057092	16-MAR-2019	PROLA	SPIL/SPM/2016/08/086
26	ASNAN KUIS MABRUKI		NAKHODA	disensity of the second second	adam and a second	

JUMLAH KESELURUHAN ABK = 26 ORANG TERMASUK NAKHODA



SHIP PARTICULARS

NAME OF VESEEL : MV. ORIENTAL RUBY : CONTAINER TYPE OF VESSEL INDONESIA FLAG : CONTAINER OWNER : POGB CALL SIGN 8902125 IMO NO MMSI NO : 525015924 PORT OF REGISTRY : SURABAYA BUILDER : BREMER VULCAN DATE KEEL LAID : 09 MARCH 1989 DATE OF DELIVERY : 12 DEC 1989 GROSS TONNAGE : 18.000 RT NETTO TONNAGE : 10.484 RT LIGHT SHIP 7.623 DEADWEIGHT 26.288 T LOA : 176.572 M LBP : 166.960 M BREADTH MOULDED EKA27.500 M MOULDED DEPTH 14.3 M MAXIMUM HEIGHT 51.8 M TYPE & MAKE OF MAIN ENGINE : BV/Man B & W 7L60 MC OUTPUT OF ENGINE 12180 KW, 16 564.8 Hp AUXILARY ENGINE : DIESEL 3 X 525 Kw (761.7 Hp) (3 X 1325 KVA) 900 Rpm EMERGENCY GEN 1 X 525 KW (761.7 Hs SERVICE SPEED 13 KNOTS PROPELLER : FIXED RIGHT-HANDED 4 - BLADE, ALCUN. BOW THRUSTER 600 Kw / 816 Hp NO OF CRANE & CAPACITY 1 / 2 / 3 SWL (36 Ts - 28.0 Mts) TANK CAPACITY : F0 = 2196.0 Cbm , D0 = 2144 CbmBALLAST CAPACITY : 6409.0 M3 TANK OF FRESH WATER CAPACITY: 336.6 M3 CONTAINER CAPACITY OF ONDECK: 969 Teus

708 Teus

3.82

: 10.73 M

: 10.52

CONTAINER CAPACITY OF INHOLD:

SUMMER FREBOARD

FRESH WATER DRAFT

SUMMER DRAFT

MASTER OF MV. ORIENTAL RUBY

Tabel Evaporation data sheet of EGE Assamble of EGE

SNO

TYPE OF M/ENGINE


HNO-1714/1715/1716/1717 MAN B&W 12K98MC-87080BHP-94RPM-at SMCR HP/AUX BOILER DRUM LP/SEPARATING DRUM


STEAM PRESSURE SATURATION TEMPERATURE FEED WATER TEMPERATURE 0 59 MpaG 164 2 °C 120°C

0 29 MeaG 142 9 °C 120°C


ESTIMATED EVAPO DATA AT SUMMER CONDITION (T/C SUC AIR TEMP.=45°C)

1	OUTLET		ON	APORATION	E\	INLET	EXHAUST GAS	ENGINE
1	GAS TEMP	LP SAT	ATED	SUPERHE.	HP SAT	GAS TEMP	AMOUNT	LOAD
1	7℃	kg/h	kg/h	*C ×	kg/h	°C	kg/h	3
1	1800	3480	17150	229	3500	277 0	570100 × 0 99=564399	MCR
1	1787	3280	15610	228	3500	2721	548500x0 99=543015	95
constraint.	177.5	3100	14330	228	3500	268 5	526700x0 99=521433	90
DES POIN	176 6	2950	13320	229	3500	268.3	504500 × 0.99=499455	NCR/85
	175 B	2810	12520	229	3500	265 3	481800 × 0 99-476982	80
	175.2	2680	11940	229	3500	265 7	458300x0 99=453717	75
1	1747	2560	11480	231	3500	267.3	433900x0 99-429581	70
	1742	2450	11170	232	3500	270 3	408500 × 0 99=404415	85
	173 8	2330	10930	234	3500	274.5	382100x0 99=378279	60
1	1733	2220	10750	238	3500	280 1	354600x0 99=351054	55
1	1728	2090	10550	240	3500	287 0	326000+0 99=322740	50
1	1722	1950	10360	244	3100	295 6	298400x0 99=293436	45
1	171.4	1790	9950	249	3500	304.4	265700 × 0 99=263043	40
J	1700	1800	9070	255	3500	3109	234000+0 99=231680	35
1	168 1	1370	7630	260	3500	3126	201500x0 99=199485	30
	165.6	1120	5610	262	3500	3070	168400x0 99=166719	25






OVERHAUL FIGURE OF CIRCULATING WATER PUMP



No.	Name	No.	Name
1	Coupling Bolt	18	Casing
2	Coupling	19	Impeller Nut
3	Coupling Key	20	Liner Ring
4	Oil Seal	21	Drain Plug
5	Bearing Cover	22	Impeller Key
6	Bearing Lock Nut	23	Impeller
7	Bearing Lock Washer	24	Seat Packing
8	Ball Bearing	25	'O' Ring
9	Oil Cap	26	Neck Bush
10	Oil Level Gauge	27	Grand Packing
11	Bearing Box	28	'O' Ring
12	Casing Cover	29	Grand
13	Ball Bearing	30	Drain Plug
14	Oil Seal	31	Cut Water
15	Stud Bolt & Nut	32	Drain Plug
16	Stud Bolt & Nut	33	Shaft
17	Side Cover	34	Oil Seat

Inner structure of this pump is as illustrated above. Overhaul of this pump must be done carefully with sufficient knowledge of the illustration. Renew the bad parts and keep constant checking in order to make the most of pump capacity.

EGE flow sheet



Rev. No.1

1/2

Procedures for Leaving Port

Work Instructions WI-E-C102 Procedures for Leaving Port

ssue date:	Prepared by: C/E	Approved by: C/E	To: All engine crew members
	C102 Procedures	for Leaving Port	
Voy.:_ 42W09	Date: 27 - MAR - 16	Port: SINGAPURE CI	E: RUS, CLAUDIY
Prepare Engine (1hr	before Departure)		
1 Check Electric	Load & Start additional D/G (if	and \	
D 2 Confirm 1) la	acket C.F.W > 75 °C, 2) BLR	W. Circ PP = RUN, 3) F.O.	supply/circ'PP = RUN
	.C.F.W. Exp. Tk level	CAL.	
3 Start Main LO	pump and check oil flow through	the crank case sight glass.	
4 Start T/C L.O.	pump and check oil flow through	the T/C sight glass.	
	oil pump and check condition.	882 117	
0 Press "M/E ST			Had all Dance
7 Check that "S	tart-up pump" is started automati	cally and running condition,	Hyd. oil Press.
6 Confirm All Inc	d' v <mark>alves are open</mark> ed. and check ampere.(carry out "0"	adjust for SEC power motor	Y
M 5 Start turning a	Time: 19:00	80 Amp	1
6 Carry out "pre		02	
	ube" button on "Auxiliaries - Cyli	nder Lubricators" screen.	
@ Press "ON"			
This opera	tion should be done by "Chief lev	el"	
※ A pre-lubric	cation will be triggered on all cylin	nder and be activated 20 tim	es at the fastest possible
speed.			
	Exh' valve Spring air press is in n		
	<mark>ain of both Air reservoirs an</mark> d Cor no <mark>rmal sound</mark> , leak, level etc, ar		
M 10 Committee au	Hollia sould, leak, level cic, al	Juliu Livi.	
< 30 minutes tur	ming. >		
11 Stop turning 8	disengage turning gear & switch	n off.	
12 Close M/E cor	nt. air line vent valve and check p	oress. Mpa (set. 0.7Mpa)	
	alves of Starting air line (A-23V)		
	arting air valves of No.1&2 Air re	servoirs.	
14 Open Main st		annulan position	
	g plate of Main starting valve on w valve of M/E FO fine filter(F-1s		
14 Close min. no	oom Fans.(1Exh'&2Sup' <case b<="" td=""><td>v case>)</td><td></td></case>	v case>)	
17 Confirm No al	arm on Data Logger CRT & MO	P,M/E Remo-con Panel.	
18 Cut fire alarm			

Ref.	ZZ-S-P-07.20.01 / ZZ-S-P-07.53.00
Posted	
Distributed	ECR,

*** Stand-by Bow thruster (by W/H request) ***

1) Start additional D/G. (Need total 3 sets Generators to start)

2) Stop D/G warm-up pump and close steam inlet vale.

3) Close VCB of No.1&2 Bow Thruster at MSB (3sets+2000kw)

4) Inform to W/H "Ready to start".

Work Instructions	WI-E-C102	Procedyres for Leaving Port	Rev. No.1	2/2
Try Engine & S/B				
1 Inform W/H	"Ready that Ti	ry Engine", and get permittion.		
☑ 2 Request to \				
		n on "Engine - Operation" screen.		
5 Confirm Aux				
-/		n "Engine – Status" screen.		
		carry out Slow-turning.		
		"Slow Turn" button on "Engine - Operation" s	screen, and Confirm co	ondition
		carry out Air running.		
		Run" button on "engine - Operation" screen,	and put telegraph on "	Dead
	en confirm cor			
11 Close all ind	icator valves.			
		gine - Operation" screen.		
		ECR(D/S Ahead & Astern), and confirm norm	nal condition.	
14 Change con	trol position to	W/H, and Try Engine from W/H.		
15 Inform bridge	e "Finish Try E	ngine & it was good condition".		
16 Read flowme	eter & tank lev	el at the timing of S/B engine.		
17 Change acco	ess level from	"Chief level" to "Operator level"		
Start Engine	THE	PAD		
< Check running co	ndition of all r	nachineries closely and carefully. >		
	1	FKA		
		up pump & close steam inlet valve.		
19 Start addition	nal Eng' room	Fan.		
*** Stop Bow thrus	ster (by W/H o	order): VCB off and Stop additional D/Gs. **	*	
Start D/G warn	n-up pump an	d op <mark>en</mark> steam inlet <mark>val</mark> ve.		
/	1 32 6	- 85 M		
20 Carry out Au	x. Boiler soot	blow at an appropriate time.		
*** Change over E.	G.E. damper a	and S/H steam line at the timing of M/E revolu	ution increasing over 5	50rpm.**
_/	10.			
21 Press "S/H o				
22 Check drain	valve (Piston	valve) is <mark>opened</mark> automaticall <mark>y and drai</mark> n valv	e is shut after time up	of its
/ timer (3 min.		1		
		pened automatically.		
		is shut automatically.		
		open" button and check the damper is open	ed automatically.	
26 Check "E.G.	E. by-pass dar	mper" is shut automatically.		
R/U6 & S.O.P				
1 Record flow	meter and cou	unter.		
2 Change Air				
		IGPS from "High" to "Low".		
3 Change Sea	a chest, and M	IGPS from "High" to "Low".		
Change Sea Carry out M	a chest, and Marine-Grit clea	IGPS from "High" to "Low".		
	a chest, and Marine-Grit clea enerator.	IGPS from "High" to "Low". ning.		



Kerusakan pada insulator panas dari *EGE*



Kerusakan pada *cover* dari *EGE*



Perbaikan pada *cover* dari *EGE*



Kerusakan pada pipa EGE



Pemotong<mark>an</mark> pada pipa *EGE*



Pengelasan pada pipa EGE



Kebocoran pada pompa



Pelepasan Pompa



Kerusakan pada mechanical seal



Perngantian pada mechanical seal



Pemasangan high pressure boiler circulating pump

LEMBAR WAWANCARA DENGAN KKM

MV. Oriental ruby

- Cadet : Selamat siang, Chief. Ijin bertanya seputar permasalahan pada *EGE*.

 Apa saja dampak kurangnya kinerja *EGE* terhadap produksi uap pada saat *voyage* di MV.Oriental Ruby?
- KKM : Dampak yang terjadi ketika kurangnya kinerja *EGE* terhadap produksi uap pada saat *voyage* antara lain, banyaknya komsumsi bahan bakar karena penggunaan *boiler* pada saat *voyage* untuk memenuhi kebutuhan media pemanas dalam heater, pemanas tanki bahan bakar, terjadi kebocoran pipa dan rusaknya cover pada *EGE* serta permesinan bantu yang memerlukan produksi uap dalam jumlah besar seperti *A/E turbin generator* memerlukan uap sebagai bahan bakar utama.
- Cadet : Apakah ada hal yang lebih rinci untuk penjelasan A/E turbin generator tidak dapat beroperasi, Chief?
- KKM: Coba lihat pada piping diagram boiler feed water system. Kemungkinan terjadi kebocoran yang mengakibatkan kurangnya air pada saat proses pemanasan.
- Cadet : Siap chief. Seperti kejadian pada tanggal 24 Maret 2017, pada *high* pressure boiler circulating pump terjadi kebocoran benar begitu, Chief?
- KKM : Benar sekali, Cadet! Dan juga terjadi kerusakan pada insulator pemanas dan *cover EGE*.
- Cadet : Apa saja upaya yang dapat dilakukan untuk meningkatkan kinerja EGE terhadap produksi uap, Chief?
- KKM : Pada *high pressure boiler circulating pump* kita lakukan *overhaul* untuk mengetahui bagian mana yang rusak. Kalau terjadi kebocoran pada pompa pasti kerusakan pada *mechanical seal*. Untuk kebocoran pada pipa EGE kita laporkan ke perusahaan agar diperbaiki saat *drydock*.
- Cadet : Siap Chief. Terina kasih atas informasi yang diberikan, semoga bermanfaat bagi saya.

LEMBAR WAWANCARA DENGAN MASINIS 3 (TIGA)

MV. Oriental Ruby

- Cadet : Selamat siang, Bass. Ijin bertanya seputar permasalahan pada *EGE*.

 Apa saja dampak kurangnya kinerja *EGE* terhadap produksi uap pada saat *voyage* di MV. Oriental Ruby?
- Masinis 3: Dampak yang terjadi ketika kurangnya kinerja *EGE* terhadap produksi uap pada saat *voyage* antara lain, banyaknya komsumsi bahan bakar karena penggunaan *boiler* pada saat *voyage* untuk memenuhi kebutuhan steam di kapal.
- Cadet : Apakah seperti kerusakan pada high pressure boiler circulating pump dan cover EGE, Bass?
- Masinis 3: Benar, Cadet! Kerusakan high pressure boiler circulating pump dan cover EGE mengakibatkan kurangnya kinerja EGE terhadap produksi uap pada saat voyage.
- Cadet : Apa saja upaya yang dapat dilakukan untuk meningkatkan kinerja

 EGE terhadap produksi uap, Bass?
- Masinis 3: Pada Kerusakan pada cover EGE dilakukan pemeriksaan pada saat drydock pada bagian EGE termasuk superheater side dan pemberian tanda kerusakan pada superheater side. Diketahui kerusakan pada pipa juga saat drydock dan dilaksanakan pengelasan pada pipa yang bocor dan penggantian cover yang telah rusak pada superheater side. Dilakukan pengawasan pada pengelasan ketika pengecekan harian saat kapal telah meninggalkan drydock. Ketika menemukan kebocoran pipa air panas pada sistem EGE di MV. Oriental Ruby maka untuk menemukan letak kebocoran pada sistem EGE harus mengurutkan pipe line dari A/E turbin generator sampai EGE. Setelah menemukan penyebabnya dilakukan tindakan awal dengan mematikan power di panel room dan memberi tanda "lock out" serta menutup katup masukan dan keluaran pada high pressure boiler circulating pump untuk memhentikan sumber air panas dari feed water tank. Setelah air panas dapat terkendali pipa yang bocor diberi tanda. Sebelum

melaksanakan overhaul dilakukan pemeriksaan pada check alignment coupling, kekurangan/kesalahan grease, visual check lubricating oil dan lubricating oil level. Setelah dipastikan tidak ada masalah dilakukan pembongkaran pada pompa. Pemeriksaan pembongkaran dilakukan dengan memperhatikan body gasket, visual check impeller, casing wear ring clearence, check impeller, volutes, balance hole, gauge dan indikator yang lain. Setelah itu dilakukan pemeriksaan diluar pompa, misalnya flush lines dan quench lines untuk mengetahui apakah terjadi corrosion atau tersumbat pada lines. Hasil dari pemeriksaan ditemukan masalah pada mechanical seal rusak. Perbaikan high pressure boiler circulating pump dilakukan di bengkel agar tidak mengganggu karena suara bising yang ditimbulkan kerja peralatan yang menunjang perbaikan. melakukan perawatan dan perbaikan di MV.Oriental Ruby terdapat mechanical seal yang rusak yang diakibatkan overheat. Pergantian mechanical seal dilakukan sesuai Instruction Manual Book Exhaust Gas Economizer yang menggunakan mechanical seal produk asli dari Shin Shin Machinery. Ukuran dan ketahanan mechanical seal diperhatikan untuk mencegah kebocoran. Selain mechanical seal yang rusak juga terdapat various gasket yang rusak. Setelah selesai diperbaiki dilakukan perakitan kembali dan memasang pompa pada tempatnya. Setelah terpasang dilakukan pengujian untuk memastikan bahwa dapat bekerja dengan normal. setelah melakukan overhaul pada high preassure boiler circulating pump dilakukan kegiatan pengawasan pada bagian yang telah diperbaiki untuk memastikan tidak terjadi kebocoran lagi. Pengawasan juga menjadi upaya untuk respon cepat untuk mengatasi kebocoran pada pipa apabila terjadi kerusakan yang baru.

Cadet : Siap Bass. Terima kasih atas informasi yang diberikan, semoga bermanfaat bagi saya.

