

## DAFTAR GAMBAR

Gambar 2.1.	Kerangka pikir penelitian.....	23
Gambar 3.1.	Fishbone <i>Analysis</i> .....	36
Gambar 3.2.	<i>Fault Tree Analysis</i> .....	41
Gambar 4.1.	Kapal MV. Meratus Malino.....	46
Gambar 4.2.	Struktur Organisasi kapal MV. Meratus Malino.....	49
Gambar 4.3.	Fishbone Diagram.....	50
Gambar 4.4.	Perawatan <i>Cross Deck</i> .....	55
Gambar 4.5.	<i>Jet Chisel</i> .....	57
Gambar 4.6.	<i>Chipping Hammer</i> .....	57
Gambar 4.7.	Hasil <i>Fault Tree Analysis</i> (FTA).....	61
Gambar 4.8.	Pohon Kesalahan 1.....	62
Gambar 4.9.	Pohon Kesalahan 2.....	64
Gambar 4.10.	Pohon Kesalahan 3.....	66
Gambar 4.11.	<i>Bilges</i> Pada Palka.....	67
Gambar 4.12.	Peta Malacca <i>Strait</i> .....	68
Gambar 4.13.	Kondisi Perairan Malacca Strait Dari ECDIS.....	68
Gambar 4.14.	Pohon Kesalahan 4.....	62