MV. ENERGY PROSPERITY	**Non-Conformity Report**		No. : 1 Page : 1 /1 Date : 15/06/2017
Organization	Class NK	Finder	**Class NK (Mr. Yogi)**
Classification	Non-Conformity, Observation	Related basis / Regulation	Annual Survey Periodical Survey
Description			

THE FOLLOWING DEFICIENCIES WAS FOUND DURING SURVEY :

1. STEERING GEAR ROOM NATURAL VENT. COVER – WAS FOUND WASTAGE AND CORODED
2. FOUND HOLE ON WATER TIGHT DOOR FOR ACCOMODATION ACCES (AFT)
3. HOLE ON EMERGENCY GENERATOR ROOM NATURAL VENT.
4. MISSING RUBBER AND WASTAGE ON RUBBER HOUSING OF SMALL HATCH
   a. C/H N0.7 AFT
   b. C/H NO.5 FWD
   c. C/H NO.3 FWD
   d. C/H NO.2 FWD
5. ECCESSIVE OIL ON ENGINE ROOM AROUND THE FOLLOWING AREA:
   a. F.O PURIFIER NO.1 AND NO.2
   b. F.O FILTER
   c. F.O TRANSFER PUMP
   d. D.O TRANSFER PUMP

ALL DEFFICIENCIES SHOULD BE RECTIFIED WITH DUE DATE 24 JUNE 2017

Plan for Correction/Improvement (Due date :)

Head of Division/Master (DD/MM/YY) Finder (DD/MM/YY)

Detail of Corrective/improvement (Completed date:)	YES☐, NO☐ Preventive Action

Head of Division/Master _____ sign	
Comment of Finder : Finder : _____ sign	
Final Confirmation	☐ Completion, Identification of data/field ☐ Re-corrective Action DP : _____ sign