

## LAMPIRAN



Gambar: Overhaul pompa *bilge* palka

Di MV. KT 02

LAMPIRAN



Gambar: Pecahnya *ball bearing* pompa *bilge* palka

Di MV. KT 02

## LAMPIRAN



Gambar: Pompa *bilge* palka

Di MV. KT 02

## LAMPIRAN



Gambar: *Control panel engine side pompa bilge palka*


Di MV. KT 02

**LAMPIRAN**



Gambar: Ausnya *shaft* pompa akibat gesekan  
Di MV. KT 02

**LAMPIRAN**



Gambar: Proses pemberian Grease

Di MV. KT 02

**LAMPIRAN**



Gambar: Bengkokny *shaft* pompa akibat getaran tinggi

Di MV. KT 02

**LAMPIRAN**



Gambar: *Mounth ring* dalam pompa *bilge palka*

Di MV. KT 02