## **HANDIL 2 BASE - INCIDENT RECORD 2014**

## **HIPO & RECORDABLE INJURY**

No	Synergi No.	Case date	Case Description	Туре	Location	Activity	MEV	Contractor	Root Cause
1	434507	24-Jan-14	BG. ADAM 1801 HIT Villager House when towed By TB. MEGA DELTA	ніт	CPU	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Rejeki Abadi Sakti	Lack of risk assessment (Current prediction failure)
2	433450	25-Jan-14	AB of TB ASL Prima IX Slip and Hit the door of bathroom. He got open wound (1.5cm) at his right upper palpebra	Slip	SPU	NA	LSA/HDL/TRP	PT. Agus Suta Line	Working area was congested
3	434230	02-Feb-14	LCT. Surya Fortuna HIT SPOB AJ Putra at Handil Piling Area	НІТ	HDL -	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Bina Insan Sukses Makmur	Lack of risk assessment (Maneuver during strong current)
4	435251	03-Feb-14	Chief Officer SPOB AJ Putra Slipped while in the bathroom resulting minor abrasion on his forehead	ENSIDE	BANGA	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Cindara Pratama Lines	Lack of Vigilant
5	438926	10-Mar-14	Pin hole at ballast tank no.2 of adimas 2 due to pushed by TB Megawati 23 at tn-Ax71 during maneuvering	НІТ	SPU	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Agus Suta Line	Lack of vigilant (by Master)
6	441925	31-Mar-14	ST. Long Peso was squeezed between CB. ASL 69 and Protection pile at GTS. AA	HIT	SPU	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Pel. Teluk Bajau Cipta Sejahtera	Not comply with procedure (no Work permit, no supervisoin)
7	447096	17-Apr-14	Scratch wounds on the left index finger a/b Tb. Forissa 88	Pinch	HDL	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Rejeki Abadi Sakti	No Appropriate PPE used
8	444258	18-Apr-14	Index Finger Pinch Between Shackle Pin and Drum Lifting Tools during Loading Chemical Drum	Pinch	SPU	Maritime (Marine Transport)	LSA/HDL/TR <b>P/SP</b> U	PT. Pel. Teluk Bajau Cipta Sejahtera	Not comply procedure (Signal man is not certified)
9	446424	08-May-14	ST DRIVER threw himself in the water and disappeared in the fish pound	NA	SPU	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Imako Perkasa	Physical Condition down and Stress
10	447398	09-May-14	Testing Barge BDU 1202 assisted by TB. Logindo Graceful touch anchor buoy of CB ASL 28	Touch	СРА	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Logindo Samudramakmur	Lack of procedure (No anchor buoy light available)
11	449125	28-May-14	ST. Kuda Laut 5 Stranded at Muara Ulu Area	Stranded	HDL	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Sea Horse	Taking shortcut
12		02-Jun-14	Slipped Over While Embarking The Sea Truck Kuda Jaya	Slip	HDL	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Sea Horse	Lack vigilant
13	457293	07-Aug-14	Scratch wounds at right palm of ST. Laju Perdana Helper	Hit	HDL	Maritime (Marine Transport)	LSA/HDL	PT. Pel. Kanaka	Lack of safety awereness (modification used tool)
14		24-Aug-14	Handrail of Barge Delta Biru was broken due to hit TB Teluk Bajau Alpha during positioning at TN-R17 9SPU)	HIT	HDL	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Agus Suta Line	Not comply with procedure (Master not meet with requirements)
15	459794	01-Sep-14	Sea Truck RUHEN-11 hitting sign board around GTS-N	НІТ	HDL	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Ekalya Purnamasari	Mechanical Failure
16	460463	05-Sep-14	ST Ruhen 01 was stranded at Muara Ulu Kecil when sailing from Handil to Hibiscus rig (TN-AA9)	Stranded	HDL	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Ekalya Purnamasari	Lack of safety awereness (Taking shortcut)
17	461146	11-Sep-14	Bg. BDU 1502 towed by TB. ASL Prima IX was stranded around 14 meter from trunkline GTS-JIL to NMP-1	Stranded	HDL	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Agus Suta Line	Not comply with procedure (Lack of experinace of master)
18	464179	08-Oct-14	Barge Sinar Handil drifted nearby GTS AA	Drifted	SPU	Maritime (Marine Transport)	LSA/HDL/TRP	PT. Bina Insan Sukses Makmur	Inadequate of equipments
19		10-Oct-14	Anchor HB. MG II Dropped when her was towed by TB MSS. Lincoln	N/A	HDL	Maritime (Marine Transport)	LSA/HDL/TRP		Lack of procedure (Anchor not secured during traveling)

No	Synergi No.	Case date	Case Description	Туре	Location	Activity	MEV	Contractor	Root Cause
20	465017		Finger injury of TB Servewell Patriot 1's oiler due to pinched by battery box cover	Pinch	SPU	Maritime (Marine Transport)	LSA/HDL/TRP/SP U		Not use PPE No risk assessment by victim
21	469742	23-Nov-14	ST Ambalat hit by Drifting Drilling Supporting Barge	Drifted	SPU	Maritime (Marine Transport)	LSA/HDL/TRP		Not comply with procedure (more than 3 barges moored on one group)

