

LSA - INCIDENT RECORD 2013

HIPO & RECORDABLE INJURY

No	Synergi No.	Case date	Case Description	Type	Location	Activity	MEV	Contractor	Root cause
1		06-Jan-13	Pile @ TN-C61 is slanted due to towing line entangled during towing operation Bg Delta biru by TB Alim 20 and TB Megawati 7	Hit	SPU	Marine Transport	LSA/MAR	PT. Alim Shipping	Operating at improper parameter
2	475741	08-Jan-13	Landing boat of Elsa 5 was lightly damaged due to hitting safety piling @ M3 channel (CPA) during towing operation by TB Harmony and Tik Bajau Harapan	Hit	CPA	Marine Transport	LSA/HDL/TRP	PT Pel Teluk Bajau Cipta Sejahtera	Last minutes risk assessment failure
3	474891	10-Jan-13	ST Long Belayan punctured by an object from the river (possible woodstick) during low tide condition (vessel was standing-by and moored)	Caught	SPU	Marine Transport	LSA/HDL/TRP	PT Pel Teluk Bajau Cipta Sejahtera	Failling inspection
4	475160	13-Jan-13	LCT Kuda Sembrani stranded at shallow area between navigation point 43 - 44 while navigating from HDL -SPU	Stranded	HDL	Marine Transport	LSA/HDL/TRP	PT Sea Horse	Tacking Shortcut (out of recommended Route)
5	476604	25-Jan-13	Crew of TB KJ 07 got finger injury while mooring at safe area TM-89	Pinch	CPU	Marine Transport	LSA/HDL/TRP	PT Karya Jaya Samudra	- Hasty work execution - Not using PPE
6	479086	19-Feb-13	TB Bahari Rejeki was trapped between piling & FTB KLP5 while holding FTB Wimsen3 which is towed by TB Alim XXI during positioning to piling HDL	Trapped	Handil (Piling Area)	Marine Transport	LSA/HDL/TRP	PT Bahtera Rezeki Abadi	Lack of safety awareness
7	479734	25-Feb-13	Cable battery burnt in engine room ST Long Palay	Fire	SPU	Marine Transport	LSA/HDL/TRP	PT Pel Teluk Bajau Cipta Sejahtera	Lack of maintenance
8		28-Feb-13	LCT. Logindo Hopfull hit North Manifold Platform during maneuvering to alongside	Hit	NPU	Marine Transport	LSA/HDL/TRP	PT. Logindo Samudra Makmur	Not Comply With Procedure (Out off route)
9	484782	20-Apr-13	LCT. Surya Fortuna slightly contact with LCT. Karyl when cast off from jetty II	Hit	Jetty II Handil Base	Marine Transport	LSA/HDL/TRP	PT. Alim Shipping	Lack of safety awareness
10	485559	23-Apr-13	ST Long Maninjau collide fisherman's boat	Collision	SPU Passenger Jetty	Marine Transport	LSA/HDL/TRP	PT Pel Teluk Bajau Cipta Sejahtera	Not Comply With Procedure (over Speed)
11		27-May-13	LCT Logindo Hopefull Stranded at NPU Area	Stranded	NPU	Marine Transport	LSA/HDL/TRP	PT. Logindo Samudra Makmur	Not Comply With Procedure (Out off route)
12		06-Jun-13	TB. ASL Prima X propeller twisted by Mooring rope during barge positioning at Rig Rasis on 06/06 at 20.00	Entangled	NPU	Marine Transport	LSA/HDL/TRP	PT. Agus Suta Line	Not Comply procedure (No Supervsion)
13		11-Jun-13	ST. Mirza 21 hit astiku jetty during travelling for crew change	Hit	SPU	Marine Transport	LSA/HDL/TRP	PT. Teluk Bajau	Not Comply With Procedure (Out off route)
14	492169	21-Jun-13	Setiawati propelled entangled by towing rope during moving activity from TN-C23 to TN-C138	Entangled	SPU	Marine Transport	LSA/HDL/TRP		Not Comply with Procedure (NO Permit available)
15	496634	02-Jul-13	TB SSS Mahakam stranded & FTB Baiduri 18288 drifted	Stranded	GTS L	Marine Transport	LSA/HDL/TRP	PT. Pel Karya Lentari Perdana	Lack fo risk assessment (Weather condition, current, wind)
16	494523	17-Jul-13	ST Ruhen 3 stranded at north of Pulau Merdeka	Stranded	Pulau Merdeka (Handil)	Marine Transport	LSA/HDL/TRP	PT. Pelayaran Nasional Ekalya	Tacking Shortcut (NO in recommended Route)
17	496347	31-Jul-13	ST Mirza 46 hit unseen marine hazard (broken pile) at RC 12	Hit	RC 12	Marine Transport	LSA/HDL/TRP	PT. Teluk Bajau	Not comply with Procedure (No complementary permit attached)
18		19-Aug-13	Gaya Pelaut hit ST Ruhen 16	Hit	HDL	Marine Transport	LSA/HDL/TRP	PT. Pelayaran Nasional Ekalya	Engine Failure
19		23-Aug-13	SPOB Sea Lion Passing Over River Crossing 86 with UKC below 1.5 m	SPOB	RC 86	Marine Transport	LSA/FMC	PT. Cindara Pratama	Not comply with procedure (UKC Minimum 1.5m)
20		29-Aug-13	LCT LOGINDO JOYFULL HIT STARBOARD SIDE LCT WITHBY(STANDBY POSITION) DURING MANOUVER ALONGSIDE LCT.WHITBY	Hit	HDL piling	Marine Transport	LSA/HDL/TRP	PT. Logindo Samudra Makmur	Lack Of safety awareness (Manouver during strong current)
21		31-Aug-13	ST. CYGNUS STRANDED AT HTC AREA G116	Stranded	HDL jetty	Marine Transport	LSA/HDL/TRP	PT. Sahabat Samudra Sejahtera	Not Comply with procedure
22		01-Sep-13	Rope entangled by LCT Berkat Anugrah's propeller	Entangled	Rasis	Marine Transport	LSA/HDL/TRP		Lack of safety awareness
23		13-Sep-13	TB Harmoni3 towing Hopper barge Capitol3 found stranded close to HVB (100m)	Stranded	HDL	Marine Transport	LSA/HDL/TRP		Taking shortcut
24	500423	16-Sep-13	Parted towing rope of TB Crest Aqua during rig move operation	drifted	Point 47	Marine Transport	LSA/HDL/TRP		Equipment defective

25	501914	27-Sep-13	Chemical barge Liputan XII hit rig	Hit	GTS-C	Marine Transport	LSA/HDL/TRP	Lack of safety awareness
----	--------	-----------	------------------------------------	-----	-------	------------------	-------------	--------------------------

