



Cargo lines cooldown

Illustration 6.3.2a Cargo Lines Cool Down




Loading with vapour return to shore

Illustration 8.3.3a Loading with Vapour Return to Shore




De-Ballasting

Illustration 8.3.4a De-Ballasting




Liquid lines cool down before discharging

Illustration 8.5.2a Liquid Line Cool Down before Discharging




Arm cooldown before discharging

Illustration 8.5.3a Arm Cool Down before Discharging



Discharging with gas return from shore

Illustration 8.5.4a Discharging with Gas Return from Shore



Ballasting

Illustration 8.5.6a Ballasting

