MT. SINAR JOGYA	ITEM DEFECTS	MR.10
Ref. No. : 04/10/SJ/M	FLEXIBLE EXPANSION JOINT	
Item Code	Report date: 16 th October 2010	
	DEFECT REPORT	
Summary Description	: 3 pcs expansion joint for cargo pipe line found leaking Size : Diam. 445 mm x 300 mm.	
Repair Specification	: Rewelding	
Cause of Defect :	MT SALA MORA	Λ
Master:	Chief	Officer: Marlint
V	FOR OFFICE USE ONLY	
Reviewed by Company	Approve to action : Yes Deffered until next dry docking :	☐ No
	Planned Completion date :	
	Carried out by :	
	Completion date :	