

LAMPIRAN 1

MARINE ACCIDENT URGENT REPORT

Ref. No. : 002/DK01/D/02/2017

1. Title of Sea Casualty (Marine Accident)		PORTSIDE ANCHOR LOOSE FROM THE PIN
2. Date		16TH February 2017
3. Place		Point Direction Mile (Lat. 07-45,55 S, Long.109-04-55 E
Ship in Sea Casualty	4. Ship's name	MV DK 01
	5. Ship's Register No.	
	6. Gross Tonnage	39219
	7. Type (age)	1991
	8. Personnel on board	Total Crew O/B 28 Person
	9. Owner	PT. KYK Lines / Operator PT Karya Sumber Energy
	10. Master (License)	ANT I
State of Da mage	11. Human life	
	12. Ship	MV DK 01
	13. Other	Portside Anchor Loose From The Pin
14. Summary		Let go anchor at 0130 LT the depth of water normal 20 m, then the brake can not handel the chain anchor then at 0137 LT portside anchor loosing
15. Causes (Estimated)		Most probably the brake not checking and directly to using as normal.
16. Measures taken		We hoping office can sent the diver as soon as possible to find out the chain anchor
17. State of Insurance		Hull Insurance : Seaman (Passenger's Insurance) : P & I Insurance :

