



LAMPIRAN 4

New software installation

INVESTIGATION / JOB DETAILS



/// Before 6hrs WIOS Trend (65%Load) ///

/// After 7hrs WIOS Trend (63%Load) ///





<A Bank Exh Gas Temp>

<A Bank Exh Gas Temp>




<B Bank Exh Gas Temp>

<B Bank Exh Gas Temp>




<A Bank Exh Gas Temp Dev>


<A Bank Exh Gas Temp Dev>




<B Bank Exh Gas Temp Dev>




<B Bank Exh Gas Temp Dev>




<A Bank Off Set>




<A Bank Off Set>



<B Bank Off Set>



<B Bank Off Set>



Sumber : Dokumentasi Kapal MV. Tangguh Foja 2016