

## LAMPIRAN 2

<b>ACCIDENT REPORT (<i>Laporan Kecelakaan</i>)</b>			
TO (Ditujukan)	Mr. Suhafrinal	C.C	Andre Astono Operational KSE Personnel KSE
FROM (Dari)	MV DK 01	REF.NO.	002/DK01/D/02/2017
DATE (Tanggal)	16 February 2017	PAGE (Halaman)	1
TITLE (Judul)	Portside Anchor Loose From The Pin		
1. Summary (Ringkasan)			
Let go anchor at 0130 LT the depth of water normal 20 m, then the brake can not handel the chain anchor then at 0137 LT portside anchor loosing.			
2. Cause of accident (Penyebab Kecelakaan)			
Most probably the brake not checking and directly to using as normal			
3. Contents of damage/loss (Isi Kerusakan)			
- Brake unfunctional			
4. Actions by ship (Tindakan oleh Kapal)			
1. To check and report as soon as possible			
5. Count measures to prevent recurrence (Menghitung langkah-langkah pencegahan terulang kembali)			
1. To check and detail before action			
6. Others(Lesson, Assistance from shore etc.) (Lainnya (pelajaran, bantuan dari pantai dll)			
-			