

OPTIMALISASI PERAWATAN SEKOCI PENOLONG DI MT. SUNGAI GERONG

SKRIPSI

Diajukan untuk memperoleh gelar Sarjana Terapan Pelayaran pada

Politeknik Ilmu Pelayaran Semarang

Oleh

BAHTIANUL MUBARAK NIT. 52155590 N

PROGRAM STUDI NAUTIKA DIPLOMA IV POLITEKNIK ILMU PELAYARAN SEMARANG

2020



OPTIMALISASI PERAWATAN SEKOCI PENOLONG DI MT. SUNGAI GERONG

SKRIPSI

Diajukan untuk memperoleh gelar Sarjana Terapan Pelayaran pada

Politeknik Ilmu Pelayaran Semarang

Oleh

BAHTIANUL MUBARAK NIT. 52155590 N

PROGRAM STUDI NAUTIKA DIPLOMA IV POLITEKNIK ILMU PELAYARAN SEMARANG

2020

HALAMAN PERSETUJUAN

OPTIMALISASI PERAWATAN SEKOCI PENOLONG DI MT. SUNGAI GERONG

Disusun oleh:

BAHTIANUL MUBARAK NIT, 52155590 N

Telah disetujui dan diterima, selanjutnya dapat diujikan di depan

Dewan Pengui Politeknik Ilmu Pelayaran Semarang

Semarang,...

Dosen Pembinibing

Materi

Dosen Pembimbing II

Metodologi dan Penulisan

Capt. H. S. SUMARDI, S.H., M.M., M.Mar

Pembina Utama Muda (IV/c) NIP, 19560625 198203 1 002 Dr. WINARNO, S.ST, M.H Penata Tingkat I (III/d) NIP. 19760208 200212 2 002

Mengetanui,

0

Kotua Program Studi Nautika

Capt. DWI ANTORO, M.M. M.Mar

Penata Tingkat I (III/d) NIP. 19740614 199808 1 001

HALAMAN PENGESAHAN

Skripsi dengan judul "Optimalisasi Perawatan Sekoci Penolong di MT, Sungai

Gerong" karya,

Nama : Bahtianul Mubarak

NIT : 52155590 N

Program Studi : Nautika

Telah dipertahankan di hadapan Panitia Penguji Skripsi Prodi Nautika, Politeknik

Ilmu Pelayaran Semarang pada hari Selasa tanggal 28 - 01 - 2020

Semurang 28 - 01 - 2020

Penguji I.

Dr. Capt. SUWIYADI, M.Pd., M.Mar Pembina Utama Muda, (IV/c) NIP, 19550419 198303 1 001 Capt. H. S. SI MARDI, S.B., M.M., M.Ma

Penguji II.

Pembina Utama Moda, (TV/c) NIP, 19560625 198200 1 002 MOH. ZAENA Per

Penata (III/e) NEP, 19760309 201012 1 002

Penguji III,

Mengetahui Direktur Politeknik Ilmu Pelayaran Semarang

Dr. Capt. MASHUDI ROFIK, M.Sc Pembina Tk. I (IV/b) NIP. 19670605 199808 1 001

PERNYATAAN KEASLIAN

Yang bertanda tangan di bawah ini:

Nama

: Bahtianul Mubarak

NIT

: 52155590 N

Program Studi

: Nautika

Skripsi dengan judul "Optimalisasi Perawatan Sekoci Penolong di MT, Sungai

Gerong"

Dengan ini saya menyatakan bahwa yang tertulis dalam skripsi ini benar-benar hasil

karya (penelitian dan tulisan) sendiri, bukan jiplakan dari karya tulis orang lain atau

pengutipan dengan cara-cara yang tidak sesuai dengan etika keilmuan yang berlaku,

baik sebagian atau seluruhnya. Pendapat atau temuan oranglain yang terdapat dalam

skripsi ini dikutip atau dirujuk betdasarkan kode etik ilmiah. Atas pernyataan ini,

saya siap menanggung resiko/sanksi yang di jatuhkan apabila ditemukan adanya

pelanggaran terhadap etika keilmuan dalam karya ini.

Semarang, 24 - 01 - 2020

Yang menyatakan pernyataan,

BAHTIANUL MUBARAK

NIT. 52155590 N

MOTO DAN PERSEMBAHAN

"Boleh jadi kamu membenci sesuatu padahal ia amat baik bagimu, dan boleh jadi pula kamu menyukai sesuatu padahal ia amat buruk bagimu, Allah mengetahui sedang kamu tidak mengetahui" (QS Al Baqarah : 216)

Persembahan:

- 1. Kedua orang tua, Ayah (Alm) H. Ahmad dan Ibu HJ. Amina
 - 2. Kakak peneliti, Muallifah, Halipi dan Nurul Aini
 - 3. Almamater saya, PIP Semarang
 - 4. Capt. H. S. Sumardi, S.H., M.M, M.Mar selaku pembimbing I
 - 5. Dr. Winarno, S.ST, M.H selaku pembimbing II
 - 6. Anggota mess pudak
 - 7. Taruna taruni angkatan 52
 - 8. Seluruh crew MT. Sungai Gerong

PRAKATA

Alhamdulillah. Puji syukur penulis panjatkan kehadirat Allah SWT, Tuhan yang Maha Esa, karena berkat limpahan rahmat serta karunianya, penulis dapat menyelesaikan skripsi ini.

Skripsi ini mengambil judul "Optimalisasi Perawatan Sekoci Penolong di MT. Sungai Gerong" dan penulisannya dilakukan dalam rangka memenuhi salah satu syarat untuk untuk mencapai gelar Sarjana Sains Terapan Pelayaran pada Program Studi Nautika Politeknik Ilmu Pelayaran Semarang.

Dalam usaha menyelesaikan penulisan skripsi ini, penulis menyadari bahwa tanpa adanya pihak-pihak yang telah memberikan bimbingan, bantuan dan masukan kepada penulis, skripsi ini tidak akan terwujud. Oleh karena itu penuliis menyampaikan ucapan terima kasih kepada yang terhormat:

- Dr. Capt. Mashudi Rofik, M.Se. M.Mar selaku Direktur Politeknik Ilmu Pelayaran Semarang.
- 2. Capt. Dwi Antoro, MM, M.Mar selaku ketua jurusan Nautika PIP Semarang.
- Capt. H. S. Sumardi, S.H., M.M, M.Mar selaku pembimbing I dan Dr. Winarno, S.ST, M.H selaku pembimbing II yang telah menyempatkan waktu diantara kesibukannya untuk membimbing penulis menyusun skripsi ini.
- Kedua orang tua peneliti, Ayah (Alm) H. Ahmad dan Ibu HJ. Amina serta Kakak peneliti, Muallifah, Halipi dan Nurul Aini.
- Seluruh dosen di PIP Semarang yang telah memberikan bekal ilmu pengetahuan yang sangat bermamfaat dalam membantu proses penyusunan skripsi ini.

- PT. BSM CSC Indonesia yang telah memberikan kesempatan untuk melaksanakan praktek laut.
- Kunti Priastuti, terimakasih atas segala bentuk perhatian, kesabaran dan selalu memberikan semangat dalam menyelesaikan skripsi ini.
- Taruna Taruni Angkatan 52 Politeknik Ilmu Pelayaran Semarang , saudara se-perjuangan selama empat setengah tahun.
- Anggota Mess Pudak (Ahmad Sofyan, M. Fakhruddin Fakhri, Zulham Pradana, Ryandhika Fathan) yang selalu memotivasi dalam penulisan skripsi ini.
- 10. Kelas N VIII B, atas dua semester yang penuh cerita suka dan duka.
- Seluruh crew MT. Sungai Gerong yang telah memberikan banyak ilmu dan pengalaman yang tak terlupakan kepada peneliti pada saat praktek laut.

Akhir kata, semoga Allah SWT membalas segala kebaikan seluruh pihak yang telah membantu penulis sejak awal hingga akhir berkuhah di Politeknik Ilmu Pelayaran Semarang. Skripsi ini untuk kalian semua.

Semarang, 24-01-2020

BAHTIANUL MUBARAK NIT, 52155590 N

Penulis

DAFTAR ISI

HALAM	1AN JUDUL	i
HALAM	MAN PERSETUJUAN	ii
HALAM	MAN PENGESAHAN	iii
HALAM	1AN PERNYATAAN	iv
HALAM	MAN MOTTO DAN PERSEMBAHAN	v
PRAKA	TA	vi
DAFTA]	R ISI	viii
A DOTED	AKSI.	
ABSTRA	AKSI	X
ABSTRA	ACT.	xi
DAETAI	R TABEL	::
DAFTA]	R GAMBAR	xiii
DAFTA]	R LAMPIRAN	xiv
	100	
BAB I	PENDAHULUAN.	
	1.1 Latar belakang	
	1.2 Rumusan masalah	
	1.3 Tujuan penelitian	2
	1.3 Tujuan penenuan	3
	1.4 Manfaat penelitian	4
	1.5 Pembatasan masalah	4
	1.6 Sistematika penulisan	5
BAB II	LANDASAN TEORETIS	8
	2.1 Tinjauan pustaka	8
	2.2 Definisi operasional	17

2.3 Kerangka pikir	19			
METODE PENELITIAN	.21			
3.1 Pendekatan dan desain penelitian	21			
3.2 Fokus dan lokus penelitian	23			
3.3 Sumber data penelitian	24			
3.4 Teknik pengumpulan data	25			
3.5 Teknik analisis data	28			
HASIL PENELITIAN DAN PEMBAHASAN	30			
4.1 Gambaran umum objek yang diteliti	30			
4.2 Hasil penelitian	33			
4.3 Pembahasan	43			
PENUTUP	70			
5.1 Simpulan	70			
5.2 Saran	71			
DAFTAR PUSTAKA				
LAMPIRAN				
DAFTAR RIWAYAT HIDUP				
	METODE PENELITIAN			

ABSTRAKSI

Mubarak, Bahtianul. (NIT.52155590N), 2020. "Optimalisasi perawatan sekoci penolong di MT. Sungai Gerong". Skripsi. Program Diploma IV, Program Studi Nautika, Politeknik Ilmu Pelayaran Semarang. Pembimbing I: Capt. H. S. Sumardi, S.H., M.M, M.Mar. Pembimbing II: Dr. Winarno, S.ST, M.H.

Sekoci penolong merupakan salah satu alat keselamatan yang digunakan untuk meninggalkan kapal pada saat terjadi keadaan darurat yang bertujuan untuk menyelamatkan jiwa *crew* kapal yang berada di atas kapal. Sekoci penolong harus selalu dalam kondisi siap untuk digunakan, maka diperlukan perawatan sesuai dengan standar dalam SOLAS bab III yang membahas tentang standarisasi alat—alat keselamatan diatas kapal termasuk sekoci penolong.

Analisis dalam penelitian ini adalah untuk menjelaskan perawatan sekoci penolong sesuai dengan SOLAS 1974, memecahkan masalah tentang kendala-kendala dalam pelaksanaan perawatan sekoci penolong dan upaya untuk mengatasi kendala-kendala pelaksanaan perawatan sekoci penolong. Sebelum melaksanakan perawatan sekoci penolong harus ada perencanaan perawatan, sehingga dapat diketahui bagian sekoci penolong yang membutuhkan penanganan terlebih dahulu, dengan demikian mualim tiga dapat bekerja secara efektif dan efisien sehingga tidak banyak waktu yang terbuang.

Dalam penulisan skripsi ini peneliti menggunakan metode kualitatif. Observasi, wawancara dan studi pustaka dilakukan untuk mengumpulkan data yang relevan. analisis data diartikan sebagai kegiatan yang dilakukan untuk merubah data hasil dari sebuah penelitian menjadi informasi yang nantinya bisa dipergunakan untuk mengambil sebuah kesimpulan.

Berdasarkan hasil penelitian, dapat diketahui bahwa peneliti menguraikan tentang hasil-hasil yang diperoleh selama dilaksanakannya penelitian, yaitu perawatan sekoci penolong di MT. Sungai Gerong sesuai dengan ketentuan SOLAS 1974 dan PMS (*Plan Maintenance* System) dari perusahaan, akan tetapi sedikitnya waktu dalam melaksanakan perawatan menjadi kedala dalam pelaksanaan perawatan sekoci penolong. Kendala tersebut harus diatasi dengan cara membagi tugas antara Mualim 3 dan Mualim 4 dalam pelaksanaan perawatan sekoci penolong, dengan cara membagi tugas perawatan sekoci penolong bisa maksimal meskipun hanya mempunyai waktu yang sedikit untuk melaksanakan perawatan.

Analisis data menghasilkan simpulan bahwa kendala dalam pelaksanaan perawatan sekoci penolong adalah *crew* kapal kurang memahami sepenuhnya perawatan sekoci penolong dan tidak adanya suku cadang. Upaya mengatasi kendala tersebut adalah dengan cara melakukan pelatihan kepada *crew* terkait perawatan sekoci penolong yang baik dan benar sesuai dengan prosedur perawatan dan meminta suku cadang kepada perusahaan agar dalam pelaksanaan sekoci penolong tidak mengalami hambatan.

Kata kunci: perawatan sekoci penolong, kendala, upaya, PMS

ABSTRACT

Mubarak, Bahtianul. (NIT.52155590N), 2020. " *Optimization Lifeboat Maintenance At MT. Sungai Gerong* ". Thesis. Diploma IV Program. Nautical Studies. Semarang Merchant Marine Polytechnic. 1st Supervisor: Capt. H. S. Sumardi, S.H., M.M, M.Mar. 2nd Supervisor: Dr. Winarno, S.ST, M.H.

Lifeboat is one of the safety equipments used to leave the ship when there is an emergency situation that aims to save the life of the crew on board of the ship. The lifeboat must be always in a ready condition for use, so required to maintenance in accordance with the standards in SOLAS chapter III which discusses the standardization of safety equipments on board including the lifeboat.

The analysis in this study is to explain the maintenance of lifeboat accordance with SOLAS 1974, solve the problems regarding the constraints in carrying out lifeboat maintenance and the efforts to overcome the constraints of carrying out lifeboat maintenance. Before carrying out lifeboat maintenance, there must be a maintenance plan, so that it can be known the lifeboat parts needs to be handled first, thus the third officer can work effectively and efficiently so that not much waste of time.

In writing this thesis researcher used a qualitative method. Observations, interviews and literature studies conducted to collect relevant data. Data analysis is defined as the activities carried out to change the results data from a study into information that can be used to take a conclusion.

Based on the results of the study, it can be known that the researcher elaborate on the results obtained during the course of the study, that is lifeboat maintenance at MT. Sungai Gerong has been accordance with the provisions of SOLAS 1974 and PMS (Plan Maintenance System) of the company, but lack of time in carrying out the maintenance becomes the constraint in the implementation of the lifeboat maintenance. This constraint must be overcome by dividing the tasks between third officer and fourth officer in carrying out lifeboat maintenance, by dividing the tasks lifeboat maintenance can be maximal even though they only have a little of time to carry out maintenance.

Data analysis resulted in the conclusion that the constraint in carrying out lifeboat maintenance was that the crew did not fully understand lifeboat maintenance and lack of spare parts. The effort to overcome the obstacle is by conducting training to the crew related to the lifeboat maintenance that is good and right in accordance with maintenance procedures and asking for spare parts to the company so that the implementation of lifeboat maintenance does not obstacle experience.

Keywords: *Lifeboat maintenance, constrain, Effort, PMS*

DAFTAR TABEL

Tabel 4.1 Ship's particular MT. Sungai Gerong	31
Tabel 4.2 Pemeliharaan <i>lifeboat</i>	44
Tabel 4.3 Muster List MT. Sungai Gerong	65



DAFTAR GAMBAR

Gambar 2.1 Kerangka pikir20	0
Gambar 4.1 MT. Sungai Gerong	3
Gambar 4.3 Mualim tiga memberi grease pada wire agar tidak mengalami	
kemacetan saat penurunan sekoci	5
Gambar 4.3 Hook sekoci berkarat3	9
Gambar 4.4 Pelaksanaan safety meeting	3
Gambar 4.5 Pemeriksaan peralatan sekoci penolong5	7
Gambar 4.6 Davit sekoci penolong berkarat	0
Gambar 4.7 Pelaksanaan drill MT. Sungai Gerong	9
EKA D D	

DAFTAR LAMPIRAN

Lampiran 1 Ship particular

Lampiran 2 Crewlist

Lampiran 3 Hasil wawancara

Lampiran 4 *Installation of boat*

Lampiran 5 Lifeboat operation instruction

Lampiran 6 Lifeboat engine operation instruction

Lampiran 7 Gambar perawatan sekoci penolong

Lampiran 8 Statement of conformity annual inspection lifeboat

Lampiran 9 Item list lifeboat

Lampiran 10 Lifeboat weekly and monthly inspection

Lampiran 11 Permintaan peralatan sekoci penolong

BABI

PENDAHULUAN

1.1 Latar Belakang.

Angkutan laut adalah salah satu jenis moda transpotasi yang sekarang ini perkembangannya menjadi faktor utama dan sangat potensial dalam kemajuan di sektor ekonomi maupun sektor non ekonomi. Selain sebagai sarana transportasi antar pulau, angkutan laut juga dapat membina hubungan antar negara dalam tukar menukar teknologi dan perekonomian termasuk ekspor dan impor barang yang sebagian besar melalui laut. Dengan adanya angkutan laut akan meningkatkan tingkat perdagangan yang mengacu pada tingkat pertumbuhan ekonomi di sektor laut.

Guna mencapai mutu pelayaran yang baik dan berkualitas, perlu di tingkatkan bagaimana mengembangkan sumber daya manusia yang bergerak dalam bisnis pelayaran, guna meningkatkan jasa pengiriman barang sebaik mungkin dari satu tempat ke tempat lain. Dalam operasionalnya bisnis pelayaran bukanlah bisnis yang tanpa resiko, salah satu resiko yang sering terjadi adalah kecelakaan kapal yang di sebabkan oleh faktor dari luar maupun faktor dari dalam seperti cuaca buruk, gelombang tinggi, atau kebakaran yang dapat menenggelamkan kapal.

Kecelakaan di laut yang terjadi dapat mengakibatkan banyak korban jiwa, salah satu penyebab banyak jatuhnya korban jiwa adalah karena kurangnya perawatan serta kemampuan anak buah kapal dalam merawat dan mengoperasikan alat keselamatan yang ada di atas kapal.

Untuk mengantisipasi keadaan darurat, Safety of Life at Sea (SOLAS) 1974 telah mengatur akan kewajiban kapal untuk melengkapi dengan ketersedian alat-alat keselamatan di atas kapal. Menurut aturan Safety of Life at Sea (SOLAS) 1974, Chapter 3 (Life-Saving Appliances and Arragements) alat-alat keselamatan yang harus ada di atas kapal yaitu lifeboat, liferaft, lifebuoy, lifejacket, immersion suit dan alat keselamatan lainnya.

Alat keselamatan di kapal sangat penting bagi anak buah kapal maupun penumpang yang menggunakan jasa angkutan laut sebagai alat pengangkutan barang maupun penumpang. Seiring dengan kemajuan teknologi khususnya pada dunia perkapalan mengakibatkan perubahan yang cukup banyak pada perlengkapan atau peralatan kapal salah satunya pada sekoci penolong.

Sekoci penolong adalah salah satu alat keselamatan yang ada di atas kapal, alat penolong ini berupa perahu yang pada umumnya mempunyai motor penggerak dan berkapasitas angkut lebih banyak bila di bandingkan dengan alat penolong lainnya, yang berfungsi untuk meninggalkan kapal pada saat kapal sedang dalam kondisi darurat dan tidak memungkinkan untuk bertahan di atas kapal.

Sekoci penolong tidak lagi terbuat dari kayu atau logam yang cukup berat dan memerlukan perawatan yang khusus, tetapi pada zaman sekarang ini sekoci penolong terbuat dari bahan-bahan sintetis seperti *fiberglass* atau bahan lainnya yang cukup kuat, ringan dan tahan terhadap cuaca. Sekoci penolong memerlukan perawatan yang cukup dan sesuai dengan prosedur perawatan yang telah ditetapkan.

Suatu kenyataan di atas kapal dimana kegagalan dalam menanggulangi suatu kecelakaan di atas kapal disebabkan karena kondisi dari alat keselamatan itu sendiri khususnya sekoci penolong yang kurang terawat sehingga tidak dapat digunakan pada saat digunakan latihan keadaan darurat dan pada saat situasi keadaan darurat.

Berdasarkan uraian dari latar belakang di atas maka peneliti terdorong untuk mengambil judul penelitian yaitu: "Optimalisasi perawatan sekoci penolong di MT. Sungai Gerong ".

1.2 Perumusan Masalah.

Berdasarkan latar belakang yang diuraikan di atas, maka peneliti mengindentifikasi pokok-pokok permasalahan yang dapat dirumuskan sebagai berikut:

- 1. Bagaimana pelaksanaan perawatan sekoci penolong di MT. Sungai Gerong?
- 2. Kendala-kendala apakah yang dijumpai dalam pelaksanaan perawatan sekoci penolong?
- 3. Bagaimana upaya yang dilakukan untuk mengatasi kendala-kendala dalam pelaksanaan perawatan sekoci penolong?

1.3 Tujuan Penelitian.

Dari judul penelitian yang diambil dari masalah-masalah yang terjadi di kapal MT. Sungai Gerong, maka tujuan dari penelitian yang akan dilakukan adalah sebagai berikut:

1.3.1 Untuk mengetahui bagaimana perawatan sekoci penolong di MT. Sungai Gerong.

- 1.3.2 Untuk mengetahui kendala-kendala apakah yang dijumpai dalam pelaksanaan perawatan sekoci penolong.
- 1.3.3 Untuk mengetahui bagaimana upaya untuk mengatasi kendala-kendala dalam pelaksanaan perawatan sekoci penolong.

1.4 Manfaat Penelitian.

Diharapkan dari hasil penelitian mengenai *Optimalisasi Perawatan Sekoci Penolong di MT. Sungai Gerong* dalam skripsi ini diperoleh manfaat sebagai berikut:

1.4.1 Manfaat Teoretis

Manfaat dalam penelitian ini adalah untuk menjadi referensi pembaca, memperluas serta memperdalam pengetahuan tentang cara perawatan terhadap sekoci yang optimal untuk menunjang keselamatan jiwa selama dalam pelayaran.

1.4.2 Manfaat Praktis.

Agar penelitian yang dilakukan oleh peneliti dapat menjadi referensi kepada pembaca dan para mualim bagaimana melakukan perawatan terhadap sekoci penolong dengan baik dan benar sesuai dengan prosedur dan peraturan yang ditetapkan sesuia dengan ketentuan *Safety of Life at Sea* (SOLAS) 1974, sehingga sekoci dapat di gunakan pada saat latihan keadaan darurat dan pada saat mengalami situasi darurat.

1.5 Pembatasan Masalah.

Dilihat dari perumusan masalah di atas, maka peneliti mencoba membatasi masalah yang akan di bahas agar lebih terarah dalam pembahasannya, yaitu: 1.5.1 Penelitian ini fokus pada perawatan sekoci penolong di MT. Sungai Gerong.

1.6 Sistematika Penulisan.

Untuk dapat memahami dan mendapatkan pandangan yang lebih jelas mengenai pokok pembahasan dan permasalahan yang dihadapi, peneliti membuat sistematika penulisan yang dijabarkan sebagai berikut:

BAB I. PENDAHULUAN

Dalam bab ini peneliti menguraikan hal-hal yang berkaitan dengan latar belakang, perumusan masalah, tujuan penelitian, manfaat penelitian, dan sistematika penulisan. Latar belakang berisi tentang kondisi kondisi nyata dan uraian pokok-pokok pikiran yang menjadi alasan pemilihan judul. Perumusan masalah merupakan uraian tentang masalah yang akan diteliti dan bersifat faktual (bukan fiktif). Tujuan penelitian adalah tujuan spesifik yang akan dicapai melalui kegiatan penelitian yang dilakukan. Manfaat penelitian berisi uraian tentang manfaat yang diperoleh dari hasil penelitian. Sistematika penulisan berisi susunan bagian penelitian, dimana bagian yang satu dengan bagian yang lain saling berkaitan.

BAB II. LANDASAN TEORETIS

Dalam bab ini menjelaskan mengenai tinjauan pustaka yang berisikan teori-teori atau pemikiran-pemikiran yang melandasi judul penelitian tentang " Optimalisasi perawatan sekoci penolong di MT. Sungai Gerong" yang disusun sedemikian rupa sehingga merupakan

satu kesatuan utuh yang dijadikan landasan penyusunan kerangka pemikiran, dan definisi operasional tentang variabel atau istilah lain dalam penelitian yang di anggap penting.

BAB III. METODE PENELITIAN

Pada bab ini terdapat waktu dan tempat penelitian, data yang diperlukan, metode pengumpulan data dan teknik analisis data. Waktu dan tempat penelitian menerangkan kapan dan di mana penelitian dilakukan. Dalam hal ini tentang "Optimalisasi perawatan sekoci penolong di MT. Sungai Gerong". Data yang diperlukan merupakan cara yang dipergunakan untuk mengumpulkan data yang dibutuhkan. Metode pengumpulan data adalah prosedur yang sistematis dan standar untuk memperoleh data yang diperlukan. Teknik analisis data berisi mengenai alat dan cara analisis data yang digunakan, pemilihan alat dan cara analisis harus konsisten dengan tujuan penelitian.

BAB IV. HASIL PENE<mark>LITIAN DAN PEMB</mark>AHASAN

Dalam bab ini akan kemukakan tentang deskriptif data dilapangan, analisis penelitian masalah yang ada, alternatif pemecahan masalah dan evaluasi pemecahan masalah guna memberikan solusi atas masalah yang dihadapi dalam pelaksanaan perawatan sekoci penolong. Bab ini menjelaskan mengenai uraian hasil penelitian dan pemecahan masalah guna memberikan pengetahuan tentang bagaimana perawatan sekoci penolong sesuai dengan aturan dan tata cara yang benar.

BAB V. PENUTUP

Dalam bab ini akan dikemukakan kesimpulan dan saran saran yang bermanfaat bagi sistem perawatan dan pengoperasian sekoci diatas kapal guna mencegah atau memperlambat kerusakan pada sekoci.

DAFTAR PUSTAKA

LAMPIRAN

DAFTAR RIWAYAT HIDUP



BAB II LANDASAN TEORETIS

2.1 Tinjauan Pustaka

2.1.1 Optimalisasi

Menurut Rao (2009:1), mengemukakan bahwa optimalisasi adalah tindakan memperoleh hasil terbaik dalam keadaan tertentu. Tujuan akhir dari semua keputusan tersebut adalah untuk meminimalkan upaya yang diperlukan atau untuk memaksimalkan manfaat yang diinginkan.

Menurut Hudzaifah (2015:39), optimalisasi adalah ukuran yang menyebabkan tercapainya tujuan. Secara umum optimalisasi adalah pencarian nilai terbaik yang tersedia dari beberapa fungsi yang diberikan pada suatu konteks.

Berdasarkan definisi diatas yang dimaksud dengan optimalisasi dalam penelitian ini adalah sebuah proses, cara dan perbuatan untuk mencari solusi terbaik dalam beberapa masalah, dimana yang terbaik sesuai dengan kriteria tertentu. Dalam penelitian ini, topik yang diangkat adalah optimalisasi perawatan sekoci penolong di MT. Sungai Gerong, sehingga yang dioptimalkan adalah pelaksanaan dalam perawatan sekoci penolong.

2.1.2 Pengertian perawatan

Menurut Stephens (2010:3), mengemukakan bahwa perawatan dapat di definisikan sebagai semua kegiatan yang diperlukan untuk menjaga sistem dan semua komponenya dalam urutan kerja. Tujuan dari setiap program pemeliharaan adalah untuk mempertahankan kemampuan sistem dengan mengendalikan biaya.

Menurut Widiatmaka (2017:1), perawatan atau pemeliharaan (maintenance) adalah suatu aktifitas atau kegiatan yang perlu dilaksanakan terhadap seluruh obyek baik non-teknik meliputi manajemen dan sumber daya manusia agar dapat berfungsi dengan baik, maupun teknik meliputi suatu material atau benda yang bergerak ataupun benda yang tidak bergerak, sehingga material tersebut dapat dipakai dan berfungsi dengan baik serta selalu memenuhi persyaratan standar internasional.

Berdasarkan definisi diatas yang dimaksud dengan perawatan dalam penelitian ini adalah segala kegiatan yang dilakukan sebelum terjadi kerusakan atau untuk mencegah sejauh mungkin untuk menghindari resiko kerusakan selama periode tertentu. Dalam perawatan sekoci penolong, yang harus dilakukan perawatan adalah:

- 2.1.2.1 Sekoci penolong
- 2.1.2.2 Davit (dewi-dewi) sekoci penolong

2.1.2.3 Peralatan sekoci penolong

Perwira yang bertanggung jawab dalam perawatan sekoci penolong melaksanakan perawatan sekoci penolong sesuai dengan prosedur dalam pelaksanaan perawatan yang diatur dalam *Safety of Live at Sea* (SOLAS) 1974 dan *Plan Maintenance System* (PMS) yang ada diatas kapal.

Perawatan sekoci penolong dilaksanakan setiap:

- 2.1.2.1 Setiap minggu
- 2.1.2.2 Setiap bulan

- 2.1.2.3 Setiap tiga bulan
- 2.1.2.4 Setiap satu tahun

Peralatan yang harus ada di dalam sekoci penolong adalah:

- 2.1.2.1 *Rowlock* (sangkutan di tepi perahu)
- 2.1.2.2 *Bilge Pump* (pompa buang)
- 2.1.2.3 *Search Light* (senter)
- 2.1.2.4 *Compass* (kompas)
- 2.1.2.5 Fire Extinguisher (pemadam api)
- 2.1.2.6 Socket for Power Source (soket sumber listrik)
- 2.1.2.7 Bucket (ember)
- 2.1.2.8 Survival Manual (manual untuk bertahan hidup)
- 2.1.2.9 Sea Anchor (jangkar laut)
- 2.1.2.10 Painter Line (tali painter)
- 2.1.2.11 Hatchet (kapak)
- 2.1.2.12 Fresh water (air tawar)
- 2.1.2.13 Dipper (gayung)
- 2.1.2.14 *Food-Ration* (makanan)
- 2.1.2.15 Rocket Parachute Flare
- 2.1.2.16 *Hand Flare*
- 2.1.2.17 Bouyant Smoke Signal
- 2.1.2.18 Waterproof Electric Torch (senter anti air)
- 2.1.2.19 *Daylight Signalling Mirror* (cermin sinyal siang hari)
- 2.1.2.20 *Instruction for Lifesaving Signals* (instruksi sinyal keselamatan)

- 2.1.2.21 Signal Whistle (peluit)
- 2.1.2.22 First Aid Kit (pertolongan pertama)
- 2.1.2.23 Anti Sea Sickness Medicine (obat anti mabuk laut)
- 2.1.2.24 *Jack Knife* (kapak)
- 2.1.2.25 *Tin Opener* (pisau pembuka kaleng)
- 2.1.2.26 Fishing Tackle (alat memancing)
- 2.1.2.27 Engine Tools & Spare Part (alat mesin dan suku cadang)
- 2.1.2.28 Radar Reflector
- 2.1.2.29 Bouyant Oar (dayung apung)
- 2.1.2.30 Thermal Protective Aids (alat pelindung dingin)
- 2.1.2.31 Boarding Ladder (tangga naik)
- 2.1.2.32 Rain Collector
- 2.1.2.33 FPD (fall preventive device) (alat pencegah sekoci jatuh)
- 2.1.2.34 Spare Battery & Spare Bulb (baterai cadangan dan bolam cadangan)

Plan Maintenance System (PMS) sangat penting untuk melakukan proses perawatan. Secara umum planned maintenance system atau yang biasa disebut sebagai pemeliharaan secara terencana digolongkan atas dua, yaitu Preventive Maintenance dan Predictive Maintenance.

Kedua jenis pemeliharaan tersebut dilakukan secara terencana. Namun demikian keduanya mengacu pada dua faktor yang berbeda dalam pelaksanaannya, dimana untuk *preventive maintenance* lebih didasarkan pada waktu atau biasa disebut dengan *Time Based Maintenance* (TBM),

sedangkan *predictive maintenance* lebih didasarkan oleh kondisi peralatan atau mesin-mesin yang dijalankan atau biasa disebut dengan *Conditional Based Maintenance* (CBM). Pembahasan detail kedua jenis golongan ini sebagai berikut:

2.1.2.1 Preventive Maintenance

Kegiatan yang dilakukan dalam pemeliharaan preventif adalah rangkaian aktifitas yang bersifat pemeriksaan atau inspeksi yang dilakukan secara berkala dengan tujuan mencegah agar peralatan atau mesin yang dimiliki tidak mengalami kegagalan fungsi atau kerusakan yang mengakibatkan adanya gangguan terhadap proses operasional suatu kegiatan perawatan.

Preventive maintenance adalah bagaimana menyusun suatu rencana kegiatan yang akan menjadi acuan selama periode tertentu. Semua kegiatan akan didasarkan pada rencana ini yang terdiri dari rencana jangka panjang dan rencana jangka pendek. Rencana jangka panjang berupa program tahunan dan rencana jangka pendek berupa program mingguan. Program mingguan itu sendiri merupakan penjabaran dari program tahunan dengan penyesuaian pada kondisi pelaksanaan dilapangan.

Program tersebut harus mampu dijalankan secara konsisten namun tetap tidak boleh kaku dan memungkinkan untuk terjadinya penyesuaian-penyesuaian kecil. Ciri yang tampak pada metode *preventive maintenance* adalah pada perencanaan yang menjadi

acuan untuk suksesnya metode ini. Perencanaan itu sendiri merupakan salah satu tahap penerapan metode *preventive maintenance* Sekalipun kegiatan perawatan ini memiliki sifat fleksibel dalam waktu, namun penundaan kegiatan *preventive maintenance* sama artinya dengan mengundang *breakdown*.

Langkah-langkah yang harus ditempuh mengikuti prosedur sebagaimana dijelaskan sebagai berikut:

- 2.1.2.1 Kumpulkan semua informasi pemeliharaan
- 2.1.2.2 Buatlah standar pemeliharaan alat
- 2.1.2.3 Susunlah prosedur kerja pemeliharaan
- 2.1.2.4 Plot kedalam program tahunan

Pelaksanaan menjadi lebih mudah dikarenakan mengacu pada jadwal inspeksi untuk melihat gejala kerusakan yang ada. Inspeksi direncanakan sedemikian rupa sehingga tidak terlalu sedikit namun juga tidak berlebihan, serta dilakukan secara berkala seperti halnya membersihkan dan mengganti suku cadang.

2.1.2.2 Predictive Maintenance

Berbeda halnya dengan *preventive maintenance*, aktivitas pekerjaan pada *predictive maintenance* biasanya menggunakan alat-alat diagnostik untuk memonitor dan mendiagnosa kondisi mesin saat beroperasi. Kegiatan pemeliharaan dalam *predictive maintenance* yang mengacu pada *Conditional Based Maintenance* (CBM) lebih ditentukan oleh kondisi aktual alat dan bukan oleh jadwal pemeliharaan.

Predictive maintenance didefinisikan sebagai beberapa inspeksi yang dijalankan dengan menggunakan alat berteknologi tinggi yang digunakan untuk meramalkan kapan kemungkinan akan terjadinya kegagalan fungsi. Alat tersebut dapat memberikan manfaat dan memberikan kita lebih banyak waktu untuk terjun dan terlibat langsung sebelum terjadi kegagalan.

Predictive maintenance relatif baru digunakan secara umum, untuk mengetahui adanya suatu perubahan dari kondisi fisik yang merupakan alasan dasar untuk dilakukannya aktivitas perawatan yang logis untuk mempertimbangkan penggunaan alat monitoring, alat ukur terutama untuk menentukan perubahan-perubahan yang signifikan.

Perawatan adalah faktor tunggal yang terpenting untuk dapat menyesuaikan diri dengan masyarakat modern dan memperpanjang masa kemerosotan kapal, namun terdapat juga beberapa bidang di mana perawatan memainkan peranan yang sedemikian dominan seperti dalam pelayaran. Kita juga mengetahui bahwa perawatan itu mahal dan hal ini menjadi godaan terhadap setiap orang untuk menunda dalam melakukan perawatan. Adapun tujuan umum perawatan kapal adalah:

- 2.1.2.1 Kapal dapat dioperasikan secara teratur dan keselamatan terjamin.
- 2.1.2.2 Meningkatkan kemampuan kapal.

- 2.1.2.3 Sistem berjalan dengan biaya yang lebih efisien.
- 2.1.2.4 Menjamin kesinambungan perawatan, karena dapat diketahui yang sudah dan akan dikerjakan.
- 2.1.2.5 Dalam keadaan *crew* yang berbeda atau berganti, sistem tetap berjalan.
- 2.1.2.6 Sebagai umpan balik perawatan yang akan datang.
- 2.1.2.7 Untuk fasilitas informasi, kesiapan, sistem inventaris suku cadang.
- 2.1.2.8 Untuk menjamin bahwa alat keselamatan selalu dirawat dan dipelihara dengan baik oleh perwira yang bertanggung jawab sesuai dengan ketentuan peraturan yang berlaku, perusahaan harus membuat prosedur, yaitu dengan melakukan inspeksi terhadap alat-alat keselamatan tersebut yang dilasanakan dalam jangka waktu yang tepat.

2.1.3 Sekoci penolong (*lifeboat*)

Sekoci penolong adalah salah satu alat keselamatan yang ada diatas kapal yang digunakan untuk meninggalkan kapal karena tidak memungkinkan untuk bertahan diatas kapal. Sekoci penolong memiliki konstruksi yang lebih kuat dari alat penolong lainnya dan mempunyai kapasitas yang lebih banyak yang dapat mengangkut 30 orang tergantung ukuran dan jenis sekoci penolong. Sesuai bab III *Safety of Life at Sea*

(SOLAS) 1974 amandemen 2009, ada beberapa tipe sekoci penolong diatas kapal, yaitu:

- 2.1.3.1 Sekoci terbuka (open lifeboat).
- 2.1.3.2 Sekoci tertutup sebagian (partially enclosed lifeboat).
- 2.1.3.3 Sekoci tertutup sebagian secara otomatis (self righting partially enclosed lifeboat).
- 2.1.3.4 Sekoci tertutup (totaly enclosed lifeboat).
- 2.1.3.5 Sekoci dengan sestem udara otomatis (self contained air support system).
- 2.1.3.6 Sekoci dengan pelindung tahan api (fire protected).

Adapun jenis-jenis sekoci penolong yang utama, diantaranya:

2.1.3.1 Sekoci Tertutup (Fully enclosed lifeboat)

Digunakan pada kebanyakan kapal *tanker* dan kontainer. Sekoci tertutup adalah sekoci paling populer yang digunakan pada kapal, karena sekoci tertutup dapat melindungi kru dari masuknya air laut, angin kencang dan cuaca buruk. Selain itu, sekoci pada jenis ini bisa tegak kembali atau kembali ke keadaan semula jika terguling oleh gelombang.

2.1.3.2 Sekoci Terbuka (Semi enclosed life boat atau open life boat)

Seperti namanya, sekoci terbuka tidak memiliki atap dan biasanya didorong oleh tenaga manual dengan menggunakan tangan didorong. Kompresi motor bakar juga dapat diberikan untuk tujuan propulsi. Namun, sekoci terbuka menjadi usang

sekarang karena norma-norma keselamatan yang ketat, tetapi masih kadang ditemukan di kapal tua. Sekoci terbuka tidak banyak membantu dalam hujan atau cuaca buruk dan kemungkinan masuknya air kedalam sekoci lebih besar dari pada sekoci tertutup.

2.1.3.3 Sekoci Luncur (free-fall lifeboat)

Sekoci jatuh bebas adalah sama dengan sebuah sekoci tertutup namun proses peluncuran sama sekali berbeda. Mereka aerodinamis di alam dan dengan demikian perahu bisa menembus air tanpa merusak badan sekoci saat diluncurkan dari kapal. Sekoci ini terletak di bagian belakang kapal, yang menyediakan area yang jelas maksimum untuk jatuh bebas. Jenis ini biasanya hanya disediakan satu saja dikapal.

2.2 Definisi Operasional

Beberapa pengertian dalam skripsi ini akan diuraikan untuk pembahasan selanjutnya yang didalamnya memberikan pembekalan-pembekalan dalam meningkatkan peranan alat keselamatan untuk menunjang pengoperasian kapal.


- 2.2.1 Perawatan dalah mengendalikan atau memperlambat tingkat kemerosotan kapal.
- 2.2.2 Safety Officer adalah perwira diatas kapal yang bertanggung jawab untuk menyelidiki kecelakaan dan mengadakan inspeksi secara mendadak.

- 2.2.3 *Safety Plan* adalah sebuah bagian yang menunjukkan letak semua alat pemadam kebakaran.
- 2.2.4 Kapal adalah meliputi setiap jenis kendaraan air termasuk kendaraan dan pesawat terbang laut bukan *displacement* atau mampu untuk digunakan sebagai sarana pengangkut air.
- 2.2.5 Alat-alat keselamatan adalah alat-alat penolong diatas kapal yang dengan persyaratan kapal (Safety of Life at Sea) SOLAS 1974 yang dapat digunakan pada waktu terjadi kecelakaan kapal.
- 2.2.6 (Safety of Life at Sea) SOLAS 1974 atau keselamatan jiwa di laut adalah konvensi internasional tentang keselamatan jiwa di laut yang menghasilkan ketentuan dan peraturan yang di gunakan sebagai acuan bagi kapal-kapal atau perusahaan pelayaran di dalam menjaga dan melindungi jiwa para pelaut yang bekerja di kapal.
- 2.2.7 (Standard Training Certificate of Watchkeeping) STCW atau sertifikat standar pelatihan tugas jaga adalah sertifikat standar yang dimiliki oleh setiap crew kapal mengenai tugas jaga di laut dan pelabuhan.
- 2.2.8 Sekoci adalah salah satu alat penolong diatas kapal, yang berfungsi untuk meninggalkan kapal pada saat kapal sedang dalam kondisi darurat dan tidak mungkin lagi bertahan di atas kapal.
- 2.2.9 *Realishing Hook* adalah alat yang berfungsi untuk melepaskan ganco di sekoci dengan *wire*.
- 2.2.10 *Embarkation ladder* adalah tangga tali yang terdiri dari dua tali berukuran 3", pada setiap jarak 30cm dipasang kayu bulat, diatas dan

- dibawah kayu bulat tersebut diikat mati untuk menjaga agar kayu tersebut tidak turun pada saat diinjak.
- 2.2.11 *Boat Hook* adalah bagian dari peralatan berperahu. Penggunaannya yang paling umum adalah sebagai alat bantu *docking* dan *undocking*.
- 2.2.12 *Boat Davit* adalah alat untuk menyimpan, menaikkan, dan menurunkan sekoci penolong.
- 2.2.13 *Plan Maintenance System* (PMS) adalah pemeliharaan berencana atau pekerjaan perawatan yang harus di rencanakan sejauh mungkin dengan mempertimbangkan keterbatasan pengoperasian (pola perdagangan, ketersediaan suku cadang, awak kapal).

2.3 Kerangka Berpikir

Agar penulisan skripsi ini menjadi jelas dan dapat bermanfaat maka peneliti memberikan uraian kerangka pemikiran yang diambil untuk memudahkan pemahaman mangenai optimalsasi perawatan sekoci penolong di MT. Sungai Gerong. Berdasarkan data-data yang diperoleh, bahwa perawatan sekoci di atas kapal tersebut sangat minim sekali dan kurang maksimal, hal ini terbukti pada saat sekoci penolong difungsikan ternyata tidak bekerja dengan sempurna. Peneliti menggunakan kerangka pemikiran secara sistematis berupa diagram.



Gambar 2.1 Kerangka pikir

BAB V

PENUTUP

5.1 Simpulan

Berdasarkan pada hasil penelitian di lapangan serta dari hasil uraian pembahasan mengenai " Optimalisasi perawatan sekoci penolong di MT. Sungai Gerong ", maka peneliti dapat menarik simpulan sebagai berikut:

4.3.4 Pelaksanaan perawatan sekoci penolong agar maksimal di MT. Sungai Gerong

Sekoci penolong harus dilakukan perawatan sesuai dengan ketentuan dalam SOLAS 1974 dan PMS (*Plan Maintenance System*) yang ada diatas kapal untuk mendapatkan hasil yang maksimal dalam perawatan sekoci penolong. Dengan adanya sistem perawatan terencana atau *Plan Maintenance System* (PMS) seperti yang diharuskan dalam sistem manajemen keselamatan, maka akan mempermudah dalam pelaksanaan perawatan sekoci penolong.

4.3.5 Kendala-kendala yang dijumpai dalam pelaksanaan perawatan sekoci penolong

Dalam pelaksanaan perawatan sekoci penolong, terdapat kendalakendala yang menyebabkan perawatan sekoci penolong kurang maksimal adalah:

 Kapal MT. Sungai Gerong sering berlayar short voyage atau alur pelayaran pendek yang menyebabkan sedikitnya waktu dalam pelaksanaan perawatan sekoci penolong.

- 2. Perwira *Deck* dan Perwira Mesin kurang memahami sepenuhnya tentang cara perawatan sekoci penolong.
- 3. Tidak adanya *spare part* atau suku cadang.
- **4.3.6** Upaya untuk mengatasi kendala-kendala dalam pelaksanaan perawatan sekoci penolong

Untuk mengatasi kendala-kendala dalam pelaksanaan perawatan sekoci penolong adalah dengan cara:

- 1. Dengan cara membagi tugas dalam melaksanakan perawatan sekoci penolong antara Mualim 3 dan Mualim 4 dapat membuat pelaksanaan perawatan lebih cepat selesai dan waktu perawatan yang dibutuhkan menjadi lebih sedikit.
- 2. Melakukan pelatihan kepada *crew* terkait perawatan sekoci penolong yang baik dan benar sesuai dengan prosedur perawatan sesuai dengan ketentuan SOLAS 1974 dan PMS (*Plan Maintenance System*) yang ada diatas kapal.
- Melakukan permintaan suku cadang kepada perusahaan agar dalam pelaksanaan sekoci penolong tidak mengalami hambatan.

5.2 Saran

Sesuai dengan permasalahan yang telah dibahas dalam skripsi ini peneliti ingin memberikan sedikit saran yang mungkin dapat bermanfaat untuk mengatasi permasalahan tersebut. Adapun saran yang peneliti sampaikan adalah sebagai berikut:

- 1. Agar perawatan sekoci penolong bisa maksimal, sebaiknya perawatan sekoci penolong dilaksanakan sesuai dengan ketentuan SOLAS 1974 dan PMS (*Plan Maintenance System*) dari perusahaan, serta *adanya manual book* untuk perawatan sekoci penolong. Perawatan dilakukan secara rutin setiap minggu, setiap bulan sesuai dengan rencana perawatan yang telah ditetapkan untuk melakukan pengecekan kelengkapan dan keadaan sekoci penolong.
- 2. Dalam mengatasi kendala-kendala pelaksanaan perawatan sekoci penolong di MT. Sungai Gerong, sebaiknya perwira yang bertanggungjawab dalam perawatan sekoci penolong membagi tugas dalam perawatan sekoci penolong. Dengan cara membagi tugas dapat membuat pelaksanaan perawatan sekoci penolong lebih cepat selesai dan waktu perawatan yang dibutuhkan lebih sedikit, sehingga perawatan sekoci penolong bisa maksimal.
- 3. Upaya untk mengatasi kendala-kendala dalam pelaksanaan perawatan sekoci penolong, sebaiknya perusahaan menyediakan suku cadang atau alat perbaikan segera mungkin untuk perawatan sekoci penolong sebelum terjadi hal yang tidak diinginkan, memberikan arahan kepada *crew* kapal akan pentingnya *safety meeting* untuk keselamatan berlayar. Pada saat *safety meeting* kita bisa berdiskusi tentang masalah apa yang di hadapai dalam pelaksanaan perawatan, sehingga permasalahan tersebut bisa diatasi bersama. Perwira senior bertanggung jawab memastikan keadaan sekoci penolong dalam kondisi baik dan siap untuk digunakan.

DAFTAR PUSTAKA

- Fitrah, Muh. dan Luthfiyah, 2017, Metodologi penelitian: Penelitian Kualitatif, Tindakan Kelas & Studi Kasus, CV Jejak, Sukabumi Jawa Barat.
- Hudzaifah, 2015, Jurnal Universitas Pembangunan Jaya #2 Volume 2 dalam Judul Analisis Optimalisasi Persediaan dengan menggunakan Metode Economic Order Quantity.
- International Maritime Organization, 2014, *International Safety Management Code*, International Maritime Organization, London.
- International Maritime Organization, 2014, Safety Of Life At Sea Consolidated Edition 2014, International Maritime Organization, London.
- International Maritime Organization, 2017, *Life-Saving Appliances 2017 Edition*, International Maritime Organization, London.
- International Maritime Organization, 2017, STCW Convention and STCW Code 2017 Edition, International Maritime Organization, London.
- Juliandi, Azuar, Irfan, dan Manurung, Saprinal, 2014, Metodologi Penelitian Bisnis Konsep dan Aplikasi, Umsu Press, Medan.
- Moleong, Lexy J. 2016, Metodologi Penelitian Kualitatif, PT. Remaja Rosdakarya, Bandung.
- Rao, Singiresu S. 2009, Engineering Optimization Theory and Practice, John Wiley & Sons, Inc. Canada.
- Stephens, Matthew P. 2010, Productivity and Reliability-Based Maintenance Management, Library of Congress Cataloging in Publication Data, United States of America.
- Wastana, Fathoni, Aziz, dan Minarsih, Maria M. 2016, Journal of Management Vol.02 No.02 dalam Judul Studi Komparatif Biaya Perawatan, Biaya Perbaikan dan Biaya Ban dalam Penerapan Active Maintenance Terhadap Profitabilitas PT. Serasi Logistics Indonesia Surabaya.
- Widiatmaka, F. Pambudi, 2018, Manajemen Perawatan dan Perbaikan Kapal, Politeknik Ilmu Pelayaran Semarang, Semarang.
- Yaumi, Muhammad dan Damopolii, Muljono, 2014, Action Research: Teori, Model & Aplikasi, PT. Fajar Interpratama Mandiri, Jakarta.
- Yusuf, Muri, 2014, Metode penelitian: Kuantitatif, Kualitatif, dan Penelitian Gabungan, PT. Fajar Interpratama Mandiri, Jakarta.

SHIP'S PARTICULARS

HARE.	ISONEM SERVICE	
CALLSESH	P030	
FSAG.	PSCHESIA	
PRINCE OF FIGURETRY	TAKWARIA.	
OFFICIAL HUMBER	William Strain Strains	
PUREATOR SOURCE AND SERVICE AN	755070000	
CLASS SOCIETY	\$300 × 300	
CLASS NOTICION	+5A1Tanks	


REELLAND,	27.AVA367.2616
AUTOCHED	06.3407.2011
DELATRE	36 DECCH#65 26+1
345,440	DEMAGRETIC SHPEADAG
	- CHINA COME

SATELLITE COMMUNICATION				
	TRUF	IVM-C		
CAME.	Personne	PRODESTREES.		
HOLE .	CONTRACTOR CONTRACTOR			
TAK.	14 1 2 1 2	Subbound Co		
TELEX	168	4500000mit		
MIS	10.900e073			
CHANGE	NA			
CELFLAG	. 36	ACRES A		

OWNERS OF PERFAMINA PERSONAL SHAPPING OCHARTEMENT ALVOID BUDWING NO SEAT TO PRIOR, ARAMTA 4000 NO ONDER TO, HISTORY PARTY AND ARAMTA AND ARAM

CHRISTORICH FIRMANA PIRTIERO SAPRIO DIPARTIMEN J. TIE ELANGO 60 DIA TEPROX, ANATA 1000 RECORD TE, ACCIDENT FAX-CUTION

PRINCIPAL DIMENSIONS			
LOA	196.00 M		
180	175.000		
EREAUTH (Extern)	16.00 M		
DSPTH (reside)	15,90 M		
HEROHT SYMMOUTH	44,8F N		
RECOUNT FROM - BOW	150.24 M		
HERE FRONT STEEM	24.36 M		
WHEN SEFERIT - HE CLD	563.50 M		



FEMANGE	76000	9162
RET.	7.293.7	194
G41005	34,907 T	HA
SECURITARISAN FOR REF.	帯が設す	TWA -

LOAD LINE BY DRIANTON	PRESIDENCE	DSAFT	/ DWT
TROPEAL	6726.9	SAMM	No. S.A.
SURPLES	5,5% M	0.990	20,785,663
WHILE	7.132 M.	KINKII	- JID JUDE 51 G
ACRESSED BY THE CORD.	No.	TARREST M.	17.60 FB
DWT WITH SUT CHAT	2/	100	-mm
PWA.	1	(WENNY	E
TPC @ Summer clust	V . /	/ 48.5 (CC)	24/1

	1140234	TANK CAPACITE	a (ann)	TWO IS NOT	ACTION OF THE
	CARDOTA	MAKE SHE LT		BLST T	POR (1909 THE
GROUPI		SLOP P45	1945.4	F.P.Ta.	1887
J1 F/8+4 F/8)	17949.6	11		1.15%	2899 (27)
Tollean 3				196	1110,368
EPENDER.	16888 1		400	1.05	1896.1
DATION		F.M Tanks	100%	4.9%	
BUTTER	TRANS.	· PM Sawiff	134:	1.7/5	2000.139
	Ta.	FIRE REPORTS	134	1.65	3000 (67)
4	1,00			APT.	900.ATT
	74	7			
TOTAL	612NEA	7, 1021.EL	288	TOTAL	18280.7
Digital Property		OPHER DET	ALS	-	
H Inch Policy	D.1887	Labor conche	manu	AL DESIGNATED I	BEADAR

WACHER IT.	PROPERTON (REDORN)
WASHINGS.	東下の文章でも1957年まりを表現は第二
RCH.	DARK KINGS SHE THE
HC.PI	MEXICAL STATE OF THE STATE OF T
HAX CHITICAL BANKE	Soro ikan
AUX BOLER (HIRE)	Thornes on leasest
GENERATOR (1) sub-	14 的对象 IL 7C的公民/WHI
EMERD G IT	- A COMPANY IN TAKING SING.
MONETTER	STATE OF THE PARTY OF PERSON
RIDGER	The Laborat
STEERING DEAD.	A THE R. LEWIS CO. LANSING.
FW GENERATOR CHP	THE STREET

CONTRACT TARREST	MYCHEL M	NOLASS ROPES I EMERGENCY TOWNS
eor (mai Plubino alli,	W.SSI PRO	MEL PARTICISANS
PET S P LATE OF THE ST	WHEN REED E	2 Personal week 12 ft fol Lase Pull
FC1 260 39 8/6	nmp nester too.	TANK
TO (69/1 / 1100 /	WHATEHES BOT	gr Emphasic which IZT ht Last Put
POSSETT PRINT/	WHEN LAND A	/ First programme 7.6
7074L B11U	FFR'WSC /1\/	1 25 per x 2 x 86 mb
19 F F F K 1 19692	ANDHOR: JULY	TEA STREET AND FUT IT YOUR DRIETS WAR.
D071 M01282	1000 /0/	PART LEADS STRONG POWE 280 YORKS
17 300 V	V-100%	100
ph nV aastwo	ZUWNG	, FARLLIAD ACHAIN RECEPTIR 200 TONIS
FOTAL 20131	H Cham	1

TIME PLANTS	MO.	GAPACITY	18.60	-AU-U
CARGO COL PIPS	.3	still depty	425 m	A 15 E21
CARROLD ROLLS TOPI.	1.	200 cheVM	11784	7900
STREENG PUREP	1.	150 cheyler	125 m	794
PALLART PUBLISH	7	950 carrys	29.m	71168
TK CLEANANCE &	1	100 carryler	14519	7.5154

Н	FACEPALL
П	SATERNA, LARGON,
ч	FROM GRAVE (Street
П	1 set x E.O tex-7, HE M
	70 19000

BUNCHOLD ARRANDIMENT HIS INTO / STORE				
Company of pargo mandad to cargo mandad.	2008 (189)			
Deministry of corporate for the security of	2000 run			
Charter of investigate to empty risk	4429 min			
Distance of spill thay grating to contra of manifold	900 mm			
Critaria d' svar dece la cente d' savidad	2100 rsw			
Ordanic of matridest fortiginal rail	1963 nm			
Distance of top of radio content/ evanions	737.698			
Distance of wanded to ship side	4000 men			
Distance of maintant have next	William .			

10 / WAPOR EMISSION / VERTING				
G BLOWER CAPACITY (Free)	255000 surviv			
PRV WALSE PROVINCE SETTING	- 200 mm/mg			
PV BREAKSTING AND SETTING	1400 mm/ug			

Mail	60 G	MC 180	96.
SM.	34.1	Sec. 7	30 m
M	PO.	W 11	E 10
6	aller I	-	Elm .

FIRST FIGHTING STETEM				
EIGH.	COLFDAN WWATER WEE	-		
PUNP ROOM	CCC & FORM			
CARGO DICARDA	PDAMAD WATER	- 1		



Form No: SHE-11

IMO Crew List

			K Arrival	Ospatus	Page No.	
1.	Name of Ship	100	2	Port of Arrival	3. Date of Activ	at .
***	MT. SUNGAI GERON	G	-	KALBUT	26.09.	2018
	Nationally of Ship	NDONESIA	S. LastPort	CLACAP	6. Nature and No of Identity document(Se arnan's Book or Passport)	Expiry date
7.No.	& Fierrity name, Given names	9. Frank or niting	15 Nationally	11 Date and piece Others	Seature's Scot.	
4	AGE, BUSIONO	MASTER	NEONEBIA	BRESSES / 29.05 1973	£ 113078	16:01 2000
2	ALBERTO TASIABE	Ot Off	NDONESIA	FALU / 18.10.1999	E 048755	18.01.202
3	BUDI-HERMANAN	2 ^{et} OFF	INDONESIA.	WATAMPONE / 11.01.1989	E 303356	28 14 200
	ARYAMAN	Spe Date	ANDDNESSA,	MENDAL / 01:08:1992	D 025507	24.11.201
5	BEHROSSY VINSENSIUS WILTED SHITE	1 STEN	KINDLINE	BATTAN I STREET THE	0.062672	20 06 201
0	ARUANTO	ACKENS	MOGNESIA	PATITION DE LINES	D 061496 -	36.02.200
+	MUHAMAS KUSYUFRS	Z ^E ING	MOONENA	KENDAL I TYOT MEAN	0.012878	06.10.200
A	RUDI BUDHARTO Q	PERMAND.	HOOKESK	PRIACHE 120 REVINE	C 014Q56	08 15 200
*	MARIO VUGO ANGGA	AMBRED	PECERTA	SHIMPANG (10 P) 154	E 098858	18 07 201
10	BANGLAN BANGTON	March /	THE ROWSE	PRINCIPAL TO GATING	D-041662	23 91 202
11	MUHEIR	PERMIT	NOONESA	WATANGERS STATEMENT NO	A 036738	90 94 201
12	AGU6	- source	HOOKESIS	CLACAS INDE 1970	D 000296	37 03 202
13	HAPIDURA	AB AB	NADOLETA /	MANO / DE DE PRET	E 009035	12.07.201
14	SYAMSUDAY ACHIVACI SALESIAN	48	HOMESA	BANIEAN STATE THAT	F 134816	64 06 202
19	KURNANDAH	The same	RCEARGA.	CAMB HEROTOR	H (04345	16 01 202
16	ом мислоно ветию	(Sept)	MODES NO	OLEGOPE PAT NO PART	E 129188	29,11,201
17	SULAMAII LO	FITTER	- President	DUE 100 PHILIPPING 123 10 1070	E 102917	29.06.201
18	ANTHON SUHARIO	(Call	MOONESIA	TEGAL/TEGE TOWN	E 127961	83.11.201
15	ALUS GUGU PAPARANG	THER	MODESA	POSD/21/00 1009	E 166308	20.02.202
20	EKO FURWANTO	SULER	INCONESIA	PARTITION	E 130861	23 12 201
21	TALFIEHDAYAT	CH COOR	HEDONESIA	JANASTA) 15.04 1988	0.027946	28.11.201
=	HANNY HARCE LUMINTANG	MESSECY	MODNEBA	SONDER / 25 03 1977	D.019668	29/10/201
23	BAHTIANUL MUBARAK	D CADET	INDONESIA	GRESH / 05 10 1995	E 150068	06.06.202
24	HANDRYAN GANJAR NUGROHO	E. CADET	MODNESA	QR0800AN/17.11.1998	F 028687	88.07.202

12. Master / Authorised agent /Officer	Signature	Date 28.09.2018
The residence of the proportion of the property of the propert	, seg-see-	A STATE OF THE PARTY OF THE PAR

LAMPIRAN 3

DAFTAR RESPONDEN

NAMA	JABATAN	KETERANGAN	TANDA TANGAN
Capt. Agil	Master of MT. Sungai	Responden I	
Sugiono	Gerong		
Alberto Tasiabe	Chief Officer	Responden II	
	MT. Sungai Gerong		
Aryawan	Third Officer MT.	Responden III	
	Sungai Gerong		
Mario yugo	Fourth Engineer MT.	Responden IV	
	Sungai Gerong		

HASIL WAWANCARA

Hasil wawancara ini yang peneliti lakukan terhadap responden pada saat peneliti melaksanakan praktek laut di MT. Sungai Gerong, wawancara ini dilakukan untuk memperoleh informasi maupun bahan masukan bagi skripsi yang peneliti buat sehingga diperoleh data-data yang mendukung terhadap penelitian yang peneliti lakukan. Adapun wawancara yang peneliti lakukan terhadap responden adalah sebagai berikut:

Responden I (Nakhoda):

Hasil wawancara yang dilakukan peneliti dengan Nakhoda kapal MT. Sungai Gerong pada saat melakukan praktek laut adalah sebagai berikut:

Bagaimana pelaksanaan perawatan sekoci penolong di MT. Sungai Gerong?
 Jawab: Agar perawatan sekoci penolong bisa maksimal, perawatan sekoci penolong harus dilaksanakan sesuai dengan prosedur perawatan yang telah di tetapkan sesuai dengan SOLAS 1974 dan sesuai dengan perawatan dari perusahaan. Perawatan dilaksanakan agar sekoci

penolong selalu dala kondisi siap untuk digunakan dan tidak mengalami kendala pada saat digunakan latihan dan pada saat terjadi keadaan darurat.

2. Apakah kendala-kendala yang dijumpai dalam pelaksanaan perawatan sekoci penolong?

Jawab: Kendala yang sering terjadi pada saat pelaksanaan perawatan sekoci penolong adalah karena kapal MT. Sungai Gerong sering berlayar short voyage atau alur pelayaran pendek. Dalam melaksanakan perawatan sekoci penolong membutuhkan waktu yang cukup agar perawatan dapat dilaksanakan dengan optimal.

3. Bagaimana upaya untuk mengatasi kendala-kendala dalam pelaksanaan perawatan sekoci penolong?

Jawab: Upaya untuk mengatasi kendala yang terjadi dalam pelaksanaan perawatan yang diakibatkan karena alur pelayaran pendek atau short voyage adalah dengan cara membagi tugas dalam melaksanakan perawatan sekoci penolong antara Mualim 3 dan Mualim 4. Dalam pelaksanaan perawatan sekoci penolong Mualim 3 juga bisa meminta bantuan kepada Crew Deck apabila dalam perawatan sekoci penolong dalam keadaan urgent atau perawatan harus di laksanakan dengan segera. Dengan demikian perawatan sekoci penolong dapat berjalan dengan maksimal.

- 4. Bagaimanakah cara menanggulangi kurang terampilnya *crew* dalam pengoperasian sekoci?
 - Jawab: Dilakukan *safety meeting* atau *familiarization* kepada *crew* kapal tentang pentingnya penggunaan alat keselamatan sekoci dan melaksanakan latihan *drill* sesuai jadwal.
- 5. Apa sajakah yang harus diperhatikan pada saat latihan penurunan sekoci?

Jawab: Keadaan sekoci dan alat pendukungnya yang terdapat di dalam sekoci, sumber daya manusia dalam pengoperasian sekoci dan perhatikan keamanan pada saat penurunan sekoci.

Responden II (Mualim I):

Hasil wawancara yang dilakukan peneliti dengan Mualim I kapal MT. Sungai Gerong pada saat melakukán prala (praktek laut) adalah sebagai berikut:

- 1. Apa penyebab tidak dijalankannya PMS (Plan Maintenance System) di stas kapal?
 - Jawab: Sebenamya PMS (*Plan Maintenance System*) telah dijalankan meskipun hanya beberapa point saja, hal ini terjadi karena begitu banyak pekerjaan yang harus dilakukan dengan segera sehingga *Plan Maintenance System* sering diabaikan.
- 2. Apakah penggunaan sekoci penolong dalam latihan sudah maksimal?
 - Jawab: Belum, karena sering terjadi kemacetan ketika penurunan sekoci sehingga membutuhkan waktu yang lama, seharusnya perawatan dilakukan secara rutin sesuai aturan.

- Apakah perawatan yang dilakukan terhadap sekoci penolong sudah baik?
 Jawab: Belum, biasanya perawatan dilakukan hanya ketika akan diadakan vetting di atas kapal, agar lolos dari pengecekan.
- 4. Bagaimana pelaksanaan perawatan sekoci penolong di MT. Sungai Gerong?
 Jawab: Dalam melaksanakan perawatan sekoci penolong harus sesuai dengan
 PMS (Plan Maintenance System) yang ada diatas kapal agar
 perawatan sekoci penolong maksimal. PMS (Plan Maintenance
 System) sangat dibutuhkan dan sangat membantu untuk menciptakan
- 5. Apakah kendala-kendala yang dijumpai dalam pelaksanaan perawatan sekoci penolong?

perawatan yang efektif dan efisien, serta untuk menghindari proses

perawatan yang dapat membahayakan keselamatan para pekerja.

- Jawab: Kendala yang sering terjadi dalam pelaksanaan perawatan sekoci penolong adalah Perwira *Deck* dan Perwira Mesin kurang memahami sepenuhnya tentang cara perawatan sekoci penolong. Dalam melaksanakan perawatan sekoci penolong harus sesuai dengan rencana perawatan yang ada diatas kapal. Mualim 3 harus mempunyai jadwal kapan perawatan akan dilaksanakan agar perawatan sekoci penolong dapat dilaksanakan secara maksimal.
- 6. Bagaimana upaya untuk mengatasi kendala-kendala dalam pelaksanaan perawatan sekoci penolong?
 - Jawab: Upaya untuk mengatasi kendala yang terjadi dalam pelaksanaan perawatan yang diakibatkan karena Perwira *Deck* dan Perwira Mesin

kurang memahami sepenuhnya tentang cara perawatan sekoci penolong adalah dengan cara melakukan pelatihan kepada *crew* terkait perawatan sekoci penolong yang baik dan benar sesuai dengan prosedur perawatan, serta dilakukannya *safety meeting* yang membahas tentang pentingnya perawatan sekoci penolong sesuai dengan prosedur perawatan agar sekoci penolong selalu dalam kondisi siap untuk digunakan. Pada saat dilaksanakan *safety meeting* Mualim I menjelaskan tentang bagian-bagian mana pada sekoci penolong yang harus dilaksanakan perawatan sesuai dengan jadwal perencanaan perawatan.

7. Apa sajakah yang harus diperhatikan pada saat pelatihan penurunan sekoci?

Jawab: Prosedur penurunan sekoci harus dilakukan dengan sebaik-baiknya karena hal ini berhubungan dengan keselamatan jiwa awak kapal.

Keadaan sekoci harus diperhatikan dan alat pendukungnya harus digunakan dengan benar.

Responden III (Mualim 3):

1. Bagaimana pelaksanaan perawatan sekoci penolong di MT. Sungai Gerong?

Jawab: Perawatan sekoci penolong dilaksanakan sesuai dengan SOLAS 1974
dan PMS yang ada diatas kapal. Sebelum melaksanakan perawatan
sekoci penolong harus sudah mengerti dan paham tentang prosedur
dalam melaksanakan perawatan. Perawatan sekoci penolong
dilaksanakan sesuai dengan rencana perawatan yang ada diatas kapal.
Perawatan dilaksanakan setiap minggu, setiap bulan, dan setiap tahun.

2. Apakah kendala-kendala yang dijumpai dalam pelaksanaan perawatan sekoci penolong?

Jawab: Kendala yang sering terjadi dalam pelaksanaan perawatan adalah karena tidak adanya *spare part* atau suku cadang. Suku cadang sangat penting demi kelancaran dalam melaksanakan perawatan.

3. Bagaimana upaya untuk mengatasi kendala-kendala dalam pelaksanaan perawatan sekoci penolong?

Jawab: Upaya untuk mengatasi kendala yang terjadi dalam pelaksanaan perawatan yang diakibatkan karena tidak adanya *spare part* atau suku cadang adalah dengan cara melakukan permintaan kepada perusahaan. Semua peralatan yang tidak ada dikapal atau peralatan yang akan habis masa berlakunya di buatkan daftar barang-barang tersebut dijadikan satu daftar, setelah itu daftar tersebut dikirimkan ke kantor perusahaan agar barang yang kita butuhkan dikirim dari darat.

4. Apa sajakah yang menyebabkan sekoci tidak dapat diturunkan pada saat latihan?

Jawab: Tidak dijalankannya PMS (*Plan Maintenance System*) dengan baik dan benar dan kurangnya perawatan terhadap alat keselamatan sekoci, serta kurangnya pengetahuan *crew* kapal tentang pentingnya keterampilan menggunakan alat-alat keselamatan seperti sekoci dan kurang optimalnya pelaksanaan *drill*.

- 5. Bagaimana seharusnya tindakan perwira dalam pelaksanaan PMS (*Plan Maintenance System*) dan perawatan alat keselamatan sekoci?
 - Jawab: Sebelum melakukan perawatan terlebih dahulu seorang perwira membaca *Plan Maintenance Sytem* untuk menunjang perawatan sekoci dengan tepat dan benar. Dan juga untuk memastikan kondisi perlengkapan dalam keadaan *safety* dan layak laut dan dilaksanakan perawatan alat keselamatan sekoci yang rusak.
- 6. Apakah perawatan yang dilakukan terhadap sekoci penolong sudah baik?
 Jawab: Belum, biasanya perawatan dilakukan hanya ketika akan diadakan vetting di atas kapal.

Responden IV (Masinis 4):

- 1. Bagaimana pelaksanaan perawatan sekoci penolong di MT. Sungai Gerong?
 - Jawab: Pelaksanaan perawatan sekoci penolong harus sesuai dengan jadwal rencana perawatan sekoci penolong khususnya dalam pelaksanaan pengecekan dan pengetesan terhadap mesin sekoci penolong. Pada saat menghidupkan mesin sekoci pastikan mesin sekoci berjalan tidak kurang dari 3 menit.
- 2. Apakah kendala-kendala yang dijumpai dalam pelaksanaan perawatan sekoci penolong?
 - Jawab: Kendala yang sering terjadi dalam pelaksanaan perawatan adalah kurangnya waktu perawatan yang diakibatkan banyaknya pekerjaan di kamar mesin, sehingga pelaksanaan perawatan mesin sekoci penolong tidak sesuai dengan jadwal perawatan mesin sekoci penolong. Dalam


pelaksanaan perawatan mesin sekoci penolong semua yang berhubungan dalam proses menghidupkan mesin sekoci penolong harus diperiksa dan dicoba agar pada saat menghidupkan mesin sekoci bisa hidup dengan normal.

3. Bagaimana upaya untuk mengatasi kendala-kendala dalam pelaksanaan perawatan sekoci penolong?

Jawab: Upaya untuk mengatasi kendala yang terjadi dalam pelaksanaan perawatan mesin sekoci penolong yang diakibatkan karena banyaknya pekerjaan di kamar mesin adalah dengan cara menambah tenaga kerja dalam perawatan mesin sekoci penolong. Dalam pelaksanaan perawatan mesin sekoci penolong Masinis 4 bisa meminta bantuan kepada Oiler atau kepada kadet mesin agar dalam pelaksanaan perawatan sekoci penolong tidak membutuhkan waktu yang lama.

ALL INSTRUCTION LIFE SAVING	HULL NO.	CH-0901/2/3/4/5	80
EQUIPMENT	DWG.NO.	-	122

(4) INSTALLATION OF BOAT



ALL INSTRUCTION LIFE SAVING	HULL NO.	CH-0801/2/3/4/5	81.
EQUIPMENT	DWG.NO.		/12

1	HEAD TACKLE	6	FASTENING UNIT	-11	SIDE SUPPORT
2	FLOATING TACKLE	7	BOARDING PLATFORM	12	TACKLE
3	BOAT FALL CHAIN	8	DAVIT FRAME	13	CROSSBEAM
4	DAVIT ARM	9	STOPPINT UNIT	14	REMOTE CONTROL UNIT
5	LIMITUNT	10	PIVOTUNIT	15	WRESYSTEM

(5) ENTERANCE

After being assigned a lifeboat, passengers should slop outside the lifeboat and await instructions from the lifeboat crew. When told to board, passengers should enter the industry wisking their lifeboat packets.

Prepare boat for launching by releasing the lesting arrangement and E.K.A. bringing the boot into boarding position. See cavit manufacturer instruction manufacturer.

Open the emberkation oper and seque in open position. After the passengers is fully on point of the boat, dose the cost.

Heimsman discondects external power pag and enters. These should not applicable, if solar power panel is installed.

Helmeman turns main battery switch on,

All designated crew (forward hook operator and all hook operator) board lifeboat and take up their assigned positions. If a painter is to be used during launching, remove from the equipment tank and secure to painter release hook on boat and other end to ship.

In case of burning liquid on sea surface, it is now the time to activate the omergency air system as described.

All passengers board lifeboat occupying the seats furthermost from the entrance first.

Once sealed and wearing lifejackets, place the straps over shoulders as shown in fig. ta & Fig. 1b.




Fig. 1s Donning safety harness



Fig. 1b Adjusting safety harness

ALL INSTRUCTION LIFE SAVING	HULL NO	C+-0801/2/3/4/5 101	2
EQUIPMENT	DWG,NO.	- /122	

(19) LIFEBOAT / RESCUE BOAT OPERATION INSTRUCTION



A LOWERING

- 1. Release the fasting line (1) by ste fook EKA
- 2. Draw out the loggle pin of arm slop lever and selecise the tinn slupper (2).
- 3. Embark personnel in book
- Pull the remote control wire (3) is suspended from the day's into the litations or immire brake lever (5) directly from the local dady.
- · CAUTION ·

During the turning out, operate as slowly as possible.

When the linebook reaches the water, release the remote control wire, and operate the releasing gear
of the litebook

B. HOISTING

- 1. Hang the suspension block of each side on the hook of the lifeboot.
- 2. Starter main switch on.
- 3. Operator at deck level presses remote push button and holds to holst
- · CAUTION

When turn in life/rescue davit, turn on clutch lever lower speed position.

- After davit is stopped by limit switch or operator, near fully stowed position the davit are brought fully home by crark handle on which.
- 5. Rt the arm stopper.
- 6. Connect the slip hook at tashing line and faster the tumbuckle.
 - 7. Starter main switch off.

ALL INSTRUCTION LIFE SAVING	HULL NO.	CH-0901/2/3/4/5	87 /
EQUIPMENT	DWG,NO.	+	122

(10) STARTING

10.1 Checks before starting

Starting any engine can be dangerous in the hands of inexperienced people. Before attempting to start any engine, the operator should be familiar with the engine instructions mounted in the boat and the engine manufacturar instruction manual.

- Ensure that the batteries are in serviceable condition and correctly connected.
- Check that the oil levels in the engine and the geartiox are correct.
- Check that the fuel tank is full and that the system is primed.
- Check that fuel valve on bottom of the tain is lopen,
- Check that all water draw plags and cooks are closed.
- Check that the water fevel in the header tank is filled up with no stupe of waterland freeze. Under no occurristances must the engine be started without liquid in the pooling system.
- Ensure that the peaston talk neutral
- 10.2 To start engine (homia plan)
- Disconnect ships external power in poly by pulling the play ries the emparkation access.
- 2. Turn main bullery swilds to "ON" positions
- 3. Please refer to the starting treatments posited pose to the harmonis position or to the engine instruction manual.

If the engine should fall to start due to poor pattery condition, continue with the emergency starting procedure. If the engine falls to start within 15 seconds; despite good battery condition, release the switch and investigate the cause. The starter motor should be allowed to cool for at least 15 seconds before attempting to restart.

CAUTION

This engine can be run with the bost out of the water for a maximum of 5 min, but the propeller shaft should only be engaged for a few seconds at a time to check is operation.

While the lifeboat engine is running the alternator will charge all its lifeboat batteries. The battery charger mounted on the art pillar only operates when the boat is stowed in the Davit and the ships power supply is connected.

- 10.3 To start engine (emergency start)
- 1. Disconnect ships external power supply by pulling the plug near the embarkation access.
- 2. Turn emergency battery switch to "ON" position,
- 3. Start engine using the normal starting procedure from step 3.

ALL INSTRUCTION LIFE SAVING	HULL NO.	CH-0901/2/3/4/5	88
EQUIPMENT	DWG.NO.	-	/122

10.4 To stop engine

Presented to the stopping instruction posted close to the helmaman's position or to the engine instruction manual.

Entergency stopping of the engine can be achieved by dosing the fuel shut-off valve located on the injector pump on the engine. This valve is normally closed by a solenoid operated by the stop button, but it may be closed manually if the solenoid is defective.

(11) TRANSPORT LIFTING



Towing hooks, sprinkler pipes, etc. must not be used for anything but the purpose for which they were constructed.

LONG PULLS!

Long pulls must be used. Short pulls put a heavy load on the wires and hook attachments.

REQUIRED LENGTH AT LEAST 1.5 TIMES THE BOAT LENGTH!



Gambar 1 Mualim 3 memberikan grease pada wire winch sekoci penolong.



Gambar 2 Mualim 3 memberikan *grease* pada *wire* pengaman sekoci penolong.



Gambar 3 Mualim 3 memberikan grease pada wire sekoci penolong.



Gambar 4 Mualim 3 memberikan *grease* pada dewi-dewi sekoci penolong.




Gambar 5 Deck cadet mengganti reflective tape sekoci penolong.



Gambar 6 Mualim 3 mengecek peralatan sekoci penolong.



Gambar 7 pengisian pada emergency air system sekoci penolong.



Gambar 8 Masinis 4 melakukan pengencekan bahan bakar sekoci penolong.



Gambar 9 Masinis 4 melakukan pengecekan pada oli sekoci penolong.



Gambar 10 Annual inspection peralatan sekoci penolong oleh teknisi dari darat.



Gambar 11 Deck Cadet membersihkan karat pada hook sekoci penolong.



Gambar 12 pengecekan pada tangga embarkasi sekoci penolong.



- Authorized Service Station LLR Is LIPEBOAT RFD 10VO, RFD, DSB, CSM, ZSDEAC SAMSONS, TERROTEN VENDERMS, PASSIMER
- Pire Extragacion & Fixed System Service and Solidy Equipment Supply

Ji. Sartuetra Sin. S Kielja - Ranostadas Sentan 1 (23) Sakarta Utara - Indonesia Misme : K2 (21) 4009053-54 Fax : 62 (21) 4009055

STATEMENT OF CONFORMITY

This is to confirm that the following lifeboat arrangements have been carried out periodic maintenance by the undersigned licensed service engineer in accordance with SOLAS Regulation III 20.3.2 and MSC / Circular 1206 and that these lifeboat arrangements have been found to be fit for purpose.

Name of Ship/Platform : MT. SUNGAI GERONG Flag : INDONESIA Class: DNV / BKI IMO No. 1 9509906 STARBOARD SIDE TOTALY ENCLOSED / BH - 6A 30 PERSONS Cap 1,4506 LIFEBOAT Seri Number Date of manufacture (NI) SEPTEMBER 2011 DINGDAD BENIAL SHIPBUILDING HEAVY INDUSTRI Manufacturer ON LOAD REDEASE MECHANISM / BG - 3 Type YZHK 60 S Seri Number RELEASE ENAAPRIL SETT Date of manufacture KINGBO ASIAN F.R.P.BOAT MANUFACTURING Co,Ltd Manufacturer MINGED GRAVITY DAVIT/BO - PV 60 Туре

DAVIT Date of menufactions : MARCH 2041

Menofactions : CBNGDAO SEPAI SHIPBUILDING HEAVY INDUSTRI

Type
Seri Number
Date of manylacting
Seri March 2011

Manufacturer - GINGDAG SCHAF SHIPBUILDING HEAVY INDUSTRI

Date of servicing: NOVEMBER 19th 2019 - Port of servicing: KALBUT - SITUBONDO

Next Service: NOVEMBER 19th 2019 - Kanal of servicing: Annual Inspection

Remarks :

WINCH

Mengetahui IPALA KANTOR UPP KELAR R KANKUT IPALA KANTOR UPP KELAR R KANKUT

Half Mys APTO S. Sies Not Halfwards 200312 1 001 Prevata Musta Tk. (1970.)

primer is systemal DCS Program to

Surveyor Signature/Stamp :



NAME: Mr. TUKIYAR

SP 09471118.12.1

Date : NOVEMBER 18th 2018













Gualify of safety is not concur-



- Authorized Service Station SLR is LIFERDAT APD TOHO, IPPC, DISK, COPI, 20000C (LOHGOW), SANGHEN KINITANIE, FASSMER
 Fire Entinguisher & York Sween Service and Safety Equipment Supply

R. Samuella NJ. S. Biotja - Rawettetak Selatan 14230 Jakarta (tara: - Josophesa Merec: 62 (21) 4006635-54 Fax: 62 (22) 4006655 E-crad: 14508eeperapertal.com

BOAT DAVIT CHECK LIST

Type of Davit	: HINGED GRAVITY DAVIT / BO - PV 60
Serial Number	: 182
Date of manufacture	MARCH 2011
Manufacture	: QINGDAD BEIHAI SHIPBUILDING HEAVY INDUSTRI
Type of ship	: OIL PRODUCTS TANKER
Class	DNV / BKI
Call Sign	: POJO
Service Location	: KALBUT - SITUBONDO
Davit Location	: STARBOARD SIDE
Printed Printed Street, 1977	11 7 11 9 10 11 11 11 11 11 11 11 11 11 11 11 11

No.	Items	Resul	it of inspection and se	ervicing	Remarks	
01	Frame	El Good	IT Part exchange	☐ Repair		
O.F	Davit arms	MEGOOD	D Part witchings	☐ Repair		
03	Hinge	1 Good	I Part exchange	☐ Repair		
04	Sheave	@ Good	71 Part exchange	N Repair		
05	Suspension block	6 Good	El Part exchange	Nepair Nepair		
96	Davit arms stopper	₩ Bood E	(A) Pars exchange	Repair		
07	Trigger hook	6 Goed	Part exc. Vango	D Répair		
08	Boat fall	Good	DiPart exchange	(I Repair		
89	Turn buckle	F Good	Pert exchange	☐ Repair		
10	Lashing line	W Good	T Part axchange	D Repair		
11	Deck operation device	E Good	□ Part exchange	## Repair		
12	Remote control device	3 Good	() Part exchange	Repair.		
13	Recovery strap	d Good	E Part exchange	Repair		
14	Hanging off pendant	HJ Good	D Part exchange	13 Repair		
15	Maintenance pendant	M Good	D Part exchange	☐ Repair		
96	Spare-parts	1 Good	(Part exchange	☐ Repair	N/A	
17	Others	☑ Good	☐ Part exchange	☐ Repair		
Notic						
	Service Station	Service eng	gineer signature :	CERTIFICATE No:		
Service Station		NAME	M-TOKIYAR	SP 09471118.12.1 Date: NOVEMBER 19th 201		













- Authorized Service Station ILR & LIFEDOAT
 HID TOYOO, RFIL DISB, CAM, TOBIAC
 SAMSDWG, TUMISTEN SOUTHAND, FASSINEN
 File Extragalities & Filed System Service and Selvin Spapment Supply

3. Samucha Nv. 5 Njetje - Ransstadak Selatan (1420) Selasta share - Instressia Harmi (142 (22) 4309655-54 Fee - 62 (23) 4309655-54 Senski - mhobiographyrmic com

Annual Inspection Check List (1/2) Lifeboat & Release General

Type of Lifeboat	: TOTALY ENGLOSED / BH - 6A
Serial Number	: 1506
Date of manufacture	: SEPTEMBER 2011
Manufacture	: QINGDAO BEIHAI SHIPBUILDING HEAVY INDUSTRI
Type of ship	: OIL PRODUCTS TANKER
Class	; DNV / BHI
Call Sign	: POJO
Service Location	: KALBUT - SITUBONDO
Lifeboat Location	: STARBOARD SIDE

No.	thems.	Resul	t of Inspection and a	ervicing	Remarks
01	Outside hull	☑ Good	☐ Part exchange	C Repair	
02	Outside canopy	⊞ -000₫	- Part exchange	C Repair	
03	Buoyant life line	(B) Good VI	Det inchange	C Repair	
04	Enclosure stucture	Good	Partexthange	C Repair	
05	Inside structure	M Good	D Part exchange	Cl Repair	
96	Painter release device	M Good	☐ Part exchange	☐ Repair	
07	Door and hatche	in Good	I Par exchange	57 Repair	
08	Window	M Good VA	C Part wichangs	Repair	
09	Ventilator	al Good	D Part suchange	C Repair	
10	Steering gear	El Greed	FI Part exchange	(1) Repair	
11	Stern tube	■ Good	☐ Part exchange	Repair	
12	Propeller and propeller guard	F) Good //	C) Part exphange	☐ Repair	
14		Cood G	D Part exchange	C Repair	
15	High pressure line for air supply nes	E Good	Part empharige	7 Registr	
16		ED Good	□ Part.ev/diange	/ Ch Repair	
17	Air cytinder Data	Press. Cyl. D.	700 BAR	Last Touted :	11- 2016
18	The second secon	I Good	Part exchange	Cl Repair	
19	Drain valve and plug	El Good	Thert exchange	C Repair	
20	Hand pump	E Good	☐ Part exchange	☐ Repair	
21	Seat belt	El Good	☐ Part esettange	C Repeir	
22	Equipment.	16-Good	D-Part exchange	☐ Repair	
23		12 Good	D Part exchange	☐ Repair	

Release Gear

No.	Hems	Res	ult of inspection and s	ervicing	Remarks
01	Reset condition	☑ Good	☐ Part exchange	☐ Repair	
02	Release handle unit	30 Good	☐ Part exchange	☐ Repair	
03	Control cable	El Good	☐ Part exchange	☐ Repair	
04	Hook unit	El Good	☐ Part exchange	☐ Repair	
05	Interlock unit	iii Good	☐ Part exchange	☐ Repair	
90	Hook fastening	id Good	☐ Part exchange	☐ Repair	
07	Release gear operation test	HI Good	☐ Part exchange	☐ Repair	
08	Release gear operation test	C Good	☐ Part exchange	☐ Repair	NIA
09	The beautiful control of the control	☐ Good	O Part exchange	☐ Repair	











pully of salety is our constitu-



- Authorized Service Softon SAI is LIFEBOAT
 BIFD TOPO, APIL DISK CON, EDIDAC
 SAMCONG, JUNGTON KRUDANG, FASSMER
 Pred Entrepowher is Freed System Service and Safety Equipment Septing

J. Sartuche No. 3 Rodja - Rovobodak Selebar (4290 Sakaria Ulava - Erebersia Phares : 62 (21) 4209653-34 Pair : 62 (21) 4209655

Annual Inspection Check List (2/2) Machinery & Electric

ENGINE

Type of Lifeboat	: 380J + 3
Serial Number	: 110694
Date of manufacture	: 64 - 2011
Manufacture	: SIYANG BRAND MARINE

No.	Items	Resu	it of inspection and si	envicing	Remarks
1	General	El Good	☐ Part exchange	☐ Repair	
2	Engine oil	H Good	☐ Part exchange	Cl Repair	
3	Clutch oil	et Good na	Past exchange	Cl Repair	
4	Fuel oil tank	W Goott W	CI Pait acchange	☐ Repair	
5	Fuel oil pipe	HE Good at	D Part melbange	C) Repair	
	S.W. pump	El Gond	D Part exchange	☐ Repair	
7	Gauge panel	El Good	D.Part exchange	C Repair	- 444.5
8	Spare parts	Good Good	Part exchange	Repair	N/A
9	Tool	P GOOM KA	D Part exchange	☐ Repair	N/A
10	Oil Filter	Good_	Part werhange	Cl Regain	
11		☐ Good	Part acchange	(7 Repair	

Electric

1 Battery 2 Interior eight 6 Good 7 Part exchange 7 Repair 2 Interior eight 6 Good 7 Part exchange 7 Repair 3 Search light 6 Good 7 Part exchange 7 Repair 4 Compass light 7 Part exchange 7 Repair 5 Belt of generator 1 Good 7 Part exchange 7 Repair 6 Electric wiring 7 Cood 7 Part exchange 7 Repair	40.	Hums	366	Best	that inspendion and h	erwiging	Remarks
3 Search light 4 Compass light 5 Belt of generator 6 Electric wiring 3 Search light 6 Good 7 Part exchange 7 Repair 7 Repair 7 Repair			- B.B.	El Good)	17 Part exphange	/th Repair	
4 Compass light F Gorsi	2 Interior 6g	fit	1000	id Good	D Part wichange	/ Repair	
5 Belt of generator Good Part exchange Repair 6 Electric wiring Good Part exchange Repair	3 Search lig	ht	1100	E Good o	D Back exchange	Repair	
5 Electric wiring	4 Compass	light		M. Gores	- Tr. Part exchange	Zi Repair	
	5 Belt of ger	serator	2, 6	M Good	I Part exchange	☐ Repair	
C Cond C Dud subbands C Sanair	6 Electric w	iring	10	El Copd		☐ Repair	
TEX DOOD C. Petr exelusive C. Rapair	100000	777.19	14.	FI Good	C Part extremes	☐ Repair	

Service Station	Service engineer eignatum :	CERTIFICATE No:
The state of the s	SHAPE	SP 09471118.12.1
	(A) (G) (E)	CAROLINA COLONIA COLO
	12010NV 1-1	
Contract of Contra	and the same of th	Date - MONEYARDED AND TOUR
PT.SEGARA PERMAI	NAME: Mr. EUSIYAR	Date: NOVEMBER 19th 2018











quality of carety is our concern



- Authorized Service Station ILR & LIPEBOAT ero 1000, APO, 100, COM, 2000AC SAMSONG, SANDISH KINDANG, FASSMER!
 Fire Estinguisher & Fixed System Service and Saltiny Equipment Supply

BOAT WINCH CHECK LIST

Type of Winch	: ELECTRIC MOTOR DRIVEN / BW = H / 63	
Serial Number	: 043	
Date of manufacture	- MARCH 2011	
Manufacture	: QINGDAO BEIHAI SHIPBUILDING HEAVY INDUSTRI	
Type of ship	OIL PRODUCTS TANKER	
Class	DNV/8KI	
Call Sign	: P0J0	
Service Location	: KALBUT - SITUBONDO	
Winch Location	: STARBOARD SIDE	

No.	Items	Result	t of Inspection and se	ervicing	Remarks
01	Gear box	III Goed	I Part exchange	C Repair	
02	Lubrication oil	Bigood	Part exchange	☐ Repair	
03	Gear	Good	Cl Part exchange	Repair	
DI	Bearing	E Good	C Part exchange	II Repair	
08	Oil soal	M Bood	□ Part exchange	C Repair	
06	Hand brake device	@ Good	El Part exchange	Th Repair	_
07	Governor brake device	No Good	D Part exchange	I Repair	
08	Cam clutch	Fi Good	C) Part exchange	C) Repair	
09	Manual handle	El Geon	th Part exchange	El Ropair	
10	Wire drum	El Good	D Part exchange	C Repair	<u></u>
11	Speed change lever	T Good	D Part exchange	Repair	N/A
12	Electric motor/Air Motor	N Good	Part exchange	(A Repair	
13	Starter panel (0)	@ Good	D Part exchange	C. Repair	
14	Limit switch	El Good	D Part exchange	Repair	
16	Push butter feet, colds, plug, receptable	F) Good	T Part exchange	Repair	
16	Dynamic winch brake test	FI Good	D Part exchange	☐ Repair	Empty boat (Annual)
17	Dynamic winch brake test	[] Good	☐ Part-exchange	☐ Repair	Full load x 1.1 times (5-yearly
18	Winch foundation	Hi Good	☐ Part exchange	☐ Repair	

Service Station

Service engineer signature :

CERTIFICATE No:

SP 09471118.12.1

Date: NOVEMBER 19th 2018











- Authorized Service Statum SLR & LIFEBOAT APO 10YO, IRO, DRB, CON, ZODING SAHDONG, XANGERN KINSTANG, FASSHERK
 Tive Everywher & Fixed System Service and Safety Equipment Supply

B. Sernado No. 5 Rieljo - Ravelindra Science 14/28 Ideatro Ideas - Indonesia Monte: 62 (21) 4/09483-54 Fax: 62 (21) 4/09483 E-mail: 6/6/Ewgmaper/mai.upo

Lifeboat Equipments

Libitost Location		STARBO	DARD SIDE			INTELLIBERCTURE
Serial Number		: 1506				HOUSER 1719 2018
O. Name of Squipment	Quant	City	Brund	Exp., Date	Solac Reg	Remark.
1 Anti Seesickress Tablets	180	Taite	ANTIMO	09-2021	6 tah/pers	RENEWED
2 Baler	1.1	Pto	371111177		1	6000
3 Bilge Pump	1.	Pts			1	6000
4 Bost Hook	-1	Pes			1	6000
5 Bouyant Rescue Quit	2	Pcs			2	6000
8 Bouyant Life Line 25 Mtr	-2	Pes			2	6000
7 Buchet	2	Pos			- 1	6000
8 Cover for Engine	- 1	Pca			1	Open Type Lifebout
9 Compass with Light	1	Pes			1	6000
10 Crutch or Thole Pin / Rawing Port	1	Pos			Deparet on LB	6000
11 Dipper with Largard	1	Pes			1	6000
12 Drinking Cup	1	16			1	6000
13 Drinking Water	180	1160 H	MINISTER	76-2021	3 fm / pen	RENEWED
14 Engine Tool Kit	1	465	acquino.	10000	1	6000
	6	Pack	AL BCS	10-1071	1	RENDAND
15 First Aid Nt	1	Set	Die Die	Carried .	1	6000
16 Fishing Kit / Tackle	-	Annual Property and Property an	1	70	1	6000
17 Food Centainer	-	A Pers		The said	Total Control of the	
16 Food Ration	30	Chhoo	SERVER	10-2637	10,000 () / Pers	ALMINED
19 Hatches / Ase	V.	Pes	EKA D		5	6000
20 Jack Knife	P NY	Pite	70	No. No.		6000
21 Ladder	1/1/	Rpr	n n	VB COS		6000
22 Life Saving Signal Tattis	37 0	Fin	P (2	No Colo		6000
23 (Der	8	(Jess	DA	7 42	Depared to LE	6000
24 Parachute Signal	4	Pts	PR	11-3059		RENGWED
25 Plug Drain	100	PER		8 20		6000
26 Portable Fire Extinguisher	1.00	IN BUT		VACO I		DP. Cap. 2 Kgx
27 Protection Cover	LVA.	PER		1000 /	/ 1	Open Type Lifebour
28 Painter Line 50 ertra	医70	Fest	0	CON /	1	6000
29 Rader Reflector	1	NOT.	0	1	7 1	1000
30 Red Hand Flares	40	Pris U	PVP	06-2025	6	RENEWED
31 Repair KX for FRP	-	Selli)		1	1	
32 Sciare Tiller	1	Set			1	-
23 Ifart		A Per		4		
34 Sau Andrer	7	Pcs A	m A		1	6000
25 See Sickness Reg	30	Pro	H		1 pos/pera	6000
	distribution in	Pes			1 Box L bank	6000
36 Search Light	1		_		1	6000
37 Signaling Mirror	1	Pcs	9667	46 5514		
18 Smoke Signal	-2	Pes	PW	09-2021	- 2	RENEWED
39 Spare Batteries	4	Pts	ARC	87-2021	1	RENEWED
40 Spare Bulb		Pes			1	
41 Storm Lamp	-	Pcs			1	Open Type Lifebox
42 Storm G6	-	Lare			5 live	Open Type Ufobox
43 Survivat Manual	.1	Pes			1	6000
44 Thermai Protective Aid	1	Pos			10 % from LB Cap	6000
45 Tin Opener	3	Pis			1	6000
46 Torch	- 1	Pes			1	6000
47 Whistie	1	Pis			1	6000
4B Safety Matches Water Proof	11	Pes			1	6000













- Authorized Service Station EUR & LIFEBOAT RPD TOYO, RPD, DSR, COM, 2010IAC, SANGEWE, SANGEEN KONTAND, NGSPIER
- · Fire Extragation & Flood System Service and Salaty Equipment Supply

3: Samushin No. 3 Hodge - Revented to Selector: 14730 36Arta More - Dubresta Phone : 62 (21) 4309657-54 Par.: 52 (21) 430965

STATEMENT OF CONFORMITY

This is to confirm that the following lifeboat arrangements have been carried out periodic maintenance by the undersigned licensed service engineer in accordance with SOLAS Regulation III 20:3.2 and MSC / Circular 1206 and that these lifeboat arrangements have been found to be fit for purpose.

Flag : INDONESIA Name of Ship/Platform : MT. SUNGAI GERONG IMO No. 1 9509906 Class: DNV / BKI PORTSIDE TOTALY ENCLOSED / BH - 6A Type : 30 PERSONS Cap ME #507 LIFEBOAT Seri Number Date of manufacture NIP SEPTEMBER 2011 GINGDAD BEHAL SHIPBUILDING HEAVY INDUSTRI Manufacture ON LOAD RELEASE MECHANISM / BG - 3 Type 89695230 Seri Number RELEASE EKA: APRIL 2013 Date of manufacture NINGEO ASIAN F.R.P. BOAT MANUFACTURING COLLID Manufacturer HINGED GRAVITY DAVITY BO - PV 60 Type 121 Seri Number DAVIT Date of manufacture MARCH 2011 Manufacturer O MODAO BEIHA/ SHIPBUILDING HEAVY INDUSTRI ELECTRIC MOTOR DRIVEN / BW - H / 63 Type Seri Number WINCH MARCH 2011 Date of manufacture GINGDAO BEIHAI SHIPBUILDING HEAVY INDUSTRI Manufacturer Date of servicing : NOVEMBER 19th 2018 Port observicing : KALBUT - SITUBONDO Next Service Annual Inspection : NOVEMBER 19th 2019 Kind of servicing : Remarks: Mengetahui Surveyor Signature/Stamp : Certificate No. TURLINE BLAZES POUR SP 09471118.12.1 DAT HATTAN WIYANTO S.Sop MEP 19770025 200312 1 001 Penata Muda Tk. (1975.) NAME: Mr. TUKIYAR Date: NOVEMBER 19th 2018

Nigotimal Is Approved SASS Progries by











quelle of safety is say concern



- Automost Service Station ILR & LIFEBOAT APD 10YO, RFD, 058, CBM, 2008AC, SANGONG, JUNGVIN KINCANG, FASSMER
- Fire Extreparation & Pixed System Service and Salety Expansion Septy

Senutra No. 5
 Nucle - Revolución Sesten 142/0
 Jakarta Utara - Indonesia.
 Plane - 62 (21) 400/655 4
 Nucle - 62 (21) 400/655
 E-mail - 101/03/03/parapentos zon.

Annual Inspection Check List (1/2) Lifeboat & Release General

Type of Lifeboat	: TOTALY ENCLOSED / BH - 6A
Serial Number	: 1507
Date of manufacture	: SEPTEMBER 2011
Manufacture	GINGDAO BEIHAI SHIPBUILDING REAVY INDUSTRI
Type of ship	OIL PRODUCTS TANKER
Class	: DNV / BKI
Call Sign	; POJO
Service Location	: KALBUT - SITUBONDO
Lifeboat Location	PORTSIDE

No.	Itams	Result	t of inspection and se	rvicing	Remarks
01	Outside truff	El Good	☐ Part exchange	f3 Repair	Seattlene -
02	Outside canopy	E-Good	G-Part exchange	☐ Repair	
03	Buoyant life line	Ji Gond VI	CEPact exchange	☐ Repair	
04	Enclosure sructure	ar-Good	D-Part-eschange	C Repair	
05	Inside structure	Fl Good	I Part exchange	☐ Repair	
08	Painter release device	E Good	Part exchange	☐ Repair	
07	Door and hatche	at Good	CF Part exchange	C Repair	
80	Window	to Good VA	IT Fart exchange	□ Repair	
09	Ventilator	id Good	D Partiershange	C Ropair	
10	Steering gear	H Geod	O Part exchange	D Ropair	
11	Stern tube	Good .	Part exchange	D. Ropair	
12	Propeller and propeller guard	El Good /7	C Part exchange	Cl. Repair	
14	Breather valve	& Good	Part exchange.	C Repair	
15	High pressure line for all supply sign	R Good	D Partituehange	/ Repair	
16	Air cylinder	ED Good	C.Partershange	D.Repair	
17	Air cylinder Data :	Press. Dyl.1	200 HAR	Last Yested :	11 - 2016
18	Sprinkler system	El Good	Part Michange	☐ Repair	
19	Deale value and obset	Et Sport	Cl Bartexchange	/ Repair	
20	Hand pump	M Good	Part exchange	☐ Repair	
21	Seat belt	S Good	D Part suchange	☐ Repair	
22	Equipment	16-Good	Part exchange	☐ Repair	
23	The state of the s	(6) Good	Part exchange	☐ Repair	

Result of inspection and servicing Remarks No. Items : ⊞ Good 01 Reset condition ☐ Part exchange 02 Release handle unit El Good ☐ Repair ☐ Repair ☐ Repair ☐ Part exchange 03 Control cable id Good M Good ☐ Part exchange 04 Hook unit El Good ☐ Repair 05 Interlock unit ☐ Part exchange 06 Hook fastening 57 Good ☐ Part exchange ☐ Repair ☐ Part exchange ☐ Repair 07 Release gear operation test El Good ☐ Part exchange ☐ Repair 08 Release gear operation test □ Good NA ☐ Repair 09 C Good Cl Part exchange













- Authorized Service Station ILP, is LEPEDCAT #TO 10YO, KPD, DEB, CSM, 2000AC SERVICING, JUNCYEN SERVICES, PASSARDS
 Face Extragulator & Read System Service and Selfes Equipment Supply

3. Semanto No. S. Rodje - Revoltadal Salatar (4220 Jakanta Utara - Indonesia Phone: 62 (21) 458653-94 Nor. 62 (21) 458655-95 E-bad - Middingengerma com

Annual Inspection Check List (2/2) Machinery & Electric

ENGINE

Type of Lifeboat	: 38OJ - 3	
Serial Number	: 110693	
Date of manufacture	: 04 - 2011	
Manufacture	: SIYANG BRAND MARINE	
The state of the s	And the second s	and the second second

Nα.	Items	Resul	Result of inspection and servicing				
1	General	17 Good	C Part exchange	☐ Repair	2010111		
2	Engine oil	H! Good	☐ Part exchange	☐ Repair			
3	Clutch oil	H. Good BALL	TPstt exchange	☐ Repair			
4	Funi oil tank	W Good WIL	I Part explange	Cl Repair			
5	Fuel oil pipe	to Good at	D Part exchange	☐ Repair			
6	S.W. pump	E Good to	Part exchange	☐ Repair			
7	Gauge panel	El Good	D.Part exchange	☐ Repair			
	Spare-parts	C Good	☐ Part sochange	D Repair	N/A		
0	Tool	TO GOOK KA	D Part oxchange	☐ Repair	N/A		
10	Oil Fitter	id Good	D Part exchange	☐ Repair			
11		[Sood	Part verifiange	T Repair			

Electric

Battery D Good Part exchange Repair	No.	Hitms	Sanul	for inspection and a	agy ic mg	Remarks
2 Interior light 3 Search light 5 Search light 6 Compass light 6 Compass light 7 Compass light 7 Compass light 8 Selt of generator 9 Code 9 Part exchange Repair 9 Code 1 Part exchange Repair 9 Code 1 Part exchange Repair	1	Battery	ED Good	- Part exchange	/ Repair	4192545547
4 Compass light	2		81 Good	D Part exchange	☐ Repair	
4 Compass light Shored Chart exchange Repair 5 Belt of generator Rigod Part exchange Repair 6 Electric wiring Repair 1 Good Part exchange Repair	3		Ed Georgia	Part mahange	Repair	
6 Electric wiring ☐ Good ☐ Part sechange ☐ Repair ☐ Good ☐ Part exchange ☐ Repair	4	Compass light		TO Rart exclusion	/ Repair	
Good ParteRhange C Repair	5	Belt of generator	El Good	Part exchange	☐ Repair	
□ Good □ Part exthange □ Repair	6	Electric wiring	El Clood	13 Part sechange	Cl Repair	
Notice :	5.33	1	Good .	Part exchange	☐ Repair	
AB	Not	ice :	1 -			

Service Station	Service engineer signature :	CERTIFICATE Not
	- GRAPE	SP 09471118,12,1
	39 6	
PT.SEGARA PERMAI	NAME: Mr. TURIYAN	Date: NOVEMBER 19th 2018













- Authorized Service Station ILA B. LIPEDOAT APG TOYO, RPG, DBB, CBM, 2001AC SAMGONG, JUNIOVIN XINDIANG, PAREMER
- Fire Extinguisher & Flood System Service and Safety Equipment Supply

J. Semulto No. 5 Hotje - Russinanie Sentan 1420 Jakots (Sare - Indonesia Preme 162 (21) 4309653 54 Ris 163 (21) 4309655 E-mail 1 intolluspanguerrus com

BOAT DAVIT CHECK LIST

Type of Davit	: HINGED GRAVITY DAVIT / BO - PV 60	
Serial Number	1181	
Date of manufacture	: MARCH 2011	
Manufacture	: QINGDAO BEIHAI SHIPBUILDING HEAVY INDUSTRI	
Type of ship	OIL PRODUCTS TANKER	
Class	: DNV / BKI	
Call Sign	POJO	
Service Location	: KALBUT - SITUBONDO	
Davit Location	PORTSIDE	

No.	Items	Resu	Remarks		
01	Frame	El Dood	f7 Part exchange	☐ Repair	
02	Davit arms	E Good	Part exchange	☐ Repair	
03	Hinge	Good 9	CI Part exchange	C) Repair	
04	Sheave	☑ Good	D Part exchange	☐ Repair	
05	Suspension block	M.Good	CI Part exchange	Repair	
08	Davit arms stopper	P Good	/ Pari sechange	Repair	
07	Trigger hook	M Good	72 Part exchange	Repair	
80	Boat fall	P.Good	D.Part.exchange	C) Repair	
09	Turn buckle	F Good	Part exchange	☐ Repair	
10	Lashing line	F) Good	D Part exchange	O Repair	
11	Deck operation device	E Good	□ Part exchange	M/Repair	
12	Remote control device	T Good	D Part exchange	Repair	
13	Recovery strep	M Good	D Part exchange	D/Repair	
14	Hanging off pendant	El Good	□ Part exchange	☐ Repair	
15	Maintenance pendant	Prepor	D Part tixchings	☐ Repair	
16	Spare parts	1 Godd	TPart exchange	☐ Repair	N/A:
17	Others	☑ Good	D Part exchange	(3 Repair	

CERTIFICATE No: Service Station Service engineer signature : SP 09471118.12.1 NAME: Mr. TUKIYAR PT.SEGARA PERMAI Date: NOVEMBER 19th 2018











quality of parety is the company



- Authorized Service Station SUR & LIPERCHT
 RPD TOYOL, RPD, DSB, CSM, ZDDOAC
 SARSCOND, JUNEAU-PIL SPICEMAN, PACCHER
 For Extrapaction & Placed System Service and Safety Equations. Supply

3. Serveira No. 3
Fortje - Revolució Sesser 14230
Decento Unio - Volucesto
Resser 143 (21) 4000055
Fee: 43 (21) 4000055
C-rest (19940-sept serveira com

BOAT WINCH CHECK LIST

: ELECTRIC MOTOR DRIVEN / BW - H / 83	
: 043	
: MARCH 2011	
: QINGDAO BEIHAI SHIPBUILDING HEAVY INDUSTRI	
: OIL PRODUCTS TANKER	
: DNV / BKI	
POJO	
: KALBUT - SITUBONDO	
PORTSIDE	
	: 043 : MARCH 2011 : GINGDAO BEIHAI SHIPBUILDING HEAVY INDUSTRI : OIL PRODUCTS TANKER : DNV / BKI : POJO : KALBUT - SITUBONDO

No.	Tieres	Result	of inspection and se	ervicing	Remarks
01	Gear box	El Good	C) Part exchange	☐ Repair	
02	Lubrication oil	N Glood	th Part exchange	☐ Repair	
03	Gear	E Good	TPart exchange	Repair	
04	Bearing	H Good	Ti Part exchange	d Hapair	
05	Oil seal	M Good	D Part exphange	Cl Hepair	
06	Hand brake device	国 Back	EKPart uxchange	C Repair	
07	Governor brake device	Z Good	D Part exchange	Repair	
08	Cam clutch	W. Groot	D Part exchange	∏ Repair	<u></u>
09	Manual handle	E Good	Chart exchange	Cl Repair	
10	Wire drum	M Good	D Part exchange	T Hoppin	~
11	Speed change tover	T Good	Cl Part exchange	13 Stepair	NIA
12	Electric motor/Air Motor	El Good	Part exchange	D Rosair	
13	Starter panel	a Good	TI Part extendings	Cl Reguir	
14	Limit switch	E Good	D Part exchange	Repair	
15	Pants button box, catrin, play, receptarity	H Good	T Part exchange	1 Repair	
16	Dynamic winch brake test	10 Good	CI Part exchange	☐ Repair	Empty boot (Annual)
17	Dynamic winch brake test	☐ Good	☐ Part-exchange	☐ Repair	Full load a 1.1 times (5-yearly
18	Winch foundation	☑ Good	☐ Part exchange	☐ Repair	
lotic	4 1				
	Service Station	Service eng	gineer signature :		CERTIFICATE No:
			ONLY)		SP 09471118.12.1

PT-SEGARA-PERMAI- N

NAME: Mr. TUKIYAR

Date: NOVEMBER 19th 2018

DNVGL









- Auchorand Service Status IDJ & LIFEDCAT
 ARD-TOYOU, RPSL DSK, CSAL, SCOOL
 SAMDONG, IDANGTON KINUTANG, PAGENERS
 Fire Extinguisher & Found Senten Service and Selliny Equipment Supply

8. Sensuta No. 3 Sorpa - Revorantes Solnes 14233 Jokato (Izara - Indonesia Prore 1.62 (21) 439653-34 Fest 1476 egangermu upo

Lifeboat Equipments

	Lifeboat Location	PORTSIDE				DATE SUPPLYTON	
	Serial Number	: 1507		HOYOMES 1919-2008			
NI.	Name of Equipment	Quant	10	Brasil	Day, Date	Selas Reg	- Souck
1	Anti Sessickness Tablets	180	Tivita	CIMITINA	@9-2021	6 sab/pers	RENEWED
2	Bailer	1.1	Pas				6000
3	Slige Pump	1.5	Pts			- 1	6000
ĭ	Boat Hook	2	Pes			2	6000
5	Booyart Resour Quit	2	Pen			5	6000
ï	Socyant Life Line 25 Mb	1.2	Pcs			2	6000
7	Bucket	1.2	Disc			2.	6000

4 18	AFRET .		10.0				The same
3 8	lige Pump	1	Pts			1	6000
mineral first	sat Hook	2	Pes			2	6000
_	osyant Rescue Quit	2	Pes			- 2	6000
-	segant Life Line 25 Mly	-2	Pcs			2	6000
	urker	2	Pts			2	6000
	over For Engine	1	Pis			9	Open Type Lifebool
	ompass with Light	1	Pts			- 1	6000
	rutch or Thole Pin / Rowing Port	1	Pzs			Depend on LB	6000
GOTO OF THE PER	apper with Lanyard	1	Pts			9	6000
Grand Co.	vinking Cup	1	Pis	8.044		1	6000
	vinking Water	189	War It	WHILE AME	76-2521	3.ft/x / pers	REMINED
	ngine Tool filt	A P	Set	-	11	1	6000
	Irst Aid KH	X	Pack	9CH	00-1011		RENEWED
	Ishing Kit / Tackle	1	Set		130		6000
		1	Pin	000	93	1	6000
	sod Ration	.00	Tent	STREET, DO	10-200%	85000 X) / Pers	RENEWED
	latches / Axe	U.S.	FEB	KA	NO.	3	6000
-	ack Knife	-	Per	The same of	1	A	6000
21 1		DAV.	Pas	1000	The Case	Mail	6000
		01	Pes	U 1	AN WEST		6000
	fo Saving Signal Yable	NA.	The state of the s	6	100	Depend on th	6000
23 0		94	Per	2 AW	11-009	trepano an La	RENEWED
	aracture lignel	4	- British -	7 1	11-10029	1	6000
	Sag Dealer	10	Pes		78 GS		
	ortable fire Extinguisher	TO V	ex L	1	1000	V	DP. Cap.é Kps
	Votection Cover	100	Pol	0	War /	/ .	Open Type Lifebout
نتهنتك	uinter Line 50 mins	10	Poy	0	190 /1		GOOD
	adar Reflector	1	Pice	100	1-4	/ 1	600D
State of the last	ad Hand Flares 01	4	Pci	PW	04-3027	0	RENEWED
-	Appeir KOL for PRIP	1	Setti		/		-
	pero Tiller	-	Sal		19/	1	-
17 5	and the same and t	-1	A Des	- A	/		-
abel nd Gr	es Anchor	1	Pos A	R		1	6000
	ea Sickness Bag	30	Por			1 pcs / pers	6000
36 5	earth Light	1	Pot			1.	GOOD
37 5	ignaling Mirror	1	Pcs			1:	6000
38 5	moke Signal	2	Pos	PW	09-2021	2	AENIWED?
39 5	para Betteries	4	Pto	ABC	67-2021	2	REVENED
40 5	pore fluib	-5	Pes			1	-
	Torre Lamp	-	Poi			1	Open Spir Lifeboat
	torn GU	1	Lira			5 ftrs	Open Type Lifeboot
10.00	unival Manual	1	Pcs			. 1	6000
	Itermal Protective Aid	3	Pts			10 % from LB Cap	6000
تتعملون	In Opener	3	Pts			1	6000
	orch	1	For			1	6000
	Whatle	1	Pes			1	6000
	gfoty Matzhes Water Proof	1	Pes	_		1	6000











quality of solely is not consent.



ITEM LIST FOR STBD LIFEBOAT

	III SERIMAN ESCENT						YEAR	2018
No.	Item .	Quantity	Remark	AUGUST	SEPTEM	OCTO	NOV	DEC
1	Newfook.	1	100	GOOD	6000	6000	6000	0000
2	Silger Forma:	1		9000	9000	9000	0000	8000
1	Sewoch Light:	1		6000	GOOD	\$000	6000	. 6000
A	Compais	1		G000	G000	5000	6000	6000
5	Fire firtinguisher	1		6000	6000	6000	6000	8000
6	Socket for Power Source	1		6000	0000	9000	9000	0000
7	Soutt Hook	2		6000	G000	G000	G000	8000
	Strayort Bullet	1		G000	-6000	6000	6000	6000
9	Bucket	- 2		G000	G000	6000	6000	6000
30	Sanival Minual	1		GOOD	0000	6000	6000	6000
11	See Anchor	1		GOOD	GOOD	G000	- G000	6000
12	Exinter Line:	2	35m	G000	G000	6000	6000	6000
18	Barchet	2		6000	6000	6000	6000	6000
	500		@500 ml					
18	Fresh water	180	(3L/person)///	6006	6000	6000	6000	6000
15	Disper	14	11/2	6000	8000	6000	6000	600
16	Drinking sesses	188	100	0000	/pode	4000	.0000	6000
17	Food-Batters	30	(1box/person)	9920	00002	6000	6000	6000
38	Rocket Paracture Flans	4100	EKA	9000	copp	6000	6000	600
19	Hand Flare	14/0	Exp:	GOUN	0000	6009	6000	900
20	Bouyert Stroke Signed	1481	Exp:	G000	Cegco /	0000	6000	600
21	Webstprint Destric Forch	100		6,000	2000	D000	8000	600
22	Daylight Signating Mirror	1	70 0	GODD	6000	G000	S000	G00
23	Vestruition for Cressing Signals	1	9	6000	epoo	/3000	6000	G00
24	Signal William	2018		6000	6000	8000	600D	600
25	First Ald ID:	136	DE CO	0000	6000	6000	6000	600
26	Anti Sea Sinimess Minimess	240	Mpcs/person	5080/	6,000	/G000	6000	600
	National Section of the Control of t	house	Espi	0000	6060	0000	GOOD	600
27	Sensideren Beg	(20)	1pc/person	0000	GODD	6000	G00D	500
29	Jack Seife	1	4	6000	6000	6000	G000	600
29	Tin Opener	1	AF	6000	6000	G000	GOOD	600
53	Piesave Quart	2		6000	6000	GOOD	6000	600
31	Fishing Tackle	1		6000	5000	9000	9000	600
32	Engine Tools & Spare Part	1		6000	6000	GOOD	G000	600
33	Ridar Reflector	1		6000	6000	G000	G000	600
34	Rousant Gar	2		6000	6000	0000	6000	600
35	Thermal Protective Aids.	3		6000	0000	G000	GOOD	600
36	Boarding Ladder	1		8000	6000	GOOD	G000	600
37	Nun Collector	1		6000	6000	G000	G000	600
38	FFO	2		6000	6000	. G000	6000	600
39	Spore Bettery & Spare Bulb	6		6000	0000	GOOD	GOOD	000

LIVE SAVING APLIANCES HEAR OF BER

Western Visual Inspection:
Survival Crafts, Launching Appliances, Energency General Alarm System and Public Address System shall be visually inspected and leated to ensure

Point of Check	Description					Weakly				
Point of Check	Description	81	92	03	04	05	06	10	08	- 89
Lifethous Fig. 1	Check Condition of Outwide Street	Good	Goot	Good	Good	Good	Google	Gost	Good	Gos
Surboard	Chard Cordition of Rodder, Tilles Propeller, Propeller Suste, etc.	-	SWE	Gred	(SOM)	Since	SWE	Swe	Sont	Gos
Sebast No. 2	Check Condition of Cubality Shall	Stood	Good	Good	Guid	Gred	Spell	Goet	Good	(300
Pat (Rescue Start)	Check Condition of Rodder, Tiller, Propeller, Propeller Guerd, etc.	Good	Greet	Comit	Comit	Good	Good	Greet	Greet	Shire
Lifeboot Louroberg Applianous Urelost No. 1 Dischoot	Check Cardison of Lifebrar Devis, Lifting Hooks, Lifebrar Winch, Lifebrar Fall and Sheaves	Seed	Deed	Geed	Ored	Over	Core	Ovet	Gove	000
Lifeboat Launching Approxima Lifeboat No. 2 Port	Cheria Cardidon of Lifebrar Davils, Lifting Hooks, Ullaboar Minch, Lifebrar Pall and Sheares	Good	Greet	Gest	Greet	Gwe	Goed	Greet	Gred	Gw
Lifebool Engine Ris: 1 Starboard	Carryout Engine Running Test (Not Less than 8. Minutes): 8. Engagement of Dear	Stand	Greek	Card	Cloud.	Charl	Dat	Ound	Bong	Gen
Lifebout Engine No. 2 Port	Carryour Engine Flurning Test (Not Lass than 3 Minutes) & Engagement of Dear	Tood	Goed	Gard	Good	Giret	Giet	Great	Good	Goo
	Check Condition of Life out Shined at Firecastle No. 1	Good	Grand	Greed	Grand	Greek.	Goed	Greet	Greet	Gre
	Check Condition of Ure raft frowed at final Deal. Starboard No. J.	Good	Goed	Geed	Goed	Goed	Gost	Great	Gosé	Goo
Life roll.	Chack Condition of Life raff Eliment of their Deck Starboard No. 3	Skot	Great	Gwq	Gred	Great	GME	Grand	Gree	Gos
	Chards Condition of Life raft filmwaif at Boat Deck Post No. 6	Stood	Good	Geed	Good	Good	Good	Good	Gost	Gos
	Check Condition of Life rat Strong at Sing Spire Part No. 5	LAMU	PE	1	Closed	Greet	gwe	Greed	Grec	Gre
Erreigency General Alarm System	Check and Test Condition (Sans Ryson)	Good	000	42	Cont	Geed	Goed	Good.	Good	Goo
Commence on Plants	Charle Condition of All Employers Lights	Short .	Gast		Buy	(694)	Good	Good	Goot	Gioq
Emergency Light	Ones Company Of the Light	10000	-	Geet	100	Gaet	Gued	Gaed	Gired	Gree
Notic Address. System or Others	Chess and Ted Constant to System (1777)	ERA	N AMERICAN	Cont.	Best	Geel	Good	Geef	Geel	Gen
	Dany of Inspection	11110	4.11.10	12/11/89	22.70/10	29.11.46	G 52.18	13.12.10	20:12:10	27.32

SUNGAL GERONG / POJO

Page 1

LIVE SAVING APLIANCES

TEAR OF JUST

11	Point of Check	Discretion	Sept	unby	06	lotter	Hovember		Dep	othe
No.	Point of Chack	H.C. CHIEN PROCESSOR	Hout	No.2	Ma. 1	Ma. 2	No. 1	No. 2	No. 1	No.
		Check Condition of Davids and Foundation	Book	faces	Dest	See	Gent	Greet	Goss	Boot
		Check Condition of Lacking Devices	Heat	Done	Sent	Good	Cont	Good	Does	Done
1	Desta	Check Condition of Lasting Wires	Gost	Scot	Good	Good	Gass	Good	Goss	Gost
		Check Condition of Limit Switch (If Applicable)	Goreii.	Gost	Calif	Chief	Good	Good	Boid.	Done
		Apply Greene to all Moving Parts	Gost	Good	Sect	Sect	Good	Good	Good	Good
		Check Condition of all Lifting Hooks	Good	Box	Seed	Seed	Guest	Good	Good	Stoot
2	Lifting Ptodus	Apply Grease to all Moving Parts	Sout.	Good:	Georg	Seed	Good	Gaset	Does	Done
	Bost Falls	Check Condition of Cost Falls and Apply Grease	Gord.	Sour.	Seed	dient	Godd	Gent	Goal	Good
3		Apply Greene to Boat Falls	Good	Gosti	Seed	Georg.	Good	Gassi	Gost	Quet.
		Check Due Dates of Falls	Good.	Gost	Good	Good	Greek	Greek	Goed	Gost
		Check Condition of Winch Greene	Goven.	Gost.	Decil	Geni	Gard	Greek	Does.	Host
		Check Condition of Boat Winch	Gost	Gost	Test	Good	Seed	Georg	Goss	Good
4	Boat Weets IT Applicable)	Check Condition of Winch Motor	Gond	Bond	Christ	Control	Class	Card	Boat	Goale
	(a transmiss)	Apply Greese to all Moving Parts	Goed	Good	Soot	Good.	Good	Glassi.	Gowl	Que
		Operational Test of Motor and Sout Winch	filmed	Start	Shoot	Sicol	lined	Sinor.	Gost	Store
	250000	Check Condition of all Sheares	Good	Goat	Good	Gost	Gest	Georg	Gost	Gost
5	Sheares	Apply Grease to all Moving Parts	Good	Gost	Good.	Good.	Good	Geod.	Greet	Domi
6	Lackter	Check Condition of Embaduation Liebbar	Goad	Grant	Seco	Sicon)	Geod	Sext	Gosti	Gost

SUNGAI GERONG / POJO Page 1

,	Launching Instruction	Check Condition of Launching Instruction	10714	Glend .	5900	Geox	Gost	Gost	Gost.	Gost.
	eleast Moretily imprest	Labet	17.5	100		177.5				
-		Barross and Equipment								
No.	Point of Check	Description		enter		otion .	1	eribet.	100	ereber
	0.0000000000000000000000000000000000000	200000	No. 1	No. 2 Good	No.1	No. 2	No. 1	No. 2	No. 1	No.
	MO Stoker	Check Combion of Lifeboat IMO Sticker	2000	100	D1333	100	1333	1333	1200	1
	Character of the Control of the Cont	Check Marking of Ship's Nam, Port of Registry, Boat No., Call Sign & MC No. at both side of bow	Geod	Good	Good	Good	Good	Good	Gasel.	Gass
P	Lifebowt Markings	Check Markings for Identifying of Boat from Top		1000	100	TAY	7500	1235	2000	380
		Check Condition of Retro-Reflective Tope around book	Gest	Gassi	Good	Good	Good	Gred	Geod.	Goor
		Check Condition of Outside Shell	Good	Good	Good	Good	Good	Good	Q000	Georg
	5000 D0010 1000 000 1000	Good	Good	Good	Good	Geo				
		Check Condition of Internal Structures	Georg	Genet	Good	tione	Good	Good	Geod	Georg
10	Lifebook Hull		Good	Gest	Good	Good	Good	Stord	Georg	Geo
		Check Condition of Hight Internal Buoyanny Oteck Condition of Lifetimes founded around	Good	Good	Good	Good	Good	Good	Georg	Georg
		Outside of Boat		PERC	1000	1333	1100	2000	1000	13
		Grick Condition of Grati lines Gritwille to Gurwale (2 Sets)	400	Good	Good	Dane	Good	Good	Good	Geo
		Check Condition of Date Porces	chist	Coppe	Good	Good	Clood	Cloud	Geed	Geo
17	Boat Hooks	Chick Canadan & Botton Mourage)	Good	South	Dec.	Good	Good	Good	Good	Geo
	55500000	trackety City to a comment	Grad	Good	Grap	Good	Good	Good	Good	Geo
	Fluidor (Attached)	Apply Comments of Museum and Their Property	Caus .	Good	Alex	Good	Good	Good	Good	Geo
12	with Titler	pers and Gattgeon ENA	84		100		10007	1728	17538	VFS
			14	11/05		1				
iU8	IGAI GERONG (PO)	P. C. C. C. C. C.	1000000 N					Pag
		W &		98000000	Topagago /	1=			1525	
		ES	ton	90000000	Mices .	1=	Gioed	Good	TEAR	00.20
IVI	E SAVING APLIANC		Cood		Mice State		Good Soed	Good		Geo
IVI		Apply Green to M Moving Parts Check Springer of Francis House &	-	5	Ca /	dioce .	1000	1000	Gead	Geo
JVI	E SAVING APLIANC	Apply Gregor to M Mayor Bers Donoth Squalition of Francisco Home & Bostongs	Cest	Geny	04	Good Good	Good	Good	Geod Geod	Geo
JVI	Propeller	Apply Groups to M Mayor Brisis Check Spreadon of Property Hour & Bearings Apply Crosse to Degings Moving Parts	Cool A	Good	Good	Good Good	Good	Good	Gead Gead Gead	Geo Geo
13	Propeller	Apply Groups to M Mayor Briss Check Spreadon of Property Hours & Bearings Apply Groups to Bearings Moving Parts	Good A	Good	Good	Good Good Good	Good	Good	Good Good Good	Geo Geo
13	Propeller Propeller Livebook Launching App	Apply Groups to M Mayor Pain Oneon Spreadon of Property Home & Bookings Apply Oneone to Despings Moving Parts Apply Oneone to Despings Moving Parts Description	Gest A	Good Good Hotel	Good Oct	Good Good Good No. 2	Good Good Near	Good Good Ma. 2	Geod Geod Geod Den	Geo Geo
13	Propeller Propeller Livebook Launching App	Apply Groups to M Monra Reits Check Consider of Francis Have & Bearings Apply Grease to Bearings Moving Parts ancies and Egypnesis	Good A	Good	Good	Good Good Good	Good	Good	Good Good Good	Geo Geo
13	Propeller Propeller Livebook Launching App	Apply Groups to M Moving Britis Check Spratted of Property Have & Bearings Apply Groups to Bearings Moving Parts There are Equipment Description Check Condition of Engine Dodling Socievable Plants, Pipe Line and Accessaries. Check Condition of Enhaust Pipe and Coner	Gest A	Good Good Hotel	Good Oct	Good Good Good No. 2	Good Good Near	Good Good Ma. 2	Geod Geod Geod Den	Geo Geo Ne Geo
13	Propeller Propeller Livebook Launching App	Apply Groupe to M Maying Reibs Check Spreading of Propering Have: & Bearings Apply Groupe to Bearings Moving Parts Check Condition of Engine Doding Seawaler Purps, Prige Line and Accompanies Check Condition of Enhant Pipe and Cover for Prevention of Entry of Water	Good Begg	Good Rock 2	Good Good No. 1 Good	Good Good Good Weet No. 2 Good	Good Good No. 1 Good	Good Good Ma. 2 Sood	Geod Geod Geod Beet No. 1	Geo Geo Geo Ne Geo
13	Propeller Propeller United Manching App Point of Check	Apply Groupe to all Moving Pitch Check Condition of Proposition Have & Bearings Apply Oncore to Bearings (Moving Pitch Description Check Condition of Engine Dooling Seawaker Plants, Pipe Line and Accessaries. Check Condition of Enhant Pipe and Covertor Prevention of Entry of Water Check Level of Lubroating Oil and Fuel Oil	Gest A Beat No. 1 Good Good	Good Good No. 2 Good Good	Good Cort	Good Good Good Wei 2 Good Good	Good Good Reon Ma. 1 Good Good	Good Good Ma. 2 Good Good	Good Good Good No. 1 Good	Geo Geo Geo Geo Geo
13 1.0	Propeller Propeller Livebook Launching App	Apply Groups to M Moving Piers Check Condition of Properies Have & Boorings Apply Oncore to Despirings Moving Parts Encore and Equipment Description Check Condition of Enfant Pipe and Cover for Prevention of Entry of Water Check Level of Lubroaring Oil and Fuel Oil Additional Faul Oil for 24 Hoors (# Applicable)	Gest A Good Good Good Good	Good Re 2 Good Good Good	Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Ween Max 1 Good Good Good Good	Good Good Ma. 2 Good Good Good	Good Good Bee No. 1 Good Good Good Good	Geo Geo Geo Geo Geo Geo
13 1.0	Propeller Propeller United Manching App Point of Check	Apply Groves to M Mayor Petro Check Spreadon of Properior House & Bearings Apply Oneses to Despings (Moving Parts Bearings) Apply Oneses to Despings (Moving Parts Check Condition of Engel Cooking Seawater Purple, Pipe Line and Accessories. Check Condition of Exhaust Pipe and Cover for Prevention of Exhaust Pipe and Cover for Prevention of Engel of Water Check Level of Lubroaring Ottand Fuel Oil Additional Fuel Oil for 24 Hours (If Applicable) Check Condition of Engelong Geer and Proporter Sheat	Good Good Good Good Good	Good Figure 1 Good Good Good Good Good Good	Good Good No. 1 Good Good Good Good Good Good	Good Good Good Good Good	Good Good Next Ma. 1 Good Good Good Good Good	Good Good Ma. 2 Good Good Good Good Good Good	Geod Geod Geod No. 1 Geod Geod Geod Geod Geod	Geo Geo Geo Geo Geo Geo Geo
13 1.0	Propeller Propeller United Manching App Point of Check	Apply Groupe to M Maying Resistances and Equipment Description Check Condition of Engine Doding Seawable: Purps, Pige Line and Accessaries. Check Condition of Enhant Pige and Conerter Prevention of Entry of Water Check Level of Lubroating Oil and Fuel Oil Additional Fuel Oil for 24 Hours (if Applicable) Check Condition of Engaging Geer and	Gest A Good Good Good Good	Good Re 2 Good Good Good	Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Ween Max 1 Good Good Good Good	Good Good Ma. 2 Good Good Good	Good Good Bee No. 1 Good Good Good Good	Geo Geo Geo Geo Geo Geo Geo
13 1.0	Propeller Propeller United Manching App Point of Check	Apply Groupe to all Moving Piets Check Condition of Fraudish Have & Bearings Apply Grease to Bhasings (Aboving Piets Bearings Apply Grease to Bhasings (Aboving Piets Description Check Condition of Eigher Cooling Seawaker Piens, Pipe Line and Accionatries. Check Condition of Eighaust Pipe and Cover- for Prevention of Eigh of Water Check Level of Lubroating Oil and Fuel Oil Additional Fluid Oil for 24 Hours (if Applicable) Check Condition of Eighgang Geer and Propular Shaff Check Condition of Rechargeotive Batheries	Good Good Good Good Good	Good Figure 1 Good Good Good Good Good Good	Good Good No. 1 Good Good Good Good Good Good	Good Good Good Good Good	Good Good Next Ma. 1 Good Good Good Good Good	Good Good Ma. 2 Good Good Good Good Good Good	Geod Geod Geod No. 1 Geod Geod Geod Geod Geod	George Ge
13 1.0	Propeller Propeller United Manching App Point of Check	Apply Groupe to M Mayers Personal Control Spreadon of Property Haver & Bearings Original Condition of Property Haver & Bearings Original Condition of Engine Coding Seawaler Purps, Pipe Line and Accompanies. Check Condition of Enhant Pipe and Cover for Prevention of Entry of Water Check Level of Lubroating Of and Fuel OX Additional Fuel Of the 24 Hours (if Applicable) Check Condition of Engaging Geer and Propeller Shaft Check Condition of Rechargeable Batteries (for Endosed Lifebook) Apply Grease to all Moving Ports	Good Good Good Good Good Good	Good Good Good Good Good Good	Good Good Good Good Good Good Good	Good Good Good Good Good Good	Good Good Ween Max 1 Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Geod Geod Geod No. 1 Geod Geod Geod Geod Geod	Geo
12 1.09 14	Propeller Propeller United Manching App Point of Check	Apply Groupe to all Moving Piets Check Condition of Fraudish Have & Bearings Apply Grease to Bearings (Moving Parts Bearings Apply Grease to Bearings) Moving Parts Check Condition of Eighaust Pipe and Cover for Prevention of Entry of Water Check Condition of Eighaust Pipe and Cover for Prevention of Entry of Water Check Level of Lubrocating Oil and Fuel Oil Additional Fuel Oil for 24 Hours (if Applicable) Check Condition of Eighaust Fig. Check Condition of Rechargeable Batheries for Enclosed Libboar) Apply Grease to all Moving Ports Check Condition of Selety Belt for each Check Condition of Selety Belt for each	Good Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Good Good Good Good	Good Good Recor Max. 1 Good Good Good Good Good	Good Good Good Good Good Good Good Good	Geed Geed Geed No. 1 Geed Geed Geed Geed Geed Geed Geed Gee	George Ge
12 1.09 14	Propeller Propeller Propeller Propeller Profest of Check Engine	Apply Groupe to all Moving Piers Check Condition of Fraudish Have & Bearings Apply Grease to Bearings (Allowing Piers Description Check Condition of Eigher Cooling Seawaker Puris), Pipe Line and Accionacties. Check Condition of Eighaust Pipe and Cover for Prevention of Eigh of Water Check Level of Lubrocating Oil and Fuel Oil Additional Fuel Oil for 24 Hours (if Applicable) Check Condition of Eighaust Figer and Propeller Shaft Check Condition of Rechargeothe Baharies for Enclosed Lifeboal) Apply Greates to all Moving Ports Check Condition of Selety Belt for each Seating Position Check Condition of Selety Belt for each Seating Position Check Condition of Selety Belt for each Seating Position Check Condition of Selety Belt for each Seating Position (Check Condition of Selety Belt for each Seating Position)	Good Good Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Good Good	Sood Good Recor Ma. 1 Good Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Geed Geed Geed Me. 1 Geed Geed Geed Geed Geed Geed Geed Gee	Georgian Georgia Georgian Geor
12 1.09 14	Propeller Propeller Boat Hondith, Incomit Ureboat Launching App Point of Chack Engine Self-Contained Air	Apply Groupe to M Mayers Person Dear Spreadon of Properior Haver & Bearings Apply Oncore to Dearings (Moving Parts Description Check Condition of Engine Cooling Seawaler Purps, Pipe Lans and Accompanies Check Condition of Enhant Pipe and Cover for Prevention of Entry of Water Check Level of Lubroating Oil and Fuel Oil Additional Fuel Oil for 24 Hours (if Applicable) Check Condition of Engaging Geer and Propeller Shaft Check Condition of Rechargeable Batheries (for Enclosed Lifebook) Apply Grease to all Moving Ports Check Meding of each Sealing Position Check Condition of Salety, Belt for each Sealing Position (for Enclosed Lifebook) Check Condition of Oxygen Biddies	Good Good Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Geed Geed Geed No. 1 Geed Good Good Good Good Good Good Good	Georgian Geo
13 1.0 Wo.	E SAVING APLIANC Propeller Install Manching App Point of Check Engine Seal-Contened Arr Support System (for	Apply Groupe to all Moving Piers Check Condition of Fraudish Have & Bearings Apply Grease to Bearings (Allowing Piers Description Check Condition of Eigher Cooling Seawaker Puris), Pipe Line and Accionacties. Check Condition of Eighaust Pipe and Cover for Prevention of Eigh of Water Check Level of Lubrocating Oil and Fuel Oil Additional Fuel Oil for 24 Hours (if Applicable) Check Condition of Eighaust Figer and Propeller Shaft Check Condition of Rechargeothe Baharies for Enclosed Lifeboal) Apply Greates to all Moving Ports Check Condition of Selety Belt for each Seating Position Check Condition of Selety Belt for each Seating Position Check Condition of Selety Belt for each Seating Position Check Condition of Selety Belt for each Seating Position (Check Condition of Selety Belt for each Seating Position)	Dept Dept Dept Dept Dept Dept Dept Dept	Good Good Good Good Good Good Good Good	Const No. 1 Gass Gass Gass Gass Gass Gass Gass Gas	Good Good Good Good Good Good	Sood Good Reco Ma. 1 Good Good Good Good Good Good Good Goo	Good Good Good Good Good Good Good Good	Gead Gead Gead Me. 1 Gead Gead Gead Gead Gead Gead Gead Gead	George Ge
JVI	Propeller Propeller Boat Hondith, Incomit Ureboat Launching App Point of Chack Engine Self-Contained Air	Apply Groupe to M Mayers Person Dear Spreadon of Properior Haver & Bearings Apply Oncore to Dearings (Moving Parts Description Check Condition of Engine Cooling Seawaler Purps, Pipe Lans and Accompanies Check Condition of Enhant Pipe and Cover for Prevention of Entry of Water Check Level of Lubroating Oil and Fuel Oil Additional Fuel Oil for 24 Hours (if Applicable) Check Condition of Engaging Geer and Propeller Shaft Check Condition of Rechargeable Batheries (for Enclosed Lifebook) Apply Grease to all Moving Ports Check Meding of each Sealing Position Check Condition of Salety, Belt for each Sealing Position (for Enclosed Lifebook) Check Condition of Oxygen Biddies	Good Good Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Good Good Good	Good Good Good Good Good Good Good Good	Good Good Good Good Good Good Good Good	Geed Geed Geed No. 1 Geed Good Good Good Good Good Good Good	Georg

SUNGAI GERONG / POJO Page 3

LIVE SAVING APLIANCES Good 1006 Good Good Good Good Good Geod (for Enstead Lifetion) Check Coedition of Engaging Unit Cessi Good Good South Good Georgi George Efficiency of Spray System during Testing Good Soot Good Good Check Condition of Helease Device Painter Release Good Georg Good Good Good Good Bood Closed Deutoe. Apply Chasse to all Moving Parts Good Good Good Good Good Good Good Geori Check Condition of Entirquisher, Label, Potable Fire 19 Exinquister Marking Lifeboal Bloodbly by Lifebook Launching Appliances and Equipment

		Providence of the control of the con	Baytumber		Ormober		Hovereber.		Desermen	
Na.	Point of Check	Description	No. 1	No. 2	No. 1	No. 2	No.1	No.2	No. 1	No. 2
20	Food Ration	Food Radion of Approved Type in Artight Reneptation Stoved in Artight Containers Talance on less than 10:200 ks/2:200 k.Cal.co. Penson Clight, Jill. Flooders, IB. 550, Grant, each Lifecost Equity State: February 38:10	Good	Good	Gene	Genet	lione	Good	Good	Clodd
21	Fresh Water	Fresh Wheler (3 Lifery or 6 Limbs per Planses) in state-right Recolphaces or Continuers (Total: 000 Page 85 000 in/ appl Lifetype) Eagling Date: Professing 3519	Good	Good	Gaoo	Good	Good	Good	Good	Good
22	Rocket Parachute Flams	Rodott Parachute Signale. (A Pcs 44th Weboat) Expery Date: August 2019	Good	Good	Good	Good	Good	Good	Good	Good
72	Hand Flores	Hand Flance (5 Pcs exch.4-Miscots)	PE	Good	Good	Good	Geod	Good	-8004	Sont
24	Support Smoke Signal	State of Section September 2 August 2019	Die	SALA S	Coord	Good	Gaad	Good	Good	Good
25	First Aid outlit in Waterproof	First Aut care of Westerpoint of an appropriate type (1 September 1998) Exploy Date: March 1998	Boot	1 2	Sept.	Good	Good	Gout	Good	Good
26	Anti-Sessickress Vecicine	Total of March 1865 Sept Total EKA	****	Skool Disco	April	Good	Gead	Gead	Good	Good

Page 4 SUNGAI GERONG + POJO

LIVE SAVING APLIANCES Do many was four of theore of 27 Wests and Salis) Not Applicable 26 Arti-Exposure Cover Not Applicable Check Constant of Large was the Surfaces for 12 hours for goes 1 hours Not Applicable hours (for span Life) half Check Condition of Liebons are along Plant Good Good G008 Good Good Gend 29 Lights Check Condition of Lifeboot Accommodation Good Good 0000 Good Light (for enclosed Lifeboot) Good Good Good Check Condition of Search Lights Good Gent Good

Lifetoot Monthly Inspection
Lifetoot Laurching Appliances and Equipment September November No. Point of Check Despether Description No. 1 No. 2 No. 1 No. 2 No.1 No.2 No.1 No.2 Sufficient buoyant ours attached to tanyant or Cloud Good Georgi Geod-Great Grood Good chain (total number: 2 pcs each lifeboot) Total number of trole pins and crutches Good attached to the boat by chain 2 pics each Good. Goot Goss Good Geod 30 Buoyant Our Spere budyant dara attached with lanyard or chain (2 pos) Not Applicable Spare those pins and cruticles (half of total Not Applicable number 1 pc). Buryant steering park allached to larryant or 31 Steering Ow Not Applicable (If Applicable) chain (for open lifebout, 1 pc) Number of plug for each tole attached to boat . Good Good Good Good Good by chain. 2 pcs 32 Plug Spare plug (one to one) Not Applicable 33 Automatic Drain Valves Number of automatic drain valves littled (if Not Applicable applicable)

SUNGAL GERONG / POJO Page 5

LIVE	E SAVING APLIAN	CES							75,000	00.JUH
34	Bigs Pursy	Sign pump manually operated (1 set)	Good	Geod	Good	Good	Good	Good	Good	Good.
35	Locions	Lockers for small items of equipment	Gead	Gent	Good	tione	Good	Good	Good	Good
56	Panter	Painters of sufficient length, 1 secured to stem; 1 secured to forward with release device (2 pay each tifeboat)	Gead	Gesd	Book	Good	Good	Good	Good	Good
37	Heaving Lines	Light bucyant heaving lines (2 pcs each (Robout)	Good	Gead	Good	Good	Sond	Song	Geod.	Gaod
38	Boat Hook	Boat hooks (2 pcs each lifeboat)	Good	Good	Good	Good	Soot	Stot	Georg	Georg
29	Bailer	Buoyant baller attached to lanyard (1 pc each lifebook)	Good	Good	Good	Bood	Good	Good	Good	Geod
40	Budat	Sucker attached to lanyard (2 pcs each literoat)	Good	Good	Gond	Good	Sloot	Goest	Geed	Gest
101	closel Nivethly Imper	ton		111						
	United Laurening Ap	planus and Equipment	Care	invitur	De	Sober :	Brook	ambar.	Dave	mine
Mg.	Point of Check	Description	No. 1	No. 2	No.1	No. I	No.1	Ma. 2	No.1	No. 2
41	Hatches	Hatches with languard, 1 at each end of the boal (2 set each Weboel)	Good	Good	Good	Good	Good	Good	Good	Good
42	Compare	Compass in binnade, filted with suitable moons of diumination (1 pc sect lifetpot)	Good	Good	Good	Good	0000	Good	Good	Good
43	See Anthor	See anchor with object repended has a visited and tripping line of personal Revolu-	CHOSE	Conci	Good	Good	Good	Good	Good	Good
44	Matches	Maches with sanital action in a water-plat container (2 bob fact liebour for open liebour		APA	18	NetA	optoable			
45	Dipper	Rustford days with langerd (1 to earth	Gues	Good	Cod	Gent	Good	Good	Good	Good
45	Directory Vessel	Restpool graduated states were EKAsc	Good	Jing a	Capoo A	Good	Good	Good	Good	Good
			13	1	E V	V			1	
5100 (S.D)	IGAI GERONG I PI	MILE			No separa				VF40	Page 6
EBIT	SANING WELLIAM	The second secon	ATTIVE TO	Move	E91/	Good	Geed	Gust	Good	Gotat
LIVE		Electric broken, was previous, multiplie for Moran-	14000	EURODES /						
47	Electric Totally	Electric londs, waterproof, suitable for Morae signaling with spage set of batteries and bulls in a waterproof organizers Lpc each Mabooli-	Good	/	9		1228	170		
	Electric Torch	signaling with spage set of batteries and built-	000E	0000	Scot	Soot	Good	Geod	Good	Good
47	20000000	in a waterproof output error to each Metcoli-	4008	0000	/	1000	Good	Good	Good	Good
47	Winter	signating with speak and of butteries, and butteries in a waterproof organizer 1,00 day histories. Dayight signating more (Light sector fraction), Jack-traffe attached to book with bacylary (1 pt.	Gase	Good Good	Good Good Good	Good Good Good	Good	Good	Gase	Good Good
47 48 49	Mirror Jack-Krefe	signating with speak and of batteries, and batteries in a waterproof orbital end to death Makedali. Disylight signating hazor (Left each Makedali. Jack-batte statend to bool first lampers (1) pic each Makedali. White or equivalent sound signal (1) pic each	Good	Good	Good	Good	Good	Good	Good	Good

0.00	-1 145 146 1		_
C. L. Philippins	at the section	y frequenc	COLUMN TO A


	201012-1016		Bearborder.		October		Nanerplan		December	
No.	Point of Check	Description	No. 1	No. 2	No. 1	No. 2	No.1	No. 2	No. 1	No. 2
53	Short Ladder	Short ladder or other means of dimbing into the upright boat from water (1 pc each lifeboar)	Geed	Good	Good	Gaod	0000	Geod	Good	Book
54	Skates	States or feeders to facilitate launching against adverse fel (2 pile each Millout)	Gead	Good	Geod	Good	Gossi	Good	Gase	Gaoo
85	Survival Manual	Sirvivel manual (1 pc each Mebout)	Good	Good	Geod	Geod	Gaod	Geod	Good	Geor
58	Seauckness Bog	Seaschness bag (1 pc each person, total 20 pcs each (feboar)	Geor	Gioda	Geor	Georg	Good.	Geas	Good	Good.
57	Tin-Openers	Tis-openers (3 pcs each Weboat)	Good	Good	Geas	Georg	Good	Good.	Geos	Greek
58	Search Light	Search light (1 pc each lifeboat)	Geed	Gred	Greed	Cress.	Gaust	Goal	Good	Good

SUNGAI GERONG / POJO Page

LIVE	SAVING APLIAN	CES							YEARS	10 2010	
59	Radar Refector	Efficient rader reflector (1 pc each lifeboxt)	Good	Good	Good	Good	Good	Sont	Street:	Good	
60	Thermal Protective Aids	Thermal protective side, for 10% of full complement or minimum 2 persons whichever proter (2 pos-each ideboat)	Gooe	Sand	Good	Goog	Goot	G004	Good	Good	
B1	Engine Tools	Tool box with sufficient tools for adjustments to the engine and its accessories (1 pc each lifeboat)	Souri.	Great	Qoost.	Good	Good	Good	Good	Gond	
62	Rescue Quality (for Rescue Boat)	Buoyent rescue quoits attached to not less than 30m of buoyent line (2 pos each lifeboot)	Gone.	Good.	Good	Gont	Good.	Goest.	Goest.	Good	
	-1000355711	with the second of the	1 Search light illuminating a width of 18m at a distance of 160m (1 pc each lifeboat)	Gonst	Good	Gone	Good	Gotat	Good	Good	Good
63	Search Light (for Rescue Boat)	 Search light capable of operating continuously for at least 3 hours (1 pc each steboat) 	Good	Good	Gané	Good	Good	Good	Good	Sout	
		Date of Inspection	15.00.18	15.00.18	0.10.18	13.36.19	12.11.10	12.11.10	10.12.18	10.12.18	
		PIC	30	3/0	90	3/0	30	3/0	310	3/0	



LAMPIRAN 11 PERMINTAAN PERALATAN SEKOCI PENOLONG



DAFTAR RIWAYAT HIDUP

1. Nama Lengkap : Bahtianul Mubarak

2. Tempat / Tanggal Lahir : Gresik, 5 Oktober 1996

3. NIT : 52155590.N

4. Alamat Asal : Dsn. Tanjungori Ds. Tanjungori Kec. Tambak

Kab. Gresik Jawa Timur

5. Agama : Islam

6. Jenis kelamin : Laki-laki

7. Golongan darah

8. Nama Orang Tua

a. Ayah : (Alm) H. Ahmad

b. Ibu HJ. Amina

c. Alamat : Dsn. Tanjungori Ds. Tanjungori Kec. Tambak

Kab. Gresik Jawa Timur

9. Riwayat Pendidikan

a. SD : MINU 33 Tanjungori, Tahun (2002-2008)

b. SMP : SMP Negeri 1 Tambak, Tahun (2008-2011)

Tahun (2011-2014)

d. Perguruan Tinggi : PIP Semarang, Tahun 2015 - 2020

10. Pengalaman Pratek Laut

a. Perusahaan Pelayaran : PT. BSM CSC Indonesia

b. Nama Kapal : MT. Sungai Gerong

c. Masa Layar : 16 Januari 2018 – 20 Januari 2019