



PT. GURITA LINTAS SAMUDERA

MAINTENANCE REQUEST

S/No.: 16/09/2016/MR/MR/GLS

Vessel	ZALEHA FITRAT	Location	Amamapare, Papua
Date	16 September 2016	(Diag if Nec)	
Time	10.10 LT	System	

STATUS: Not Operational Safety Equip Operational Routine

C/O	Dwi Karyono	C/Eng	Endro Pristanto	Capt.	Sutrisman
-----	-------------	-------	-----------------	-------	-----------

Descriptions: Dikarenakan ada kerusakan crane no 2 bagian torque pada tanggal 15 September 2016 di Laut Amamapare Papua maka kami meminta kiriman barang berupa torque sejumlah 2 buah. Dengan demikian laporan ini kami buat dengan sebenar benarnya.

Supervisor:	Capt. Abu Hasan	Assigned to:	Capt. Fajar Adi
-------------	-----------------	--------------	-----------------

Mech.		Date Started	
Assist		Date Comp.	

Total Man/hours	
-----------------	--

Tools/Parts/Materials required:
Torque crane yoshimura tipe kh0637zn berukuran besar 2 buah

Mengetahui

ENDRO PRISTANTO
Chief Engineer



CAPT. SUTRISMAN
Master