

LAMPIRAN II



Gambar 1.1 hatch tanki



Gambar 1.2 hatch tanki terbuka saat operasi bongkar muat

LAMPIRAN III



Gambar 1.3 Reeli



Gambar 1.4 kurangnya perawatan

LAMPIRAN IV



Gambar 1.5 Kurangnya perawatan



Gambar 1.6 Kurangnya perawatan

LAMPIRAN V



Gambar 1.7 Kurangnya perawatan



Gambar 1.8 Kurangnya Perawatan

LAMPIRAN VI



Gambar 1.9 Kurangnya perawatan



Gambar 1.10 No Return Valve

LAMPIRAN VII



Gambar 1.11 *Vacuum Valve* bocor



Gambar 1.12 *IG Fan*

LAMPIRAN VIII



Gambar 1.13 *Oxygen Analyzer*

