

DAFTAR LAMPIRAN

Lampiran 1	Tabel <i>crew list</i> MV. NYK Vega.....	74
Lampiran 2	Dokumentasi pengambilan kuesioner.....	75
Lampiran 3	Rekapitulasi hasil angket.....	76
Lampiran 4	<i>Ship particulars</i> MV. NYK Vega.....	77
Lampiran 5	Tabel <i>evaporation data sheet of EGE</i>	78
Lampiran 6	<i>Assamble of EGE</i>	79
Lampiran 7	<i>Assamble of high pressure boiler circulating pump</i>	80
Lampiran 8	<i>EGE flow sheet</i>	81
Lampiran 9	<i>Piping of boiler feed water system</i>	82
Lampiran 10	<i>Procedures for Leaving Port</i>	83
Lampiran 11	Kerusakan pada insulator panas dari <i>EGE</i>	85
Lampiran 12	Kerusakan pada <i>cover</i> dari <i>EGE</i>	85
Lampiran 13	Perbaikan pada <i>cover</i> dari <i>EGE</i>	86
Lampiran 14	Kerusakan pada pipa <i>EGE</i>	86
Lampiran 15	Pemotongan pada pipa <i>EGE</i>	87
Lampiran 16	Pengelasan pada pipa <i>EGE</i>	87
Lampiran 17	Kebocoran pada pompa	88
Lampiran 18	Pelepasan Pompa	88
Lampiran 19	Kerusakan pada <i>mechanical seal</i>	89
Lampiran 20	Penggantian pada <i>mechanical seal</i> dan <i>gasket</i>	89
Lampiran 21	Pemasangan <i>high pressure boiler circulating pump</i>	89
Lampiran 22	Wawancara dengan KKM MV. NYK Vega.....	90
Lampiran 23	Wawancara dengan Masinis 3 MV. NYK Vega	91
Lampiran 24	Kuesioner menurunnya kinerja <i>Exhaust Gas Economizer</i> terhadap produksi uap pada saat <i>sea passage</i>	93