


LAMPIRAN 2



Gambar. Garbage Record book

LAMPIRAN 3

(ВЪЗВРАЩАЮЩИ СЪДЕЛНИ ВЕДУЩИ НО. ТЪК. ПЪРВОРАЗ ВЪМ. ЗИМ.)
 ВЪМ. ПЪРВОРАЗ ВЪМ. ЗИМ.)

BARUNA-BARAT
 BADAN HUKUM NO. 754/PAD/KWK2/III-27-3-1996
 Jln. Ujung Baru Belawan Telp. 6940481 Fax (061) 6940481

Port of Belawan

CERTIFICATE

Complying with the MARPOL 73/78 International Convention, in its paragraph V according to the official publication No. 4633, dated 15.09.1993 and established by the Indonesian legislation in the resolution Kep. 135/BAPEDAL/09/2000, being authorized by the Ministry of transport and communication, Department of Marine Transport.

THAT THE M/V : KT 05 EKA FLAG : INDONESIA
 PROCEEDING FROM : Belawan ARRIVED AT THIS : 18-02-2018
 AND SAILED : 25-02-2018 PORT THE : Belawan
 WAS ATTENDED BY OUR ORGANIZATION DURING : DAY (S)

Herewith we do give testimony before third parties that the above mentioned vessel sails from this terminal/port without any garbage on board.
 With desnity : TC. BARU without any garbage on board.

THE GARBAGE WAS LANDED AS BELOW SPECIFIED

TINS	: <u>0.25 M³</u>	PAPERS	: <u>0.10 M³</u>
RAGS	: <u>0.15 M³</u>	SCRAP METAL (S)	: <u>—</u>
GLASS	: <u>—</u>	WASTE FOOD	: <u>0.08 M³</u>
PLASTICS	: <u>0.25 M³</u>		

"Let us protect our seas, by not contaminating, let us think about our future"

RESPECTFULLY YOURS
 COLLECTED BY
KOPERASI BARUNA BARAT
 Unit of Cleaning Service
GARBAGE COLLECTOR
 PORT OF BELAWAN
 MARDI

SIGNED AND STAMPED BY
 Port MASTER OF VESSEL


Gambar. Sertifikat dari garbage collector.