

PT KARYA SUMBER ENERGY

SHIP'S PLANNED MAINTENANCE SYSTEM ENGINE DEPARTMENT

Vessel Name : MV. KT02 Period : March 2017

Symbol

S : Scheduled Maintenance C : Completed Maintenance

Note: Please kindly furbish to substantiate for all the maintainence/repair completed Current Data since last Interval CMS Due Next Due Months Run Hours Months Hours Apr May Jun Jul Aug Last Month ME Total Running Hours This Month Running Hours 181 Current Total Running Hours 87456 6 PURIFIER 6.1 F.O. Purifier No. 1 6.1.1 Clean Filter for operation water 9-May-17 7 500 25/Sep/2017 S 25/Aug/2017 S 6.1.2 Clean Filter feed pump 25-Jul-16 500 47 2,000 27/Nov/2017 S 6.1.3 Check Crankcase 27-Aug-16 6.1.4 Clean Gear camber 27-Aug-16 47 2,000 27/Nov/2017 S 27/Nov/2017 S 6.1.5 Change 0il 27-Aug-16 47 2,000 6.1.6 Clean bowl 47 27/Nov/2017 S 27-Aug-16 2,000 47 27/Nov/2017 S 6.1.7 Check bowl Gasket 27-Aug-16 2,000 27-Aug-16 47 2,000 27/Nov/2017 S 6.1.8 Check starting time Remove bowl & clean inside of upper suction 47 S 27-Dec-16 5,000 27/Jul/2017 6.1.9 frame 6.1.10 Check thickness of brake lining 27-Dec-16 47 5,000 27/Jul/2017 S 6.1.11 Check gearing of worm drive 27-Dec-16 47 5,000 27/Jul/2017 S 6.1.12 Clutch shoe check 27-Dec-16 47 5,000 27/Jul/2017 s 6.1.13 Control panel check 27-Dec-16 47 27/Jul/2017 S 5,000 6.1.14 Check & clean selenoid valve 27-Dec-16 47 5,000 27/Jul/2017 S 47 27/Jul/2017 S 6.1.15 Check 3/2 way valve 27-Dec-16 5,000 47 27/Jul/2017 S 6.1.16 condition 27-Dec-16 5,000 6.1.17 Remove Vertical gear & Horizontal Gear shaft 27-May-16 47 12,000 27/Sep/2017 S 6.1.18 Change all bearing/seal, gasket 27-May-16 47 12,000 27/Sep/2017 S Check spring piston&all spring including spindle spring & Renew if reg. 47 27-May-16 12,000 27/Sep/2017 S Total No. of Outstanding Scheduled Task Total No. of completed task with Maintenace Report Percentage of Scheduled Tasks Completed

Summary of unscheduled breakdown repair

* All maintenance must be supported by Maintenance/Repair Report

Year to Date Completed Task Percentile

PMS No.	Summary of Job	Last Maint. Date/Hrs	Date of repair done	Remarks / Description of Work done