

## DAFTAR GAMBAR

Gambar 2.1 Sistem <i>Oily Water Separator</i> .....	15
Gambar 2.2 Kerangka Pikir .....	19
Gambar 3.1 Diagram <i>Fishbone</i> .....	29
Gambar 3.2 Simbol FTA.....	37
Gambar 3.3 Diagram <i>Fault Tree Analisis</i> .....	38
Gambar 4.1 MV. Glovis Daylight Sedang Berlabuh Jangkar .....	41
Gambar 4.2 <i>Oily Water Separator</i> di MV. Glovis Daylight .....	44
Gambar 4.3 Diagram <i>Fishbone Analisis</i> .....	47
Gambar 4.4 Pohon Kesalahan FTA.....	50
Gambar 4.5 <i>Filter Coalescer</i> Kotor .....	54
Gambar 4.6 <i>Bilge Well</i> Yang Kotor.....	56
Gambar 4.7 Pohon Kesalahan .....	60
Gambar 4.8 Penggantian <i>Filter Coalescer</i> Baru.....	65
Gambar 4.9 <i>Bilge Well</i> Setelah Dilakukan Pembersihan .....	67