

## 2. Lub. Oil Consumption

Kind of Lub. Oil	Standard	TTL Run	TTL L.O.	Cons./Hr	Compare.
	(Ltr/Hr) - A	Hour (M/E)	Cons. (Ltr)	(Ltr/Hr) - B	(%) - A/B
M/E Cyl' Oil	12	1972	10887	5.5	45.8%
M/E Sys' Oil	0.9	1972	1579	0.8	88.9%
G/E Sys' Oil	0.7		7286		

Note) Please input the total data of recent voyages from July. 1<sup>ST</sup> to December 31<sup>th</sup> in this year

## **♦ Summary of Inspection (Major Parts)**

### 1. Hull

Paint Condition		1-1,2
Physical Condition	LITEKNIK ILMU PELATAP	1-3

# 2. Cargo Hold (or Cargo Tank)

Paint Condition	2-1
Physical	2.2
Condition	2-2

#### 3. Ballast Tank

3. Ballas	tiank	
	Paint Condition	3-1
TST	Physical Condition	Pic. No.
DBT	Paint Condition	3-2
	Physical Condition	Pic. No.
FPT	Paint Condition	3-3
APT	Physical Condition	Pic. No.
Etc.	Paint	Pic. No.