




Gambar 1: Patahnya *Railing Lashing Bridge*



Gambar 2: Patahnya *Railing Lashing Bridge*



Gambar 3: Patahnya *Railing Lashing Bridge*



Gambar 4: Patahnya *Railing Lashing Bridge*





Gambar 5: Pengelasan *Railing Lashing Bridge*



Gambar 6: Pengelasan *Railing Lashing Bridge*



Gambar 7: Pengelasan *Railing Lashing Bridge*



Gambar 8: Hasil pengelasan *Railing Lashing Bridge*





Gambar 9: Hasil pengelasan *Railing Lashing Bridge*



Gambar 10: Alternatif sementara pengganti patahnya *Railing Lashing Bridge*



Gambar 11: Perawatan *Railing Lashing Bridge*



Gambar 12: Perawatan *Railing Lashing Bridge*





Gambar 13: Perawatan *Railing Lashing Bridge*



Gambar 14 Penyambungan *Railing Lashing Bridge* dengan cara pengelasan



Gambar 15: Safety Meeting yang dipimpin oleh Muallim 1